

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005959/KBA3Q2

Date: 16/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700070960-20

Claimant
Vehicle No : SMN8219G **Insured Vehicle No :** SLT3625E

Date of Loss: 22/05/2020 **Nature of Claim:** TP **Claim No:** 6169649808SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN8219G	Engine No:	LEB7109059
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP72007187
Reg. Date:	29/08/2019 (Man. Year: 2018)	Odometer:	58668 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Grenlander 9 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Grenlander 9 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,338.16	1,095.28	1,242.88	53.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	940.00	490.00	34.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,768.16	2,035.28	1,732.88	45.99
+ GST 7.00/7.00% (S\$)	263.77	142.47	121.30	45.99
Nett Amount (S\$)	4,031.93	2,177.75	1,854.18	45.99
+ Car Rental (5.0 x S\$78.00/day) (S\$)		390.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,569.75		
Global Sum Settlement (S\$)		2,550.00		

INSPECTION

Date of Assignment: 27/05/2020

Date Inspected: 27/05/2020 Inspected At:

City Auto Pte Ltd (HQ)
160 Sin Ming Drive #05-01,, Sin Ming
AutoCity,
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,193.00 FL	*1,193.00 FL
2	1		*TAILGATE LOGO	Necessary	38.00 FL	*38.00 FL
3	1		*TAILGATE EMBLEM -SHUTTLE	Necessary	58.00 FL	*58.00 FL
4	1		*TAILGATE EMBLEM -HYBRID	Necessary	80.10 FL	*80.10 FL
5	1		*REAR BUMPER	Not Necessary	1,150.60 FL	*- FL
6	8		*REAR BUMPER CLIPS	Not Necessary	28.00 FL	*- FL
7	1		*REVERSE SENSOR	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,847.70	1,369.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	509.54	273.82
Total Parts (\$\$)	2,338.16	1,095.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
2	TO TRANSFER TAILGATE COMPONENTS TO NEW TAILGATE	New	80.00	60.00
3	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	600.00	360.00
4	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	600.00	400.00
Gross Labour Cost (S\$)			1,430.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >