

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD20005964/KTF3E2

Date: 22/02/2021

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00012493-01
Claimant Vehicle No : SGR171L Insured Vehicle No : SDB2244S
Date of Loss: 22/05/2020 Nature of Claim: TP Claim No: 1202000017973

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGR171L**
Make & Model: PORSCHE C4S, 3.8 COUPE TIP (A) Engine No: 68811554
Reg. Date: 30/06/2008 (Man. Year: 2008) Chassis No: WPOZZZ99Z8S723763
Colour: Metallic Grey Odometer: 86633 km
Engine Capacity: 3824 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35 ZR19 Rear Tyre Size: 305/30 ZR19
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	53,179.68	13,534.57	39,645.11	74.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,747.50	1,640.00	8,107.50	83.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	62,927.18	15,174.57	47,752.61	75.89
+ GST 7.00/7.00% (\$\$)	4,404.90	1,062.22	3,342.68	75.89
Nett Amount (\$\$)	67,332.08	16,236.79	51,095.29	75.89

INSPECTION

Date of Assignment: 27/05/2020
Date Inspected: 28/05/2020 Inspected At: Lye Designs (HQ)
10 Amk Autopoint #04-04, Ang Mo Kio Industrial Park
2A
Singapore 568047
Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2021)
Parts:	M1-COUPE	PORSCHE C4S 3.8 COUPE TIP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGR171L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHR DOOR OUTER MOULDING	Serviceable	533.70 F	*- FL
2	1		*RHR DOOR STICKER	Not Necessary	55.80 F	*- FL
3	1		*RHR DOOR STICKER (CARRERA)	Not Necessary	85.90 F	*- FL
4	1		*RHR FENDER	Repair	9,037.00 F	*- FL
5	1		*RHR FENDER GARNISH (NPA)	Serviceable	0.00 F	*- FL
6	1		*RHR FENDER GARNISH CLIPS (NPA)	Not Necessary	0.00 F	*- FL
7	1		*RHR FENDER OUTER SIDE GARNISH (NPA)	Serviceable	0.00 F	*- FL
8	1		*REAR BUMPER	Cracked	5,885.00 F	*2,305.40 FL
9	1		*REAR BUMPER LOWER LIP	Serviceable	1,453.60 F	*- FL
10	1		*REAR BUMPER SIDE RETAINER RHR	Serviceable	341.33 F	*- FL
11	10		*REAR BUMPER CLIPS	Necessary	292.00 FS	*100.00 FS
12	1		*RHR LOWER ARM	Distorted	1,573.70 F	*1,130.00 FL
13	1		*RHR UPPER ARM	Distorted	1,909.61 F	*696.40 FL
14	1		*RHR SPINDLE KNUCKLE	Bent	3,370.50 F	*1,800.00 FL
15	1		*RHR SHOCK ABSORBER	Bent	3,033.17 F	*1,630.00 FL
16	1		*RHR SHOCK ABSORBER STABILISER LINK	Serviceable	179.49 F	*- FL
17	1		*RHR ABSORBER LINKAGE	Serviceable	262.56 F	*- FL
18	1		*RHR DRIVE SHAFT	Repair	5,280.17 F	*- FL
19	1		*RHR WHEEL HUB	Necessary	1,461.42 F	*613.00 FL
20	1		*RHR WHEEL BEARING	Necessary	1,432.56 F	*395.60 FL
21	1		*RHR RIM	Dented/Scratched	3,000.00 F	*1,851.00 FL
22	1		*RHR TYRE	Serviceable	8,988.87 F	*- FL
23	1		*RHR CROSS MEMBER	Bent	2,247.00 F	*2,247.00 FL
24	1		*RHR AXLE SIDE PANEL	Distorted	749.00 F	*749.00 FL
25	1		*REAR ANTI-ROLL BAR	Bent	1,498.00 F	*1,070.00 FL
26	1		*REAR ABSORBER SPONGE	Necessary	59.90 F	*59.90 FL
27	1		*REAR ABSORBER TOP MOUNTING	Bent	449.40 F	*380.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	53,179.68	15,027.30
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,492.73
Total Parts (\$\$)	53,179.68	13,534.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REFOCUS,RE-WIRE TAILLAMP BRAKE LIGHTS,BUMPER BEAM & CHECK WIRINGS	New	280.00	40.00
2	TO REMOVE,REFIX PARKING SENSOR AND CAMERA	New	150.00	80.00
3	TO REMOVE,REFIX INTERIOR TRIMS TO ASSIST REPAIR	New	250.00	0.00
4	TO CHECK WHEEL ALIGNMENT AFTER REPAIRS	New	280.00	120.00
5	TO JACK UP TO CHECK,RE-FIX CHASSIS ALIGNMENT	New	380.00	0.00
6	TO HOIST UP TO CHECK,REFIX UNDER CARRIAGE	New	380.00	240.00
7	TO CHECK CONTROL UNITS,RE-SET MEMORY TO STANDARD SETTINGS	New	580.00	0.00
8	TO RESTORE BACK SCRATCHED RHR RIMS	New	280.00	40.00
9	TO PUTTY AND SPRAY PAINTING ON DAMAED AREA	New	2,000.00	600.00
10	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	1,500.00	400.00
11	TO CHECK WHEEL ALIGNMENT AFTER REPAIRS 17.07.2020.03.08.2020.07.08.2020	New	200.00	120.00
12	TO JACK UP TO CHECK,RE-FIX CHASSIS ALIGNMENT	New	800.00	0.00
13	TO SYMETRICAL SPECIFICATIONS ON CROSS MEMBER	New	267.50	0.00
14	TO HOIST UP TO CHECK,REFIX UNDER CARRIAGE:28 MAY,13 JULY,3 AUG	New	2,400.00	0.00
Gross Labour Cost (\$\$)			9,747.50	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >