

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005970/UGA3Q2

Date: 01/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900141357

Claimant
Vehicle No : FT7306X **Insured Vehicle No :** SJG2017J

Date of Loss: 20/05/2020 Nature of Claim: TP Claim No: 4008801807SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FT7306X		
Make & Model:	YAMAHA RXZ, 133cc (M)	Engine No:	3BS260004
Reg. Date:	30/07/2001 (Man. Year: 2001)	Chassis No:	ZMC260004
Colour:	Black	Odometer:	5338 km
Engine Capacity:	133 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80-80-18	Rear Tyre Size:	80-80-18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,505.70	650.90	1,854.80	74.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	510.00	300.00	210.00	41.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,015.70	950.90	2,064.80	68.47
Approved Total (Overridden) (S\$)		750.00		
Nett Amount (S\$)	3,015.70	750.00	2,265.70	75.13
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
Nett Liability (S\$)		870.00		

INSPECTION

Date of Assignment: 27/05/2020

Date Inspected: 28/05/2020 Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
1 Kaki Bukit Avenue 6, #02-62
AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	65.00 FL	*65.00 FL
2	2		*FORK INNER TUBES	Serviceable	210.00 FL	*- FL
3	2		*FORK OUTER TUBES	Not Necessary	220.00 FL	*- FL
4	1		*FORK UNDER BRACKET	Serviceable	145.00 FL	*- FL
5	1		*FRONT SPORT RIM	Not Necessary	250.00 FL	*- FL
6	1		*FRONT RIM SHAFT	Cut	38.00 FL	*38.00 FL
7	1		*TOP COWLING	Cut	85.00 FL	*85.00 FL
8	1		*WINDSHIELD	Serviceable	32.00 FL	*- FL
9	1		*LAMP ASSY	Not Necessary	50.00 FL	*- FL
10	1		*HEADLAMP	Cracked	70.00 FL	*70.00 FL
11	2		*FRONT SIGNALS	Serviceable	80.00 FL	*- FL
12	1		*HANDLE BAR -L/H	Bent	68.00 FL	*68.00 FL
13	1		*SET HAND GRIP	Torn	35.00 FL	*35.00 FL
14	1		*HANDLE BAR END	Missing	18.00 FL	*18.00 FL
15	1		*CLUTCH LEVER	Cracked	25.00 FL	*25.00 FL
16	1		*METER ASSY	Not Necessary	420.00 FL	*- FL
17	1		*FUEL TANK (LOCAL RESPRAY)	Bent	360.00 FS	*100.00 FS
18	1		*FRONT FOOTREST-L/H	Cut	32.00 FL	*32.00 FL
19	1		*FRONT FOOTREST BRACKET-L/H	Serviceable	55.00 FL	*- FL
20	1		*GEAR PEDAL	Bent	32.00 FL	*32.00 FL
21	1		*REAR FOOTREST -L/H	Cut	28.00 FL	*28.00 FL
22	1		*REAR CENTRE COWLING	Cracked	35.00 FL	*35.00 FL
23	1		*REAR TAILBOARD -L/H	Cracked	70.00 FL	*70.00 FL
24	1		*SET NUMBER PLATE	Rear Scratched	28.00 FS	*10.00 FS
25	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
26	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
27	1		*SET STEERING CONE	Not Necessary	75.00 FS	*- FS
28	1		*FRONT TYRE	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,712.00	711.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	206.30	60.10
Total Parts (\$\$)	2,505.70	650.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	50.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	250.00
Gross Labour Cost (\$\$)			510.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >