

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20005972/EVF3E2

Date: 03/06/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/20-507202-WTT
Claimant Vehicle No :	SMN7209S	Insured Vehicle No :	FBM1543B
Date of Loss:	23/05/2020	Nature of Claim:	TP
		Claim No:	MSC/V/20-000527

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN7209S		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD249588
Reg. Date:	25/11/2016 (Man. Year: 2016)	Chassis No:	WAUZZZ8U4HR019745
Colour:	White	Odometer:	40915 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,261.82	7,308.57	3,953.25	35.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	790.00	1,000.00	55.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,051.82	8,098.57	4,953.25	37.95
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	13,051.82	6,500.00	6,551.82	50.20
+ GST 7.00/7.00% (S\$)	913.63	455.00	458.63	50.20
Nett Amount (S\$)	13,965.45	6,955.00	7,010.45	50.20

INSPECTION

Date of Assignment:	27/05/2020	
Date Inspected:	28/05/2020 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit)
		8 Kaki Bukit Ave 4, #01-49, Premier @
		Kaki Bukit
		Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jun 2020)

Parts: M1-SUV AUDI Q3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMN7209S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,444.50 FL	*1,444.50 FL
2	1		*FRONT LOWER BUMPER LIP	Broken	289.60 FL	*289.60 FL
3	1		*FRONT BUMPER RETAINER	Broken	79.00 FL	*79.00 FL
4	1		*FRONT BUMPER GRILLE	Not Necessary	95.00 FL	*- FL
5	1		*FRONT BUMPER GRILLE CHROME	Not Necessary	815.70 FL	*- FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	84.60 FL	*- FL
7	1		*FRONT REINFORCEMENT	Not Necessary	497.60 FL	*- FL
8	1		*LHS HEADLAMP	Broken	5,455.60 FL	*5,455.60 FL
9	1		*LHS HEADLAMP NOZZLE	Broken	215.80 FL	*215.80 FL
10	1		*LHS HEADLAMP BRACKET	Broken	81.60 FL	*81.60 FL
11	1		*SUPPORT PANEL	Not Necessary	789.50 FL	*- FL
12	1		*SUPPORT PANEL TOP GARNISH	Not Necessary	95.20 FL	*- FL
13	1		*LHS BONNET LOCK	Not Necessary	184.20 FL	*- FL
14	1		*LHS FRONT FENDER	Repair	587.20 FL	*- FL
15	1		*LHS FRONT FENDER SHIELD	Not Necessary	162.80 FL	*- FL
16	1		*LHS FRONT FENDER ARCH	Broken	210.60 FL	*210.60 FL
17	1		*WIPER TANK	Crushed	197.20 FL	*197.20 FL
18	1		*RADIATOR	Not Necessary	365.00 FL	*- FL
19	1		*CONDENSER	Not Necessary	585.50 FL	*- FL
20	1		*LHS HEADLAMP NOZZLE COVER	Not Necessary	40.20 FL	*- FL
21	1		*SET FRONT BUMPER CLIP	Necessary	61.00 FS	*30.00 FS
22	10		*RHS FRONT FENDER SHIELD CLIP	Not Necessary	50.00 FS	*- FS
23	1		*FRONT BUMPER FOG LIGHT COVER	Cut	113.40 FL	*113.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,500.80	8,117.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,238.98	808.73
Total Parts (\$\$)	11,261.82	7,308.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-	New	800.00	300.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT	New	600.00	400.00
3	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	60.00	30.00
4	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	80.00	30.00
5	TO CONDUCT HEADLAMP FOCUS	New	80.00	30.00
6	TO SUPPLY UNDER COATING / PUTTY ON PARTS REPLACED	New	50.00	0.00
7	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	120.00	0.00
Gross Labour Cost (S\$)			1,790.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >