

ASS/REC. BY:

Steve

REF:

CS/MSG20095972/evf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

XX	
N/S	O/S
	...

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: _____

SMN 72095

Yr Regn: _____

25/11/16

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q3

c.c.

1395

Colour

White

A/C:

Insured / Std / NI / NA

Sp.Reading

40915

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WAUZZZ8U4HR-919745

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

F:

235/5R18

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

23/5/20

D.O.I.

28/5/20

Survey held at

Bi Frost, Premium @ KKK buki

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frd LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MK 92K

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 29/5/20-Typist

Report Format: Merimen

Lump Sum / I.B.E. (\$ LS \$6500)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: SMN 7209 S

Model: AUDI Q3

Chassis No: WAUZZZ8U4HR019745

Year of manufacturing: 2006

S/No	Qty	Items	Unit Price	Amount
1	1	Front Bumper / <i>DD</i>	\$ 1,444.50	\$ 1,444.50 /
2	1	Front Lower Bumper Lip ? / <i>OR</i>	\$ 289.60	\$ 289.60 /
3	1	Front Bumper Retainer ? / <i>OR</i>	\$ 79.00	\$ 79.00 /
4	1	Front Bumper Grille X <i>NAI</i>	\$ 95.00	\$ 95.00 X
5	1	Front Bumper Grille Chrome X <i>MM</i>	\$ 815.70	\$ 815.70 X
6	1	Front Bumper Sponge X <i>NAI</i>	\$ 84.60	\$ 84.60 X
7	1	Front Reinforcement X <i>NAI</i>	\$ 497.60	\$ 497.60 X
8	1	LHS Headlamp ? / <i>OR</i>	\$ 5,455.60	\$ <i>check price</i> 5,455.60
9	1	LHS Headlamp Nozzle ? / <i>OR</i>	\$ 215.80	\$ <i>now</i> 215.80 /
10	1	LHS Headlamp Nozzle Cover ? X <i>NAI</i>	\$ 40.20	\$ 40.20 X
11	1	Front Bumper Fog Light Cover ? / <i>CUT</i>	\$ 113.40	\$ 113.40 /
12	1	LHS Headlamp Bracket ? / <i>OR</i>	\$ 81.60	\$ 81.60 /
13	1	Support Panel ? X <i>MM</i>	\$ 789.50	\$ 789.50 X
14	1	Support Panel Top[Garnish X	\$ 95.20	\$ 95.20 X
15	1	LHS Bonnet Lock X	\$ 184.20	\$ 184.20 X
16	1	LHS Front Fender X <i>R</i>	\$ 587.20	\$ 587.20 X
17	1	LHS Front Fender Shield X <i>MM</i>	\$ 162.80	\$ 162.80 X
18	1	LHS Front Fender ARCH ? / <i>OR</i>	\$ 210.60	\$ 210.60 /
19	1	Wiper Tank ? / <i>CRY</i>	\$ 197.20	\$ 197.20 /
20	1	Radiator X <i>NAI</i>	\$ 365.00	\$ 365.00 /
21	1	Condenser X <i>NAI</i>	\$ 585.50	\$ 585.50

\$ 12,389.80

-10% \$ 1,238.98

Total for spare parts \$ 11,150.82

Special Nett								
1	1 set	Front Bumper Clip	/ M	\$	61.00	\$ 30	61.00	
2	10	RHS Front Fender Shield Clip	X NN	\$	5.00	\$	50.00	

Total for SP	\$	111.00
Sub-Total for Parts :	\$	11,261.82

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-	\$	800.00 300
2		To putty and spray paint on all accident damage parts and other accident	\$	600.00 400
3		To check wiring system to facilitate repair and refit the same	\$	60.00 30
4		Apply rust proofing on the adjacent panels	\$	80.00 30
5		To conduct headlamp focus	\$	80.00 30
6		To supply under coating / putty on parts replaced	\$	50.00 X
7		To perform water seepage test after repair	\$	120.00 X

TOTAL AMOUNT :	\$	1,790.00
OVERALL COST:	\$	13,051.82

Steve (LKK) W/L Pul
28/5/20, 10.45am
3 dys
L/S
By AL dy

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: