

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20005974/KBA3Q2

Date: 11/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900232175

Claimant Vehicle No : SHC5542J **Insured Vehicle No :** SKW5528K

Date of Loss: 25/05/2020 Nature of Claim: TP Claim No: 4247804940SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5542J**

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) Engine No: M9R8839C001870

Reg. Date: 15/08/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC278894

Colour: Metallic White/Red Odometer: 521935 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Sailun 9 mm Rear Left Side: Sailun 9 mm

Front Right Side: Sailun 9 mm Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,486.58	1,585.20	6,901.38	81.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,340.00	490.00	13,850.00	96.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,826.58	2,075.20	20,751.38	90.91
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	22,826.58	1,650.00	21,176.58	92.77
+ GST 7.00/7.00% (S\$)	1,597.86	115.50	1,482.36	92.77
Nett Amount (S\$)	24,424.44	1,765.50	22,658.94	92.77
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$21.40/day) (S\$)		64.20		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,987.19		
Global Sum Settlement (S\$)		1,985.00		

INSPECTION

Date of Assignment: 27/05/2020

Date Inspected: 27/05/2020 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Cracked	16.60 FL	*16.60 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	100.90 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	313.10 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
18	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
19	1		*BOOT REAR	Repair	1,677.20 FL	*- FL
20	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
24	1		*BOOT BADGE RENAULT	Not Necessary	82.40 FL	*- FL
25	1		*BOOT BADGE	Not Necessary	95.80 FL	*- FL
26	1		*EXHAUST CAP REAR	Serviceable	125.40 FL	*- FL
27	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
28	1		*SET REAR BUMPER CLIP	Necessary	68.00 FS	*68.00 FS
29	1		*SET BUMPER BRACKET CTR CLIP	Necessary	35.00 FS	*35.00 FS
30	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	25.00 FS	*- FS
31	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	35.00 FS	*- FS
32	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	25.00 FS	*- FS
33	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	35.00 FS	*- FS
34	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	30.00 FS	*- FS
35	1		*SET BUMPER LOWER REAR CLIP	Necessary	68.00 FS	*68.00 FS
36	1		*BOOT STICKER TRANS-CAB	Not Necessary	35.00 FS	*- FS
37	1		*BOOT STICKER 6555-3333	Not Necessary	35.00 FS	*- FS
38	1		*SET BOOT FINISHER CLIP	Not Necessary	35.00 FS	*- FS
39	1		*TAILLAMP CLIP LH	Not Necessary	28.00 FS	*- FS
40	1		*TAILLAMP CLIP RH	Not Necessary	28.00 FS	*- FS
41	1		*REAR BUMPER PROTECTOR	Necessary	120.00 FS	*30.00 FS
42	1		*REAR LICENCE PLATE WITH HOLDER	Serviceable	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,273.76	1,739.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	787.18	153.80
Total Parts (\$\$)	8,486.58	1,585.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	TO RUST PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
7	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
8	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	200.00
9	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
10	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	220.00
13	TO REPAIR AND REALIGN REAR EXHAUST CAP AND EXHAUST PIPE	New	170.00	0.00
Gross Labour Cost (\$\$)			14,340.00	490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >