

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005984/FPS3Q2

Date: 28/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800090499
Claimant		
Vehicle No : SHC3710D	Insured Vehicle No :	SMD362E
Date of Loss: 26/05/2020	Nature of Claim: TP	Claim No: 1721778782SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3710D		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU410425
Reg. Date:	23/01/2020 (Man. Year: 2019)	Chassis No:	KMHC851CVLU190380
Colour:	Blue	Odometer:	19335 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,670.12	690.96	1,979.16	74.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,440.00	940.00	500.00	34.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,110.12	1,630.96	2,479.16	60.32
+ GST 7.00/7.00% (S\$)	287.71	114.17	173.54	60.32
Nett Amount (S\$)	4,397.83	1,745.13	2,652.70	60.32
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	27/05/2020	
Date Inspected:	28/05/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: PARASURAM SHANMUGAM

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	418.30 FL	*- FL
2	1		*FRONT BUMPER BRACKET -RH	Not Necessary	28.00 FL	*- FL
3	1		*FRONT BUMPER TOP BRACKET-RH	Not Necessary	12.00 FL	*- FL
4	10		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
5	1		*HEADLAMP -RH	Not Necessary	1,993.65 FL	*- FL
6	1		*FRONT FENDER -RH	Dented	490.70 FL	*490.70 FL
7	1		*FRONT WHEEL COVER -RH	Scratched	346.40 FL	*346.40 FL
8	1		*FRONT FENDER EMBLEM -RH	Necessary	26.60 FL	*26.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,337.65	863.70
- List Item Discount on L Items 20.00/20.00% (\$)	667.53	172.74
Total Parts (\$)	2,670.12	690.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	480.00
2	SPRAY PAINTING CHARGE	New	500.00	400.00
3	WIRING CHARGE	New	80.00	30.00
4	TUFF KOTE	New	80.00	30.00
5	FRONT WHEEL ALIGNMENT	New	80.00	0.00
Gross Labour Cost (\$)			1,440.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >