Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005986/UGA3N2

Date: 19/08/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993872 Claimant SFG8188G Insured Vehicle No: SMM560C Vehicle No:

Date of Loss: 06/05/2020 Nature of Claim: TP Claim No: 2070687463SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SFG8188G Reg No:

Make & Model: BMW 428I, 2.0 Coupe (A) Engine No: A1680764N20B20A Chassis No: Reg. Date: 25/04/2014 (Man. Year: 2014) WBA3N32070K238460 Odometer: 17557 km

Colour: Grey

**Engine Capacity:** 1997 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

**General Condition:** Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

**CONDITION OF TYRES** 

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18 Rear Left Side: Front Left Side: Michelin 7 mm Michelin 7 mm Front Right Side: Rear Right Side: Michelin 7 mm Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,848.10	1,839.19	1,008.91	35.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,335.00	930.00	1,405.00	60.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,183.10	2,769.19	2,413.91	46.57
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	5,183.10	2,200.00	2,983.10	57.55
+ GST 7.00/7.00% (S\$)	362.82	154.00	208.82	57.55
Nett Amount (S\$)	5,545.92	2,354.00	3,191.92	57.55
+ Loss of Use (5.0 x S\$8	30.00/day) (S\$)	400.00		
	(S\$)	2,754.00		
Liable Amount (50.00%) (S\$)  + Doc/Search Fee (S\$)  Nett Liability (S\$)  Global Sum Settlement (S\$)		1,377.00		
		7.45		
		1,384.45		
		1,300.00		

**INSPECTION** 

Date of Assignment: 27/05/2020

Date Inspected: 28/05/2020 Inspected At: Adjuster Report Page 2 of 4

Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR ASSY ,LH	Badly Dented	1,650.00 F	*1,650.00 FL
2	1		*FRONT DOOR REGULATOR GEAR LH	Not Necessary	340.00 F	*- FL
3	1		*FRONT DOOR POWER WINDOW MOTOR LH	Not Necessary	350.00 F	*- FL
4	1		*FRONT DOOR WEATHER STRIP LH	Not Necessary	200.00 F	*- FL
5	1		*FRONT OUTER FRAME MOULDING LH	Necessary	128.10 F	*128.10 FL
6	1		*FRONT SOUND PROOF SHIELD LH	Necessary	180.00 FS	*150.00 FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	2,848.10	1,928.10
- List Item Discount on L Items 0.00/5.00% (S\$)				0.00	88.91	
				Total Parts (S\$)	2,848.10	1,839.19
	Report was unsubmitted during this print-out.					

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	CUT OUT ,RENEW ,KNOCKING & WELDING ,FRONT DOOR ASSY ,LH ,REMOVE & INSTALL ALL DAMAGE PARTS ,STRAIGHTEN & RE-ALIGN BODY }	New	780.00	300.00
2	REMOVE & INSTALL FRONT DOOR LOCK ,POWER WINDOW GEAR & REGULATOR ETC }	New	250.00	0.00
3	TUFF-KOTE ON DAMAGE PARTS	New	40.00	30.00
4	RESET & DIAGNOSIS	New	300.00	80.00
5	SPRAY PAINTING ON DAMAGE PARTS	New	900.00	500.00
6	CHECK LIGHTING AFTER REPAIR	New	65.00	20.00
	Gross Labour Cost		2,335.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >