

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD		Ref: CC4/ASM20005991/Uka3s2			
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date: 03-11-2020		
ATTN: STACEY NG		Code: ASM			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHF 591J	Veh. Inspected	CB 6099E	
	Policy No.	VFX/P1680520	Coverage (\$)	0.00	
	Claim No.	S0M02OGI	Excess (\$)	0.00	
	Assign From	STACEY NG	Assign Date	27/05/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE (M)	c.c	2985	
	Engine No.	HIDDEN	Year of Reg.	2002	
	Chassis No.	LH1726108205	Colour	WHITE	
	Odometer	765693	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195 R15	MAXTREK	6 mm	
	L/H Front Tyre	195 R15	MAXTREK	6 mm	
	R/H Rear Tyre	195 R15	MAXTREK	6 mm	
	L/H Rear Tyre	195 R15	MAXTREK	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	26/05/2020	Inspection Date	28/05/2020	
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	. Remarks				
	A)THE INSPECTION B)IN ACCORDANCE	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 15 Working Days				