Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20005993/KGA3Q2

Date: 13/04/2021

REFERENCE

AIG Asia Pacific Insurance Pte. Handling Insurer:

2100478844-Policy No: 00000

Ltd. Claimant

SHB9557X

Insured Vehicle

SJJ161Y

Vehicle No:

No:

Claim

Date of Loss: 18/04/2017 Nature of Claim: ΤP

1460083067SG No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHB9557X Reg No:

Make & Model: CHEVROLET EPICA, 2.0 (A) Engine No: **HIDDEN**

Reg. Date: 01/03/2003 (Man. Year: 2003) Chassis No: KL1LA69RJBB123394

Colour: Odometer: 474478 km Red

Engine Capacity: Market Value/New Car

Price:

N/A

1991 cc

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Citicomfort 5 mm Rear Left Side: Citicomfort 5 mm Front Right Side: Citicomfort 5 mm Rear Right Side: Citicomfort 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,231.92	905.64	6,326.28	87.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,400.00	740.00	5,660.00	88.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,631.92	1,645.64	11,986.28	87.93
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	13,631.92	1,300.00	12,331.92	90.46
+ GST 7.00/7.00% (S\$)	954.23	91.00	863.23	90.46
Nett Amount (S\$)	14,586.15	1,391.00	13,195.15	90.46
+ Loss of Use (2.0 x S	550.00/day) (S\$)	100.00		
+ Car Rental (2.0 x S	577.39/day) (S\$)	154.78		
+ Doc/S	Search Fee (S\$)	5.35		
No	ett Liability (S\$)	1,651.13		

INSPECTION

Date of Assignment: 19/04/2017

Trans-cab Auto Services Pte Ltd Date Inspected: 19/04/2017 Inspected At:

No 2 Ang Mo Kio Street 63

Singapore 569111

Adjuster Report Page 2 of 4

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,202.00 FL	*- FL
2	1		*FRONT BUMPER LOWER ABSORBER	Serviceable	180.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	356.00 FL	*- FL
4	1		*FRONT BUMPER RETAINER RH	Distorted	102.00 FL	*102.00 FL
5	1		*FRONT BUMPER RETAINER LH	Serviceable	102.00 FL	*- FL
6	1		*FRONT BUMPER LOWER GRILLE	Serviceable	78.00 FL	*- FL
7	1		*FRONT BUMPER LOWER STIFFENER	Repair	134.37 FL	*- FL
8	1		*BUMPER FOG LAMP COVER RH	Serviceable	32.40 FL	*- FL
9	1		*FRONT HEADLAMP RH	Serviceable	816.00 FL	*- FL
10	1		*FRONT FENDER RH	Bent	837.60 FL	*837.60 FL
11	1		*FRONT FENDER LINER RH	Serviceable	47.00 FL	*- FL
12	1		*WINDSCREEN WASHER TANK -FILLER NECK	Serviceable	4.80 FL	*- FL
13	1		*WINDSCREEN WASHER TANK	Serviceable	62.00 FL	*- FL
14	1		*WINDSCREEN WASHER TANK MOTOR	Serviceable	51.00 FL	*- FL
15	1		*RADIATOR GRILLE (GRILLE A-RAD)	Serviceable	367.00 FL	*- FL
16	1		*FRONT SHOCK ABSORBER ASSY RH	Serviceable	216.17 FL	*- FL
17	1		*FRONT LOWER ARM RH	Serviceable	283.00 FL	*- FL
18	1		*FRONT KNUCKLE ARM RH	Serviceable	230.00 FL	*- FL
19	1		*FRONT STABILIZER BAR LINK RH	Serviceable	51.79 FL	*- FL
20	1		*FRONT DOOR RH	Repair	1,133.00 FL	*- FL
21	1		*FRONT DOOR HINGE UPPER RH	Repair	65.00 FL	*- FL
22	1		*FRONT DOOR HINGE LOWER RH	Repair	65.00 FL	*- FL
23	1		*FRONT SIDE VIEW MIRROR RH	Serviceable	939.00 FL	*- FL
24	1		*SET FRONT BUMPER FASTENER CLIP	Not Necessary	30.00 FS	*-FS
25	1		*SET FRONT FENDER LINER CLIP RH	Not Necessary	30.00 FS	*- FS
26	1		*FRONT WHEEL RIM HUB CAP RH	Serviceable	166.30 FS	*- FS
27	1		*FRONT TYRE RH	Serviceable	180.00 FS	*- FS
28	1		*FRONT TYRE RIM RH	Serviceable	126.00 FS	*-FS
29	1		*DOOR STICKER TRANS-CAB RH	Necessary	80.00 FS	*60.00 FS
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.					
				Sub Total (S\$)	7,967.43	999.60
	- List Item Discount on L Items 10.00/10.00% (S\$)				735.51	93.96
				Total Parts (S\$)	7,231.92	905.64

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	2,800.00	300.00				
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	220.00	30.00				
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,700.00	400.00				
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00				
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00				
6	TOWING FEES	New	120.00	0.00				
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00				
	Gross Labou	r Cost (S\$)	6,400.00	740.00				
Г								
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >