

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20005996/ATF3E2

Date: 18/11/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No: DMCG19007733

Claimant Vehicle No : SKX4721U

Insured Vehicle No : YL851B

Date of Loss: 25/01/2020

Nature of Claim: TP

Claim No: CDMCG20000392

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX4721U**

Make & Model: MERCEDES-BENZ C180K, 1.6 (A)

Engine No: 27191031251114

Reg. Date: 18/08/2009 (Man. Year: 2009)

Chassis No: WDD2040452A308707

Colour: Silver

Odometer: 221934 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,556.60	2,620.20	1,936.40	42.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	530.00	320.00	37.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,406.60	3,150.20	2,256.40	41.73
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	5,406.60	2,500.00	2,906.60	53.76

INSPECTION

Date of Assignment: 28/05/2020

Date Inspected: 28/05/2020 Inspected At:

Advance Auto Garage

10 Kaki Bukit Road 2, #01-21 First East Centre

Singapore 417868

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2020)
Parts:	143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX4721U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,325.00 FL	*1,325.00 FL
2	1		*FRONT BUMPER SIDE HOLDER RH	Necessary	68.00 FL	*68.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	408.00 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	285.00 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP COVER RH	Not Necessary	103.00 FL	*- FL
6	1		*HEADLAMP RH	Cracked	1,485.00 FL	*1,485.00 FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
8	1		*FRONT RH WHEEL RIM	Not Necessary	1,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,924.00	2,908.00
- List Item Discount on L Items 10.00/10.00% (S\$)	367.40	287.80
Total Parts (S\$)	4,556.60	2,620.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	400.00	250.00
2	SPRAY PAINTING TO AFFECTED AREA	New	400.00	250.00
3	WIRING CHECK	New	50.00	30.00
Gross Labour Cost (S\$)			850.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >