

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20006000/DVF3E2

Date: 25/08/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80440424QMX

Claimant Vehicle No : SHC8848H

Insured Vehicle No : SJH8205M

Date of Loss: 27/05/2020

Nature of Claim: TP

Claim No: 624359

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC8848H**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDEU475081

Reg. Date: 10/03/2016 (Man. Year: 2015)

Chassis No: KMHLB41UMGU085562

Colour: Blue

Odometer: 592377 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Hankook 5 mm

Rear Left Side: Hankook 5 mm

Front Right Side: Hankook 5 mm

Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,090.40	11,275.92	5,814.48	34.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,490.00	1,600.00	1,890.00	54.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,580.40	12,875.92	7,704.48	37.44
Approved Total (Overridden) (\$\$)		11,500.00		
(\$\$)	20,580.40	11,500.00	9,080.40	44.12
+ GST 7.00/7.00% (\$\$)	1,440.63	805.00	635.63	44.12
Nett Amount (\$\$)	22,021.03	12,305.00	9,716.03	44.12

INSPECTION

Date of Assignment: 28/05/2020

Date Inspected: 28/05/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Aug 2020)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC8848H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,265.90 FL	*2,265.90 FL
2	1		*BONNET RUBBER (LH)	Serviceable	35.70 FL	*- FL
3	1		*BONNET RUBBER (RH)	Serviceable	35.70 FL	*- FL
4	2		*BONNET HINGE (LH/RH)	Not Necessary	253.40 FL	*- FL
5	1		*BONNET LOCK	Bent	142.40 FL	*142.40 FL
6	1		*BONNET ABSORBER (LH ONLY)	Not Necessary	61.60 FL	*- FL
7	1		*BONNET INSULATOR	Not Necessary	202.50 FL	*- FL
8	1		*BONNET SEAL	Not Necessary	31.90 FL	*- FL
9	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
10	1		*BONNET CABLE	Not Necessary	69.60 FL	*- FL
11	1		*RADIATOR GRILLE H EMBLEM	Necessary / Broken	129.50 FL	*129.50 FL
12	1		*RADIATOR GRILLE	Broken	1,480.00 FL	*1,480.00 FL
13	1		*FRONT BUMPER COVER	Dented / Distorted	1,052.20 FL	*1,052.20 FL
14	1		*FRONT BUMPER SPONGE	Torn	379.20 FL	*379.20 FL
15	1		*FRONT BUMPER REINFORCEMENT	Dented	588.40 FL	*588.40 FL
16	1		*FRONT BUMPER GRILLE (LH)	Not Necessary	149.20 FL	*- FL
17	1		*FRONT BUMPER LIP	Not Necessary	152.00 FL	*- FL
18	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	89.60 FL	*- FL
19	1		*FRONT BUMPER BRACKET (LH)	Not Necessary	49.20 FL	*- FL
20	1		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	76.20 FL	*- FL
21	1		*FRONT BUMPER GRILLE AIR DUCT (LH)	Not Necessary	126.20 FL	*- FL
22	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked / Bent	907.40 FL	*907.40 FL
23	1		*HEADLAMP (LH/RH) (2PCS)	Mtg Broken (1Pc Only)	5,552.00 FL	*2,776.00 FL
24	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
25	1		*RADIATOR	Bent / Punctured	1,637.20 FL	*708.50 FL
26	1		*RADIATOR GUARD	Serviceable	76.50 FL	*- FL
27	1		*COOLANT	Not Necessary	45.00 FL	*- FL
28	1		*RADIATOR FAN BLADE, COWLING, MOTOR ASSY	Cracked	1,194.20 FL	*792.95 FL
29	1		*RADIATOR HOSE UPPER	Not Necessary	229.50 FL	*- FL
30	1		*RADIATOR HOSE LOWER	Not Necessary	135.60 FL	*- FL
31	2		*HORN UNIT (LH/RH)	Broken	144.60 FL	*144.60 FL
32	1		*HORN WIRE	Not Necessary	156.60 FL	*- FL
33	1		*FRONT FENDER (LH)	Dented	566.30 FL	*566.30 FL
34	1		*FRONT FENDER SHIELD (LH)	Not Necessary	174.90 FL	*- FL
35	1		*INTER COOLER	Punctured	1,032.50 FL	*1,032.50 FL
36	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	*- FL
37	1		*HOSE C TO INTER COOLER INLET	Not Necessary	294.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*FRONT NUMBER PLATE	Broken	25.00 FS	*25.00 FS
39	1		*FRONT NO.PLATE TRIM COVER	Broken	30.00 FS	*20.00 FS
40	1		*FRONT FENDER ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
41	1		*AIRCON CONDENSER	Punctured / Bent	947.80 F	*947.80 FN

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	21,087.30	14,058.65
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,996.90	2,593.17
- Nett Item Discount on N Items 0.00/20.00% (\$\$)	0.00	189.56

Total Parts (\$\$)	17,090.40	11,275.92
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	700.00
2	SPRAY PAINTING CHARGE	New	1,000.00	700.00
3	WIRING CHARGE	New	120.00	30.00
4	TUFF KOTE	New	120.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	RE-SET FRT ABS SYSTEM	New	200.00	0.00
7	REMOVE / REFIX RADIATOR	New	90.00	50.00
8	REMOVE / REFIX AIRCON & REFILL GAS	New	130.00	80.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (S\$)			3,490.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >