



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

ALLIED WORLD ASSURANCE COMPANY LTD
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01
(8th FLOOR) MAPLETREE ANSON
SINGAPORE 079914

INV No. AC2002662
INV Date 26/03/2020
Reference CS3/AWA20004304/R1vd3e
Code AWA



PROFESSIONAL SERVICE FEE

Vehicle No. SLX 5599M
Insured Veh. FBK 2310K
Claim No. NSV2000121/PC
Policy No. AVFMSB0000591904
Accident Date 14/03/2020
Inspection Date 23/03/2020

RECEIVED
27 MAR 2020

Allied World Assurance Company, Ltd

Description	Total
Pre-Repair Survey	150.00
Subtotal	150.00
GST (7%)	10.50
Grand Total	160.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

COPY

TAX INVOICE

ALLIED WORLD ASSURANCE COMPANY LTD
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01
(8th FLOOR) MAPLETREE ANSON
SINGAPORE 079914

INV No. AC2002662
INV Date 26/03/2020
Reference CS3/AWA20004304/R1vd3e
Code AWA



PROFESSIONAL SERVICE FEE

Vehicle No. SLX 5599M
Insured Veh. FBK 2310K
Claim No. NSV2000121/PC
Policy No. AVFMSB0000591904
Accident Date 14/03/2020
Inspection Date 23/03/2020

Description	Total
Pre-Repair Survey	150.00
Subtotal	150.00
GST (7%)	10.50
Grand Total	160.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLE TREE ANSON S 079914			Ref: CS3/AWA20004304/R1vd3e2 Date: 26-03-2020	
Code: AWA				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	FBK 2310K	Veh. Inspected	SLX 5599M	
Policy No.	AVFMSB0000591904	Coverage (\$)	0.00	
Claim No.	NSV2000121/PC	Excess (\$)	0.00	
Assign From	STELLA GOH	Assign Date	20/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E250 CGI A	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WDD2120472A199270	Colour	WHITE	
Odometer	119325 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/55 R19	GOODYEAR	6 mm	
L/H Front Tyre	245/55 R19	GOODYEAR	6 mm	
R/H Rear Tyre	245/55 R19	GOODYEAR	6 mm	
L/H Rear Tyre	245/55 R19	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/03/2020	Inspect Date / Time	23/03/2020 (05:52 PM)	
Survey held at	HUP HUP WORKSHOP PTE LTD 27-A JURONG PORT ROAD #01-29 SINGAPORE 619101			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	

Report Ref No. CS3/AWA20004304/R1vd3e2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT(RET)


BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



PRE-REPAIR INSPECTION REPORT				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON S 079914		Ref: CS3/AWA20004304/R1vd3e2 Date: 26-03-2020 Code: AWA		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	FBK 2310K	Veh. Inspected	SLX 5599M	
Policy No.	AVFMSB0000591904	Coverage (\$)	0.00	
Claim No.	NSV2000121/PC	Excess (\$)	0.00	
Assign From	STELLA GOH	Assign Date	20/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E250 CGI A	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WDD2120472A199270	Colour	WHITE	
Odometer	119325 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/55 R19	GOODYEAR	6 mm	
L/H Front Tyre	245/55 R19	GOODYEAR	6 mm	
R/H Rear Tyre	245/55 R19	GOODYEAR	6 mm	
L/H Rear Tyre	245/55 R19	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/03/2020	Inspect Date / Time	23/03/2020 (05:52 PM)	
Survey held at	HUP HUP WORKSHOP PTE LTD 27-A JURONG PORT ROAD #01-29 SINGAPORE 619101			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

Report Ref No. CS3/AWA20004304/R1vd3e2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLX 5599M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLX 5599M

RE-INSPECTION

