



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2005473
INV Date 11/08/2020
Reference CS/AGI20006005/Dyf3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SHD 6584B
Insured Veh. SGW 4256Z
Claim No. C10006363
Policy No.
Accident Date 27/05/2020
Inspection Date 28/05/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20006005/Dyf3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRES SINGAPORE

239924

Date : 11-08-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGW 4256Z	Veh. Inspected	SHD 6584B
Policy No.		Coverage (\$)	0.00
Claim No.	C10006363	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	28/05/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU091543	Colour	BLUE
Odometer	513359	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/05/2020	Inspection Date	28/05/2020
Survey held at	BLK 9 SECTOR C #01-42, SIN MING INDUSTRIAL ESTATE		
Repairer	BIFROST AUTO PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6584B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	1,106.00	553.00
1	REAR BUMPER REINFORCEMENT BRACKET	NOT NECESSARY	160.60	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
1	REAR BUMPER CLIP	NECESSARY	19.00	19.00
1	REAR BUMPER SPONGE	NOT NECESSARY	119.50	-
1	REAR BUMPER UNDER COVER	NOT NECESSARY	228.00	-
1	REAR BUMPER REFLECTOR LAMP (I40)	NOT NECESSARY	32.00	-
1	TAIL LAMP (LH)	NOT NECESSARY	697.80	-
1	TAIL LAMP QUARTER PANEL (LH)	NOT NECESSARY	453.00	-
1	REAR FENDER WITH HOUSING (LH)	BUCKLED / TORN	4,736.80	4,736.80
1	REAR FENDER UNDER SHIELD (LH)	DEFORMED	338.60	169.30
1	REAR FENDER AIR-DUCT (LH)	NOT NECESSARY	51.60	-
1	REAR FENDER TRIM BOARD (LH)	NOT NECESSARY	688.75	-
1	REAR DOOR BLACK PLASTIC COVER	NOT NECESSARY	225.00	-
1	REAR DOOR (LH)	DENTED	2,201.10	2,201.10
1	REAR DOOR RUBBER (LH)	NECESSARY	185.40	185.40
1	REAR DOOR REGULATOR (LH)	MOUNTING BROKEN	660.90	660.90
1	REAR DOOR POWER WINDOW MOTOR	NOT NECESSARY	386.20	-
1	REAR DOOR LOCK ASSY	NOT NECESSARY	468.20	-
1	REAR DOOR TRIM BOARD (LH)	DEFORMED / MOUNTING BROKEN	743.80	743.80
1	REAR DOOR OUTER MOULDING (LH)	NOT NECESSARY	176.80	-
1	ROCKER PANEL OUTER GARNISH (LH)	BROKEN	732.80	341.40
1	ROCKER PANEL OUTER	NOT NECESSARY	1,380.50	-
1	ROCKER PANEL ENFORCEMENT (LH)	NOT NECESSARY	969.40	-
1	ROCKER PANEL INNER (LH)	NOT NECESSARY	551.70	-
1	REAR TYRE RIM (LH)	DISTORTED	650.60	650.60
1	REAR TYRE WHEEL CAP	CUT	214.20	214.20
1	REAR WHEEL BEARING ING & HUB	DAMAGED	724.00	362.00
1	REAR TRAILING ARM (LH)	DISTORTED	384.00	192.00

Report Ref No. CS/AGI20006005/Dyf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR ASSIST (LH)	DISTORTED	219.40	105.70
1	REAR SHOCK ABSORBER (LH)	DISTORTED	683.70	276.30
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	162.60	-
1	ABS SENSOR	NOT NECESSARY	217.90	-
1	REAR CROSS MEMBER	DISTORTED	2,021.50	2,021.50
1	STABILIZER BAR	NOT NECESSARY	199.60	-
1	STABILIZER LINK	NOT NECESSARY	85.90	-
1	REAR UPPER ARM (LH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (LH)	DISTORTED	545.60	545.60
1	REAR WIRING ASSY	NOT NECESSARY	1,521.50	-
	LESS 20% DISCOUNT		-5,212.38	-2,933.63
			20,849.52	11,734.52
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	118.00	-
1	REAR BUMPER ADVERTISEMENTS LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT/I40 PLATE (SN)	NECESSARY	50.00	50.00
1	REAR FENDER ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	REAR DOOR ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	ROCKER PANEL ADVERTISEMENT (LH)(SN)	NECESSARY	120.00	120.00
1	REAR TYRE (LH)(SN)	NOT NECESSARY	216.00	-
			834.00	500.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,800.00	900.00
	SPRAY PAINTING CHARGE.		1,400.00	700.00
	WIRING CHARGE.		160.00	30.00
	TUFF KOTE.		160.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00

Report Ref No. CS/AGI20006005/Dyf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX UNDERCARRIAGE (RR).		400.00	150.00
	RE-SET REAR ABS SYSTEM.	NOT NECESSARY	400.00	-
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	80.00	-
	REMOVE/REFIX EXHAUST PIPE.	NOT NECESSARY	80.00	-
	TRANSFER OF DOOR MECHANISM REAR.		80.00	60.00
	RE-SET REAR POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	180.00
			5,900.00	2,320.00
GRAND TOTAL			27,583.52	14,554.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,600.00

Report Ref No. CS/AGI20006005/Dyf3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.