



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20006008/Aka3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 06-08-2020



ATTN:PETER

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |           |                |            |
|--------------|-----------|----------------|------------|
| Insured Veh. | FBP 7517Y | Veh. Inspected | SLP 6216D  |
| Policy No.   | P2301566  | Coverage (\$)  | 0.00       |
| Claim No.    | S0M02OGJ  | Excess (\$)    | 0.00       |
| Assign From  |           | Assign Date    | 28/05/2020 |

### 2. Vehicle Particulars & Condition

|              |                    |              |            |
|--------------|--------------------|--------------|------------|
| Make & Model | mitsubishi attrage | c.c          | 1193       |
| Engine No.   | HIDDEN             | Year of Reg. | 2017       |
| Chassis No.  | MMBSTA13AHH005682  | Colour       | SILVER     |
| Odometer     | 72152              | Steering     | IN ORDER   |
| Brakes       | IN ORDER           | Modification | SPORTS RIM |
| General      | GOOD               |              |            |

### 3. Conditions of Tyres

|                | Size       | Make     | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 185/55 R15 | GOODYEAR | 6 mm    |
| L/H Front Tyre | 185/55 R15 | GOODYEAR | 6 mm    |
| R/H Rear Tyre  | 185/55 R15 | GOODYEAR | 6 mm    |
| L/H Rear Tyre  | 185/55 R15 | GOODYEAR | 6 mm    |

### 4. Description of Damages

|                                                                        |
|------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br>DAMAGES SEE DETAILS. |
|------------------------------------------------------------------------|

### 5. General Information

|                |                                                                                                      |                 |            |
|----------------|------------------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 27/05/2020                                                                                           | Inspection Date | 28/05/2020 |
| Survey held at | NEW HOCK TECK MOTOR PTE LTD<br>1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                 |            |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 5 Working Days |
|-------------------------------------|----------------|