

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006014/FPS3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100436826
Claimant Vehicle No :	SHD4626C	Insured Vehicle No :	EX2628R
Date of Loss:	28/05/2020	Nature of Claim:	TP
		Claim No:	2998134112SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4626C		
Make & Model:	HYUNDAI SONATA NF, 2.0 CRDI AT ABS 2WD 4DR TURBO (A)	Engine No:	D4EAD310966
Reg. Date:	06/06/2013 (Man. Year: 2013)	Chassis No:	KMHET41VMDA834628
Colour:	Blue	Odometer:	108574 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R15	Rear Tyre Size:	215/60 R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,101.80	2,019.00	82.80	3.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	1,100.00	310.00	21.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,511.80	3,119.00	392.80	11.19
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	3,511.80	2,500.00	1,011.80	28.81
+ GST 7.00/7.00% (S\$)	245.83	175.00	70.83	28.81
Nett Amount (S\$)	3,757.63	2,675.00	1,082.63	28.81
+ Loss of Use (4.5 x S\$50.00/day) (S\$)		225.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,907.49		

INSPECTION

Date of Assignment:	28/05/2020		
Date Inspected:	29/05/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: PARASURAM SHANMUGAM**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SUSP UPR ARM LH	Bent	321.70 FL	*321.70 FL
2	1		*REAR SUSP LWR ARM LH	Damaged	195.80 FL	*195.80 FL
3	1		*REAR WHEEL KNUCKLE ARM LH	Damaged	550.80 FL	*550.80 FL
4	1		*REAR SHOCK ABSORBER LH	Scratched	190.60 FL	*190.60 FL
5	1		*REAR WHEEL BEARING /HUB LH	Necessary	384.60 FL	*384.60 FL
6	1		*REAR WHEEL RIM LH	Scratched	284.70 FL	*284.70 FL
7	1		*REAR WHEEL CAP LH	Cracked	145.00 FL	*145.00 FL
8	1		*REAR ASSIST ARM LH	Damaged	115.00 FL	*115.00 FL
9	1		*REAR TRAILING ARM LH	Bent	115.00 FL	*115.00 FL
10	1		*REAR STABILIZER LINK LH	Necessary	65.30 FL	*65.30 FL
11	1		*REAR WHEEL TYRE LH	Cut	207.00 FS	*124.20 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,575.50	2,492.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	473.70	473.70
Total Parts (\$\$)	2,101.80	2,019.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING -REAR FENDER LH	New	300.00	240.00
2	SPRAYPAINT -REAR BUMPER ETC	New	500.00	400.00
3	TUFF COAT ON AFFECTED PARTS	New	40.00	30.00
4	R/I REAR SUSPENSION LH	New	300.00	200.00
5	WHEEL ALIGNMENT	New	120.00	80.00
6	TOWING FEE-KING DOLLY	New	150.00	150.00
Gross Labour Cost (\$\$)			1,410.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >