

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE

SINGAPORE 068877

INV No. AC2005098

INV Date 21/07/2020

Reference CC4/FCI20006019/Des3n2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLE 4044D

Insured Veh. SHA 5736C

Claim No. D20002256MFSH

Policy No. D-20094922MFSH

Accident Date 27/05/2020

Inspection Date 01/06/2020

| Description | Total |
|--------------------------------|--------|
| Third Party Express Settlement | 350.00 |
| Subtotal | 350.00 |
| GST (7%) | 24.50 |
| Grand Total | 374.50 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

| | Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|---|-----------------------|------------|--|--|--|
| MS FIF | FIRST CAPITAL INSURANCE LTD Ref : CC4/FCl20006019/Des3n2 | | | | | | |
| 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | Date: 21-07-2020 Code: FCI2 | | | | | |
| 1. | . Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| lı | nsured Veh. | SHA 5736C | Veh. Inspected | SLE 4044D | | | |
| F | Policy No. | D-20094922MFSH | Coverage (\$) | 0.00 | | | |
| | Claim No. | D20002256MFSH | Excess (\$) | 0.00 | | | |
| | Assign From | KAREN TAN | Assign Date | 29/05/2020 | | | |
| 2. | | Vehicle Partic | culars & Condition | | | | |
| N | Make & Model | HONDA VEZEL | c.c | 1496 | | | |
| E | Engine No. | HIDDEN | Year of Reg. | 2016 | | | |
| | Chassis No. | RU11117145 | Colour | BLUE | | | |
| | Odometer | 73115 | Steering | IN ORDER | | | |
| E | Brakes | IN ORDER | Modification | SPORTS RIM | | | |
| | General | GOOD | | | | | |
| 3. | | Condition | ons of Tyres | | | | |
| | | Size | Make | Balance | | | |
| F | R/H Front Tyre | 215/60 R16 | DUNLOP | 5 mm | | | |
| L | _/H Front Tyre | 215/60 R16 | DUNLOP | 5 mm | | | |
| F | R/H Rear Tyre | 215/60 R16 | DUNLOP | 5 mm | | | |
| L | _/H Rear Tyre | 215/60 R16 | DUNLOP | 5 mm | | | |
| 4. | | • | on of Damages | | | | |
| T | THE VEHICLE SUS | STAINED DAMAGES AT THE O/S | FRONT AND O/S REAR PO | RTION. | | | |
| | DAMAGES SEE DE | ETAILS. | | | | | |
| 5. | | General | Information | | | | |
| A | Accident Date | 27/05/2020 | Inspection Date | 01/06/2020 | | | |
| S | Survey held at | RALLY PITSTOP | | | | | |
| | | 176 SIN MING DRIVE #04-17 SIN MING AUTO CARE SINGAPORE 575721 | | | | | |
| 5a. | | Re | emarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | | |
| 5b. | Estimate Days of Repair | | | | | | |
| E | ESTIMATED NORM | MAL PERIOD FOR REPAIR: | 5 Working Days | | | | |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 4044D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER | TO REPAIR SEE LABOUR | 689.30 | - |
| 1 | REAR BUMPER SIDE RETAINER (RH) | SERVICEABLE | 48.60 | - |
| 1 | REAR RIGHT FENDER GARNISH | СИТ | 256.90 | 256.90 |
| 1 | REAR RIGHT DOOR | TO REPAIR SEE LABOUR | 897.30 | - |
| 1 | FRONT RIGHT FENDER | DENTED | 459.80 | 459.80 |
| 1 | FRONT RIGHT FENDER GARNISH | CUT | 256.90 | 256.90 |
| 1 | HEAD -LAMP (RH) | SCRATCHED | 585.10 | 585.10 |
| 1 | FRONT BUMPER | TO REPAIR SEE LABOUR | 658.60 | - |
| 1 | FRONT BUMPER RETAINER (RH) | SERVICEABLE | 48.60 | - |
| 1 | FRONT RIGHT SPORT RIM | CUT | 469.80 | 469.80 |
| 1 | FRONT RIGHT KNUCKLE | DISTORTED | 425.90 | 425.90 |
| 1 | FRONT RIGHT WHEEL BEARING | DAMAGED | 225.90 | 225.90 |
| 1 | FRONT RIGHT SHOCK ABSORBER | DISTORTED | 389.60 | 389.60 |
| 1 | FRONT RIGHT LOWER ARM | DISTORTED | 423.90 | 423.90 |
| 1 | FRONT RIGHT STABILIZER LINKAGE | DISTORTED | 112.10 | 112.10 |
| 1 | FRONT RIGHT DRIVE SHAFT | NOT NECESSARY | 957.90 | - |
| | LESS 20% DISCOUNT | | -1,381.24 | -721.18 |
| | | | 5,524.96 | 2,884.72 |
| | <u>LABOUR</u> | | | |
| | LABOUR TO DISMANTLE & REPLACED THE DOORS ,FENDER AND ALL ACCIDENT DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR RIGHT DOOR AND FRONT BUMPER . | | 1,300.00 | 800.00 |
| | LABOUR TO PUTTY & SPRAY PAINTING ON THE ACCIDENT DAMAGED PARTS & REPLACED PARTS. | | 1,000.00 | 800.00 |
| | TO PROVIDE UNDER-COATING. | | 60.00 | 40.00 |
| | TO DO WHEEL ALIGHTMENT. | | 60.00 | 50.00 |
| | LABOUR FOR CHECKING ALL WIRING . | | 60.00 | 30.00 |
| | | | 2,480.00 | 1,720.00 |

Report Ref No. CC4/FCI20006019/Des3n2



Page No.:2 of 2

| GRAND TOTAL | 8,004.96 | 4,604.72 |
|--|----------|----------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | 3,650.00 |

Report Ref No. CC4/FCI20006019/Des3n2



ANG BRYAN TANI

Automotive Assessor / Investigator



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 4044D

















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3591 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No: 19-9607198-R
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 4044D


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 4044D

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315



