Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG20002865/GQF3E2-1

Date: 03/06/2020

REFERENCE

MSIG Insurance (Singapore) Pte. Handling Insurer:

MSD/VMS/19-Policy No: 504879

Claimant Vehicle SJN5982R No:

Insured Vehicle No:

FBH2168X

Date of Loss: 13/02/2020

ΤP Nature of Claim:

Claim MSC/V/20-

No: 000282

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN5982R**

Make & Model: TOYOTA ESTIMA, 2.4 AERAS (A) Engine No: 2AZF216789 Reg. Date: 20/02/2009 (Man. Year: 2008) Chassis No: ACR500083589 Colour: Odometer: 111257 km

Silver **Engine Capacity:** 2362 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

215/55 R17 Front Tyre Size: 215/55 R17 Rear Tyre Size: Front Left Side: Giti 5 mm Rear Left Side: Giti 5 mm Rear Right Side: Giti 5 mm Front Right Side: Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,096.50	954.97	4,141.53	81.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	1,040.00	3,380.00	76.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) 9,516.50	1,994.97	7,521.53	79.04
Approved Total (Overridden) (S\$)	1,600.00		
Nett Amount (S\$) 9,516.50	1,600.00	7,916.50	83.19

INSPECTION

Date of Assignment: 19/02/2020

Date Inspected: 19/02/2020 Inspected At: Providence Motor Pte Ltd (HQ)

11 KAKI BUKIT ROAD 1 #03-08 EUNOS

TECHNOLINK Singapore 415939

Estimated Period of Repair: 5.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen p... 3/6/2020

Adjuster Report Page 2 of 4

Adjuster: XING GUO QIANG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 3 of 4 Adjuster Report

REPAIR DETAILS

Reference Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jun 2020) Parts: M1-MPV TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0) Repairer's (Price-denominated Standard List) Labour: Print Code: (Unsubmitted, no print-code for SJN5982R) Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked / Deformed	588.50 FL	*588.50 FL
2	2		*REAR BUMPER SIDE RETAINER LONG	Serviceable	96.30 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER SHORT	Serviceable	74.90 FL	*- FL
4	1		*TAIL LAMP RH	Serviceable	406.60 FL	*- FL
5	1		*REAR RH FENDER	Repair	1,849.80 FL	*- FL
6	1		*REAR RH FENDER PROTECTOR	Deformed	165.85 FL	*165.85 FL
7	1		*REAR RH INNER TRIM	Serviceable	80.25 FL	*- FL
8	1		*REAR LH INNER TRIM	Serviceable	80.25 FL	*-FL
9	8		*REAR RH FENDER INNER TRIM CLIP	Serviceable	34.24 FL	*- FL
10	1		*REAR RH INNER TRIM FENDER 1/4 GLASS MOULDING	Serviceable	235.40 FL	*-FL
11	1		*REAR RH 1/4 GLASS SEALANT	Serviceable	90.95 FL	*- FL
12	1		*REAR RH FENDER SIDE SHIELD	Serviceable	80.25 FL	*- FL
13	1		*REAR RH RIM	Grazed / Dented	374.50 FL	*374.50 FL
14	2		*REAR RH SHOCK ABSORBER	Serviceable	535.00 FL	*- FL
15	1		*REAR RH TYRE	Serviceable	251.45 FL	*- FL
16	1		*REAR RH AXEL	Serviceable	588.50 FL	*- FL
17	1		*REAR RH KNUCKLE ARM	Serviceable	481.50 FL	*- FL
18	2		*REAR RH BEARING	Serviceable	438.70 FL	*- FL
19	1		*REAR RH DOOR	Repair	197.95 FL	*- FL
20	1		*REAR RH DOOR PROTECTOR	Necessary	144.45 FL	*144.45 FL
F=Fra	anchise	part. L=L	istItemDisc.	Sub Total (S\$)	6,795.34	1,273.30
			- List Item Discount on L	Itams 25 00/25 00% (S\$)	1 608 8/	318 33

- List Item Discount on L Items 25.00/25.00% (S\$) 1,698.84

Total Parts (S\$) 5,096.50 954.97

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR	New	1,600.00	400.00
2	SPRAY	New	1,600.00	500.00
3	REWIRE	New	100.00	20.00
4	ANTI-RUST	New	100.00	0.00
5	UPHOLSTERY	New	300.00	60.00
6	ALIGNMENT	New	100.00	60.00
7	R&R REAR DOOR UNDER CARRIAGE	New	500.00	0.00
8	R&R REAR RIGHT HAND 1/4 GLASS	New	120.00	0.00
		Gross Labour Cost (S\$)	4,420.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >