Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20006021/UKA3Q2

Date: 26/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 1700090456 Policy No: Claimant FBK2286Y Insured Vehicle No: SJR2865U Vehicle No:

Date of Loss: 24/05/2020 Nature of Claim: ΤP Claim No: 7144563187SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBK2286Y Reg No:

Make & Model: YAMAHA YBR125, 124cc (M) Engine No: E3F5E038411

Chassis No: Reg. Date: 26/05/2015 (Man. Year: 2015) LBPRE101000053403

Colour: Odometer: 92036 km Red

Engine Capacity: 124 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 2.75-18 Rear Tyre Size: 2.75-18 Front Left Side: Rear Left Side: Michelin 7 mm Michelin 7 mm

Front Right Side: Rear Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,407.00	1,036.50	370.50	26.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	560.00	335.00	225.00	40.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,967.00	1,371.50	595.50	30.27
Approved Total (Overridden) (S\$)		1,050.00		
(S\$)	1,967.00	1,050.00	917.00	46.62
+ GST 7.00/7.00% (S\$)	137.69	73.50	64.19	46.62
Nett Amount (S\$)	2,104.69	1,123.50	981.19	46.62
+ Loss of Use (3.0 x S\$2	60.00			
+ Doc/Se	earch Fee (S\$)	2.00		
Net	t Liability (S\$)	1,185.50		

INSPECTION

Date of Assignment: 29/05/2020

Date Inspected: 29/05/2020 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*AXLE WHEEL FRONT	Not Necessary	23.00 F	*- FL
1		*BRACKET UNDER FORK	Bent	180.00 F	*180.00 FL
1		*COVER TANK SIDE LH (RED)	Repair	119.00 F	*-FL
1		*COVER TANK SIDE RH (RED)	Repair	119.00 F	*-FL
1		*COWLING FRONT (RED)	Cracked	112.00 F	*112.00 FL
1		*CRASH BAR	Bent	203.00 F	*203.00 FL
1		*FORK FRONT ASSY LH	Dented	138.00 F	*138.00 FL
1		*LAMP SIGNAL FRONT LH	Broken	21.00 F	*21.00 FL
1		*LEVE BRAKE	Scratched	19.00 F	*19.00 FL
1		*MIRROR LH	Cut	35.00 F	*35.00 FL
1		*MIRROR RH	Cut	35.00 F	*35.00 FL
1		*MUDGUARD FRONT (RED)	Cracked	97.00 F	*97.00 FL
1		*PROTECTOR EXHAUST	Scratched	119.00 F	*119.00 FL
1		*PROTECTOR EXHAUST CAP	Scratched	56.00 F	*56.00 FL
1		*RUBBER FOOTREST FRONT	Torn	14.00 F	*14.00 FL
1		*SET STEERING CONE	Necessary	66.00 F	*66.00 FL
1		*STICKER (MCDONALDS) SIDECOVER/WINDSHIELD	Necessary	16.00 FS	*16.00 FS
1		*STICKER (MCDONALDS) SIDECOVER/WINDSHIELD	Necessary	16.00 FS	*16.00 FS
1		*STICKER NUMBER PLATE FRONT (BLACK)	Necessary	19.00 FS	*19.00 FS
nchise	part. S=Spc	Nett. L=ListItemDisc.			
			· · · ·	•	1,146.00
- List Item Discount on L Items 0.00/10.00% (S\$)					109.50
			Total Parts (S\$)	1,407.00	1,036.50
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	*AXLE WHEEL FRONT *BRACKET UNDER FORK *COVER TANK SIDE LH (RED) *COVER TANK SIDE RH (RED) *COWLING FRONT (RED) *CRASH BAR *FORK FRONT ASSY LH *LAMP SIGNAL FRONT LH *LEVE BRAKE *MIRROR LH *MIRROR RH *MUDGUARD FRONT (RED) *PROTECTOR EXHAUST *PROTECTOR EXHAUST CAP *RUBBER FOOTREST FRONT *SET STEERING CONE *STICKER (MCDONALDS) SIDECOVER/WINDSHIELD *STICKER (MCDONALDS) SIDECOVER/WINDSHIELD *STICKER NUMBER PLATE FRONT (BLACK) *Inchise part. S=SpcNett. L=ListItemDisc.	1 *AXLE WHEEL FRONT Bent 1 *BRACKET UNDER FORK Bent 1 *COVER TANK SIDE LH (RED) Repair 1 *COVER TANK SIDE RH (RED) Repair 1 *COWLING FRONT (RED) Cracked 1 *CRASH BAR Bent 1 *FORK FRONT ASSY LH Dented 1 *LAMP SIGNAL FRONT LH Broken 1 *LEVE BRAKE Scratched 1 *MIRROR LH Cut 1 *MIRROR RH Cut 1 *MUDGUARD FRONT (RED) Cracked 1 *PROTECTOR EXHAUST Scratched 1 *PROTECTOR EXHAUST Scratched 1 *PROTECTOR EXHAUST CAP Scratched 1 *RUBBER FOOTREST FRONT TOrn 1 *SET STEERING CONE Necessary 1 *STICKER (MCDONALDS) SIDECOVER/WINDSHIELD Necessary 1 *STICKER NUMBER PLATE FRONT (BLACK) Necessary 1 *STICKER SUMBER PLATE FRONT (BLACK) Necessary	*AXLE WHEEL FRONT

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TRANSPORT CHARGES	New	56.00	35.00
2	LABOUR QUOTED FOR DISMANTLE AND INSTALLATION OF PARTS	New	504.00	300.00
	Gross Labour Cost (S\$)		560.00	335.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >