

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20006023/T1PS3Q2

Date: 11/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100503054

Claimant

Vehicle No : SLK7556S

Insured Vehicle No : SLL7341P

Date of Loss: 28/05/2020

Nature of Claim: TP

Claim No: 0341865316SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK7556S**

Make & Model: VOLKSWAGEN GOLF, 1.4 TSI (A)

Engine No: CZCC05947

Reg. Date: 31/01/2020 (Man. Year: 2019)

Chassis No: WVVWZZAUZKW196593

Colour: Grey

Odometer: 0 km

Engine Capacity: 1395 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,371.81	7,655.33	3,716.48	32.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,600.00	8,200.00	7,400.00	47.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,971.81	15,855.33	11,116.48	41.22
+ GST 7.00/7.00% (S\$)	1,888.03	1,109.87	778.16	41.22
Nett Amount (S\$)	28,859.84	16,965.20	11,894.64	41.22
+ Loss of Use (11.0 x S\$60.00/day) (S\$)		660.00		
+ Medical Costs (S\$)		136.90		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		17,764.10		

INSPECTION

Date of Assignment: 02/06/2020

Date Inspected: 02/06/2020 Inspected At:

Volkswagen Centre Singapore (HQ)

247 Alexandra Road

Singapore 159934

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*1K WINDOW ADHESIVE	Necessary	99.02 FS	*99.02 FS
2	1		*ADHESIVE REMOVER	Necessary	114.78 FS	*114.78 FS
3	1		*PRIMER	Necessary	25.74 FS	*25.74 FS
4	1		*ACTIVATOR FOR PRECOATED W	Necessary	23.77 FS	*23.77 FS
5	2		*APPLICATOR	Necessary	18.78 FS	*18.78 FS
6	1		*HECK Klappe Rear Boot Lid	Bent	1,952.18 FS	*1,952.18 FS
7	1		*HOOD LATCH SATIN BLACK BOOT LID LOCK	Not Necessary	352.43 FS	*- FS
8	1		*BETATIGUNG MIT MIKROSCHAL LID OPER MECHANISM	Cracked	1,643.63 FS	*1,643.63 FS
9	1		*GASKET BOOT WEATHERSTRIP	Necessary	254.30 FS	*254.30 FS
10	1		*ADDITIONAL BRAKE LIGHT WI 3RD BRAKE LIGHT	Necessary	158.79 FS	*158.79 FS
11	1		*INSCRIPTION BRIGHT CHROME NAME PLATE (GOLF)	Necessary	75.22 FS	*75.22 FS
12	1		*LED TAIL LIGHT TAILLIGHT INNER LH	Not Necessary	534.20 FS	*- FS
13	1		*LED TAIL LIGHT TAILLIGHT INNER RH	Not Necessary	534.20 FS	*- FS
14	1		*TRIM PANEL FOR HATCH GATE BOOT LID TRIM COVER	Not Necessary	153.49 FS	*- FS
15	1		*COVER FOR BUMPER PRIMED REAR BUMPER	Deformed	1,124.14 FS	*1,124.14 FS
16	1		*REAR DIFFUSOR SATIN BLACK BUMPER SPOILER	Not Necessary	312.15 FS	*- FS
17	4		*POP-RIVET	Necessary	4.36 FS	*4.36 FS
18	1		*BUMPER BUMPER REINFORCEMENT	Not Necessary	604.40 FS	*- FS
19	1		*ATTACHMENT STRIP BUMPER CENTRE BRACKET	Necessary	63.22 FS	*63.22 FS
20	1		*GUIDE PIECE TAILLIGHT LOWER BRACKET LH	Necessary	36.38 FS	*36.38 FS
21	1		*GUIDE PIECE TAILLIGHT LOWER BRACKET RH	Not Necessary	36.38 FS	*- FS
22	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Necessary	36.38 FS	*36.38 FS
23	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Not Necessary	36.38 FS	*- FS
24	2		*SENSOR BRACKET	Necessary	23.80 FS	*23.80 FS
25	1		*SENSOR BRACKET	Necessary	11.90 FS	*11.90 FS
26	1		*SENSOR BRACKET	Necessary	12.60 FS	*12.60 FS
27	2		*SENSOR BRACKET	Missing	336.20 FS	*336.20 FS
28	2		*SEAL RING SATIN BLACK	Necessary	2.36 FS	*2.36 FS
29	1		*HARNESS FOR BUMPER SENSOR WIRE HARNESS	Not Necessary	89.04 FS	*- FS
30	1		*2K-PLASTIC ADHESIVE	Necessary	75.94 FS	*75.94 FS
31	1		*BONDING AGENT FOR PLASTIC	Necessary	59.40 FS	*59.40 FS
32	2		*LICENSE PLATE LIGHT	Missing	76.02 FS	*76.02 FS
33	1		*DECORATIVE MOULDING BRIGH BUMPER LOWER CHROME (CENTRE)	Not Necessary	141.09 FS	*- FS
34	1		*DECORATIVE MOULDING BRIGH BUMPER LOWER CHROM (LH)	Not Necessary	116.01 FS	*- FS
35	1		*DECORATIVE MOULDING BRIGH BUMPER LOWER CHROM (RH)	Not Necessary	116.01 FS	*- FS
36	1		*ABSCHLUSSBLECH HINTEN END PANEL INNER	Not Necessary	674.84 FS	*- FS
37	1		*END PLATE END PANEL OUTER	Deformed	118.44 FS	*118.44 FS
38	8		*WELD STUD BOLT	Necessary	4.88 FS	*4.88 FS
39	1		*ZINC SPRAY	Necessary	62.88 FS	*62.88 FS
40	1		*2K-BODY ADHESIVE	Necessary	406.76 FS	*406.76 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*SEALANT CAN BE SPRAYED	Necessary	61.67 FS	*61.67 FS
42	1		*COVER FOR LOCK CARRIER TI END PANEL TRIM COVER	Deformed	164.17 FS	*164.17 FS
43	1		*CARGO PLATFORM BLACK SPARE WHEEL COVER	Deformed	415.75 FS	*415.75 FS
44	1		*BOLT FOR SPARE WHEEL MOUN SPARE WHEEL BOLT	Not Necessary	15.86 FS	*- FS
45	1		*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS
46	1		*LICENCE PLATE LIGHT WIRE HOUSING	Cut	10.35 FS	*10.35 FS
47	1		*SPARE WHEEL COVER BRACKET LH	Deformed	50.76 FS	*50.76 FS
48	1		*SPARE WHEEL COVER BRACKET RH	Deformed	50.76 FS	*50.76 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,371.81 7,655.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	6,720.00	3,360.00
4	SPRAY PAINT	New	5,600.00	2,400.00
5	R&R REAR W/SCREEN	New	840.00	840.00
6	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
7	R&R REAR LUGGAGE TRIM	New	840.00	420.00
Gross Labour Cost (\$\$)			15,600.00	8,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >