

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20006027/T1PS3Q2

Date: 07/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SML4816U	Insured Vehicle No :	SHC8601C
Date of Loss: 22/05/2020	Nature of Claim: TP	Claim No: MCT20050154

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML4816U		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B5566357
Reg. Date:	23/05/2019 (Man. Year: 2019)	Chassis No:	RU11316345
Colour:	White	Odometer:	12287 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,064.40	2,882.80	1,181.60	29.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,785.00	1,430.00	355.00	19.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,849.40	4,312.80	1,536.60	26.27
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	5,849.40	3,450.00	2,399.40	41.02
+ GST 7.00/7.00% (S\$)	409.46	241.50	167.96	41.02
Nett Amount (S\$)	6,258.86	3,691.50	2,567.36	41.02
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		4,020.50		

INSPECTION

Date of Assignment:	28/05/2020		
Date Inspected:	29/05/2020	Inspected At:	Ethoz Group Ltd (HQ) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML4816U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,475.20 FL	*1,100.90 FL
2	1		*TAILGATE WINDSCREEN SEAL	Necessary	74.60 FL	*74.60 FL
3	1		*TAILGATE EMBLEM CENTRE	Necessary	71.10 FL	*71.10 FL
4	1		*TAILGATE EMBLEM VEZEL	Necessary	65.50 FL	*65.50 FL
5	1		*TAILGATE LOCK	Not Necessary	342.20 FL	*- FL
6	1		*TAILGATE RUBBER	Not Necessary	224.30 FL	*- FL
7	1		*REAR BUMPER	Deformed	674.50 FL	*674.50 FL
8	10		*REAR BUMPER CLIP	Necessary	45.00 FL	*45.00 FL
9	1		*REAR BUMPER SIDE BRACKET LH	Not Necessary	65.50 FL	*- FL
10	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	65.50 FL	*- FL
11	1		*REAR BUMPER REFLECTOR LH	Cracked	95.20 FL	*95.20 FL
12	1		*REAR END PANEL	Bent	741.30 FL	*530.90 FL
13	1		*TOOL KIT COVER (SPONGE)	Cracked	285.40 FL	*285.40 FL
14	1		*SPARE TYRE PANEL (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
16	1		*END PANEL SEALANT	Necessary	40.00 FS	*40.00 FS
17	1		*REVERSE SENSOR	Not Working	220.00 FS	*200.00 FS
18	1		*TAILGATE SENSOR	Cracked	455.20 FL	*285.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,000.50	3,528.50
- List Item Discount on L Items 20.00/20.00% (\$)	936.10	645.70
Total Parts (\$)	4,064.40	2,882.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO CARRY OUT REAR BUMPER	New	700.00	600.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	35.00	30.00
3	TO SPRAY PAINTING ON REAR AFFECTED AREA	New	600.00	500.00
4	SPRAY RUST PROOF ON AFFECTED AREA	New	40.00	30.00
5	TO DETACH & RENEW REVERSE SENSOR	New	60.00	30.00
6	TO TRANSFER TAILGATE FITTING	New	100.00	60.00
7	TO REMOVE & INSTALL REAR TAILGATE GLASS	New	150.00	120.00
8	TO REMOVE & REFIT ALL NECESSARY TRIM BOARDS ,GARNISH ,CARPET ,FLOOR MATS & SEAT	New	100.00	60.00
Gross Labour Cost (\$\$)			1,785.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >