Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20006035/KBA3Q2

Date: 11/08/2020

REFERENCE

India International Insurance Pte Handling Insurer:

D19MPC0005088

Claimant

SHF620J

Ltd

Insured Vehicle No:

SJK1418X

TP

Vehicle No: Date of Loss:

28/05/2020

Nature of Claim:

Claim No:

MPC2020D0001003

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHF620J Reg No:

RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR Make & Model:

Engine No:

M9R8839C001715

Reg. Date:

27/06/2014 (Man. Year: 2014)

Chassis No: VF1ABL15AUC278507

Metallic White/Red Colour:

Odometer:

659286 km

Engine Capacity: Market Value/New Car

N/A

1995 cc

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Sailun 9 mm Rear Left Side: Sailun 9 mm Front Right Side: Rear Right Side: Sailun 9 mm Sailun 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|----------------------|------------|------------|--------|
| Parts | 14,013.57 | 2,610.48 | 11,403.09 | 81.37 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 18,660.00 | 1,105.00 | 17,555.00 | 94.08 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 32,673.57 | 3,715.48 | 28,958.09 | 88.63 |
| Approved Total (Overridden) (S\$) | | 2,950.00 | | |
| (S\$) | 32,673.57 | 2,950.00 | 29,723.57 | 90.97 |
| + GST 7.00/7.00% (S\$) | 2,287.15 | 206.50 | 2,080.65 | 90.97 |
| Nett Amount (S\$) | 34,960.72 | 3,156.50 | 31,804.22 | 90.97 |
| + Loss of Use (6.0 x S | \$40.00/day) (S\$) | 240.00 | | |
| + Car Rental (6.0 x S\$81.13/day) (S\$) + Doc/Search Fee (S\$) | | 486.78 | | |
| | | 7.45 | | |
| N | Nett Liability (S\$) | | | |
| Global Sum | Settlement (S\$) | 3,800.00 | | |

INSPECTION

Date of Assignment: 29/05/2020

Date Inspected: 29/05/2020 Inspected At: Adjuster Report Page 2 of 5

Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jul 2020)

Parts: 143 RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHF620J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Repairer's

Amount

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts No. Qty Part No. Particulars

| 1 | 1 | *BUMPER COVER REAR | Buckled | 561.70 FL | *561.70 FL |
|----|---|--|---------------|-------------|------------|
| 2 | 1 | *BUMPER LOWER REAR | Dented / Cut | 411.90 FL | *411.90 FL |
| 3 | 1 | *BUMPER BRACKET CTR REAR | Serviceable | 98.10 FL | *- FL |
| 4 | 1 | *BUMPER BRACKET SIDE RH REAR | Serviceable | 82.10 FL | *- FL |
| 5 | 1 | *BUMPER RETAINER RH REAR | Serviceable | 59.80 FL | *-FL |
| 6 | 1 | *BUMPER REFLECTOR RH | Serviceable | 16.60 FL | *-FL |
| 7 | 1 | *BUMPER BRACKET SIDE LH REAR | Serviceable | 80.80 FL | *-FL |
| 8 | 1 | *BUMPER RETAINER LH REAR | Serviceable | 54.20 FL | *- FL |
| 9 | 1 | *BUMPER REFLECTOR LH | Serviceable | 16.60 FL | *- FL |
| 10 | 1 | *BUMPER BEAM REAR | Bent | 547.80 FL | *547.80 FL |
| 11 | 1 | *BUMPER BEAM BRACKET LH REAR | Repair | 114.50 FL | *- FL |
| 12 | 1 | *BUMPER BEAM BRACKET RH REAR | Repair | 100.90 FL | *- FL |
| 13 | 1 | *BOOT REAR | Repair | 1,677.20 FL | *-FL |
| 14 | 1 | *BOOT FINISHER | Serviceable | 344.70 FL | *- FL |
| 15 | 1 | *BOOT WEATHERSTRIP | Serviceable | 178.20 FL | *- FL |
| 16 | 1 | *BOOT REFLECTOR LAMP LH | Serviceable | 277.70 FL | *- FL |
| 17 | 1 | *BOOT REFLECTOR LAMP RH | Serviceable | 277.70 FL | *-FL |
| 18 | 1 | *BOOT BADGE RENAULT | Not Necessary | 82.40 FL | *- FL |
| 19 | 1 | *BOOT BADGE | Not Necessary | 95.80 FL | *-FL |
| 20 | 1 | *BOOT STRUT LH | Serviceable | 145.10 FL | *- FL |
| 21 | 1 | *BOOT STRUT RH | Serviceable | 145.10 FL | *- FL |
| 22 | 1 | *BOOT HINGE LH | Repair | 254.20 FL | *- FL |
| 23 | 1 | *BOOT HINGE RH | Repair | 253.80 FL | *- FL |
| 24 | 1 | *BOOT TRIM BOARD | Serviceable | 611.00 FL | *- FL |
| 25 | 1 | *BOOT LOCK | Repair | 246.60 FL | *- FL |
| 26 | 2 | *BOOT RUBBER PLUG | Serviceable | 139.30 FL | *-FL |
| 27 | 2 | *LICENCE PLATE LAMP | Serviceable | 26.30 FL | *- FL |
| 28 | 1 | *TAILLAMP RH | Serviceable | 401.40 FL | *-FL |
| 29 | 1 | *TAILLAMP PANEL RH | Repair | 401.40 FL | *-FL |
| 30 | 1 | *TAILLAMP PANEL LH | Serviceable | 401.40 FL | *-FL |
| 31 | 1 | *TAILLAMP LH | Serviceable | 401.40 FL | *- FL |
| 32 | 1 | *OUTER PANEL REAR (END PANEL) | Bent | 745.80 FL | *745.80 FL |
| 33 | 1 | *OUTER PANEL REAR (END PANEL)TRIM | Serviceable | 404.56 FL | *-FL |
| 34 | 1 | *SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) | Repair | 1,229.40 FL | *-FL |
| 35 | 1 | *SPARE WHEEL PANEL TRIM | Serviceable | 612.21 FL | *-FL |
| 36 | 1 | *SPARE TYRE BOARD | Serviceable | 680.90 FL | *-FL |
| 37 | 1 | *EXHAUST CAP REAR | Serviceable | 125.40 FL | *-FL |
| 38 | 1 | *SET PARKING AID | Shorted | 700.00 FS | *400.00 FS |
| 39 | 1 | *SET REAR BUMPER CLIP | Necessary | 69.00 FS | *69.00 FS |
| 40 | 1 | *SET BUMPER BRACKET CTR CLIP | Necessary | 35.00 FS | *35.00 FS |
| 41 | 1 | *SET BUMPER BRACKET SIDE CLIP RH RR | Not Necessary | 20.00 FS | *-FS |
| 42 | 1 | *SET BUMPER RETAINER RH CLIP RR | Not Necessary | 25.00 FS | *-FS |
| | | *SET BUMPER BRACKET SIDE CLIP LH RR | Not Necessary | 20.00 FS | *-FS |

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 5

| No. | Qty | Part No | . Particulars | Condition | Repairer's | Amount |
|-------|--|------------|-------------------------------------|-------------------|------------|-----------|
| 44 | 1 | | *SET BUMPER RETAINER CLIP LH RR | Not Necessary | 25.00 FS | *- FS |
| 45 | 1 | | *SET BUMPER LOWER REAR RIVET | Not Necessary | 30.00 FS | *-FS |
| 46 | 1 | | *SET BUMPER LOWER REAR CLIP | Necessary | 66.00 FS | *66.00 FS |
| 47 | 2 | | *END PANEL SEAM SEALANT | Not Necessary | 170.00 FS | *- FS |
| 48 | 1 | | *SET BOOT FINISHER CLIP | Not Necessary | 30.00 FS | *-FS |
| 49 | 1 | | *BOOT STICKER TRANS-CAB | Not Necessary | 35.00 FS | *- FS |
| 50 | 1 | | *BOOT STICKER 6555-3333 | Not Necessary | 35.00 FS | *-FS |
| 51 | 1 | | *BOOT INNER TRIM CLIP | Not Necessary | 45.00 FS | *-FS |
| 52 | 1 | | *SPARE TYRE RIM (ROUE 7J 16H 2547) | Not Necessary | 385.00 FS | *-FS |
| 53 | 1 | | *SPARE TYRE | Serviceable | 330.00 FS | *- FS |
| 54 | 1 | | *TAILLAMP CLIP RH | Not Necessary | 25.00 FS | *-FS |
| 55 | 2 | | *REAR WINDSCREEN SEALANT | Not Necessary | 150.00 FS | *-FS |
| 56 | 1 | | *WINDSCREEN MOULDING | Not Necessary | 180.00 FS | *-FS |
| 57 | 1 | | *REAR WINDSCREEN INNER SPONGE SEAL | Not Necessary | 120.00 FS | *-FS |
| 58 | 1 | | *TAILLAMP CLIP LH | Not Necessary | 25.00 FS | *-FS |
| 59 | 1 | | *REAR BUMPER PROTECTOR | Not Necessary | 120.00 FS | *-FS |
| 60 | 1 | | *SET REAR LICENCE PLATE WITH HOLDER | Serviceable | 100.00 FS | *-FS |
| 61 | 1 | | *SET END PANEL INSULATION PAD | Not Necessary | 200.00 FS | *-FS |
| F=Fra | anchise | part. S=Sp | cNett. L=ListItemDisc. | | | |
| | | | | Sub Total (S\$) | - | 2,837.20 |
| | - List Item Discount on L Items 10.00/10.00% (S\$) | | | | 1,230.40 | 226.72 |
| | | | | Total Parts (S\$) | 14,013.57 | 2,610.48 |

Total Parts (S\$) 14,013.57 2,610.48

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------|---|--------------|------------|----------|
| Labo | our Items | | | |
| 1 | TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR | New | 170.00 | 0.00 |
| 2 | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME. | New | 7,500.00 | 500.00 |
| 3 | TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING | New | 380.00 | 0.00 |
| 4 | TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| 5 | TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 6 | TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| 7 | TO REPAIR AND REALIGN REAR EXHAUST PIPE | New | 350.00 | 0.00 |
| 8 | TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 9 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 10 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 170.00 | 30.00 |
| 11 | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR | New | 380.00 | 0.00 |
| 12 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 7,500.00 | 440.00 |
| 13 | TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING | New | 170.00 | 0.00 |
| 14 | TO REINSTALL REAR BUMPER PARKING SENSOR | New | 170.00 | 60.00 |
| 15 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 15.00 |
| 16 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR | New | 380.00 | 60.00 |
| | Gross Labour | r Cost (S\$) | 18,660.00 | 1,105.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >