

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 May 2020 Edit Reg		29 May 2020 00:00 Edit Adj Rpt	S\$8,200.00 Edit Estimates	S\$8,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: FOO JUAT LIN , ID: S1256286A									
Main Claimant: SATINDER SINGH GILL , ID: S2628712Z									
Vehicle Reg. No.: SMR4525C		Date of Loss: 28/05/2020 00:00 - :59 [30 Months From LTA Reg Date (Man Yr)]							
Claim Type: TP / 0789394729SG		Policy/Cover Note No.: 2100453348 (Comprehensive)							
Vehicle Reg. No. (Insured): SKR7567K		Policy No. (Claimant):							
		Excess:							
Repairer: Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]									
Claimant's Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/06/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMR4525C (0789394729SG)**
[SKR7567K]

TP

SATINDER SINGH GILL

May 28 2020 12:00AM

[FOO JUAT LIN]

Vision Autowork Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser		
Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/09/20 23:45	General View		Load JPG	
2	17/09/20 23:45	General View		Load JPG	
3	17/09/20 23:45	General View		Load JPG	
4	17/09/20 23:45	General View		Load JPG	
5	17/09/20 23:45	General View		Load JPG	
6	17/09/20 23:45	General View		Load JPG	
7	17/09/20 23:45	General View		Load JPG	
8	17/09/20 23:45	General View		Load JPG	
9	17/09/20 23:45	General View		Load JPG	
10	17/09/20 23:45	General View		Load JPG	
11	17/09/20 23:45	General View		Load JPG	
12	17/09/20 23:45	General View		Load JPG	
13	17/09/20 23:45	General View		Load JPG	
14	17/09/20 23:45	General View		Load JPG	
15	17/09/20 23:45	General View		Load JPG	
16	17/09/20 23:45	General View		Load JPG	
17	17/09/20 23:45	General View		Load JPG	
18	17/09/20 23:45	General View		Load JPG	
19	17/09/20 23:45	General View		Load JPG	
20	17/09/20 23:45	General View		Load JPG	
21	17/09/20 23:45	General View		Load JPG	
22	17/09/20 23:45	General View		Load JPG	
23	17/09/20 23:45	General View		Load JPG	
24	17/09/20 23:45	General View		Load JPG	
25	17/09/20 23:45	General View		Load JPG	
26	17/09/20 23:45	General View		Load JPG	
27	17/09/20 23:45	General View		Load JPG	
28	17/09/20 23:45	General View		Load JPG	
29	17/09/20 23:45	General View		Load JPG	
30	17/09/20 23:45	General View		Load JPG	
31	17/09/20 23:45	General View		Load JPG	
32	17/09/20 23:45	General View		Load JPG	
33	17/09/20 23:45	General View		Load JPG	
34	17/09/20 23:45	General View		Load JPG	
35	17/09/20 23:45	General View		Load JPG	
36	17/09/20 23:45	General View		Load JPG	
37	17/09/20 23:45	General View		Load JPG	
38	17/09/20 23:45	Reinspection Photo		Load JPG	
39	17/09/20 23:45	Reinspection Photo		Load JPG	
40	17/09/20 23:45	Reinspection Photo		Load JPG	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	17/09/20 23:45	Reinspection Photo	Load JPG	☒
42	17/09/20 23:45	Reinspection Photo	Load JPG	☒
43	17/09/20 23:45	Reinspection Photo	Load JPG	☒
44	17/09/20 23:45	Reinspection Photo	Load JPG	☒
45	17/09/20 23:45	Reinspection Photo	Load JPG	☒
46	17/09/20 23:45	Reinspection Photo	Load JPG	☒
47	17/09/20 23:45	Reinspection Photo	Load JPG	☒
48	17/09/20 23:45	Reinspection Photo	Load JPG	☒
49	17/09/20 23:45	Reinspection Photo	Load JPG	☒
50	17/09/20 23:45	Reinspection Photo	Load JPG	☒
51	17/09/20 23:45	Reinspection Photo	Load JPG	☒
52	17/09/20 23:45	Reinspection Photo	Load JPG	☒
53	17/09/20 23:45	Reinspection Photo	Load JPG	☒
54	17/09/20 23:45	Reinspection Photo	Load JPG	☒
55	17/09/20 23:45	Reinspection Photo	Load JPG	☒
56	17/09/20 23:45	Reinspection Photo	Load JPG	☒
57	17/09/20 23:45	Reinspection Photo	Load JPG	☒
58	17/09/20 23:45	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/05/20 17:33	NOTIFICATION FROM WORKSHOP	Load PDF	
2	29/05/20 17:33	ACKNOWLEDGEMENT EMAIL TO AIG DD 29.05.2020	Load PDF	
3	30/05/20 17:50	EMAIL FROM AIG DD 29.05.2020	Load PDF	
4	30/05/20 17:50	TP GIA REPORT	Load PDF	
5	01/06/20 21:01	WHEEL ALIGNMENT REPORT	Load PDF	
6	07/09/20 17:29	EMAIL FROM AIG - APPROVAL TO REJECT TP CLAIM	Load PDF	
7	07/09/20 17:29	REJECT TP CLAIM EMAIL TO TP WORKSHOP	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	01/06/20 15:20	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20006038/AKA3S2**Date:** 24/09/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100453348
Claimant Vehicle No :	SMR4525C	Insured Vehicle No :	SKR7567K
Date of Loss:	28/05/2020	Nature of Claim:	TP
		Claim No:	0789394729SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR4525C		
Make & Model:	MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)	Engine No:	27492030950637
Reg. Date:	28/11/2017 (Man. Year: 2016)	Chassis No:	WDC2539462F210071
Colour:	White	Odometer:	22719 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	55,948.70	9,518.10	46,430.60	82.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,990.00	790.00	10,200.00	92.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	66,938.70	10,308.10	56,630.60	84.60
Approved Total (Overridden) (S\$)		8,200.00		
(S\$)	66,938.70	8,200.00	58,738.70	87.75
+ GST 7.00/7.00% (S\$)	4,685.71	574.00	4,111.71	87.75
Nett Amount (S\$)	71,624.41	8,774.00	62,850.41	87.75

INSPECTION

Date of Assignment:	29/05/2020	
Date Inspected:	01/06/2020 Inspected At:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (UPPER)	Deformed	2,196.00 FL	*2,196.00 FL
2	1		*FRONT BUMPER (LOWER)	Deformed	856.00 FL	*856.00 FL
3	1		*FRONT BUMPER FOGLAMP GARNISH RH	Not Necessary	95.00 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE (CENTER CHROME)	Not Necessary	396.00 FL	*- FL
5	2		*FRONT BUMPER LOWER GRILLE (SIDE CHROME)	Cracked	302.00 FL	*302.00 FL
6	1		*FRONT BUMPER SENSOR RH	Cracked 1pc Only	660.00 FL	*220.00 FL
			3pcs			
7	6		*FRONT BUMPER SENSOR HOLDER	Necessary	390.00 FL	*390.00 FL
8	1		*FRONT BUMPER SIDE RETAINER	O/s Necessary	296.00 FL	*148.00 FL
9	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	160.00 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	504.00 FL	*- FL
11	1		*FRONT BUMPER SPONGE	Cracked	198.00 FL	*198.00 FL
12	1		*HEAD LAMP RH	Cracked	3,528.00 FL	*3,528.00 FL
13	1		*HEAD LAMP LOWER BRACKET RH	Not Necessary	98.00 FL	*- FL
14	1		*HEAD LAMP SIDE BRACKET RH	Not Necessary	85.00 FL	*- FL
15	1		*FRONT FENDER RH	Repair	1,026.00 FL	*- FL
16	1		*FRONT FENDER ARCED GARNISH RH	Cut	277.00 FL	*277.00 FL
17	1		*FRONT FENDER COWLING RH (FRONT)	Not Necessary	213.00 FL	*- FL
18	1		*FRONT FENDER COWLING RH (REAR)	Not Necessary	156.00 FL	*- FL
19	1		*FRONT WHEEL RIM	O/s Cut	4,788.00 FL	*2,394.00 FL
20	2		*FRONT ABS SENSOR	Not Necessary	570.00 FL	*- FL
21	1		*FRONT STEERING RACK & PINION	Not Necessary	9,324.00 FL	*- FL
22	2		*FRONT WHEEL HUP WITH BEARING	Not Necessary	1,404.00 FL	*- FL
23	2		*FRONT SHOCK ABSORBER	Not Necessary	2,124.00 FL	*- FL
24	2		*FRONT KNUCKLE ARM	Not Necessary	2,880.00 FL	*- FL
25	2		*FRONT CASTER ARM	Not Necessary	1,908.00 FL	*- FL
26	2		*FRONT LOWER ARM	Not Necessary	1,656.00 FL	*- FL
27	2		*FRONT UPPER ARM	Not Necessary	1,886.00 FL	*- FL
28	2		*FRONT STABILIZER LINKAGE	Not Necessary	366.00 FL	*- FL
29	1		*REAR BUMPER TOP COVER CHROME	Not Necessary	376.00 FL	*- FL
30	1		*REAR BUMPER (UPPER)	Not Necessary	1,008.00 FL	*- FL
31	1		*REAR BUMPER (LOWER)	Not Necessary	727.00 FL	*- FL
32	1		*REAR BUMPER CHROME (CENTER)	Not Necessary	496.00 FL	*- FL
33	2		*REAR BUMPER REFLECTOR	Not Necessary	110.00 FL	*- FL
34	1		*REAR BUMPER TOWING COVER	Not Necessary	62.00 FL	*- FL
35	2		*REAR BUMPER EXHAUST CHROME	Not Necessary	794.00 FL	*- FL
36	2		*REAR BUMPER EXHAUST CHROME BRACKET	Not Necessary	306.00 FL	*- FL
37	4		*REAR BUMPER SENSOR	Not Necessary	876.00 FL	*- FL
38	6		*REAR BUMPER SENSOR HOLDER	Not Necessary	408.00 FL	*- FL
39	1		*REAR BUMPER SENSOR WIREHARNES	Not Necessary	896.00 FL	*- FL
40	2		*REAR BUMPER SIDE RETAINER	Not Necessary	310.00 FL	*- FL
41	2		*REAR BUMPER CENTER TOP BEAM	Not Necessary	336.00 FL	*- FL
42	1		*REAR BUMPER CENTER LOWER BEAM	Not Necessary	269.00 FL	*- FL
43	2		*REAR BUMPER LOWER BRACKET	Not Necessary	150.00 FL	*- FL
44	1		*REAR BUMPER REINFORCEMENT	Not Necessary	799.00 FL	*- FL
45	2		*TAILLAMP	Not Necessary	1,136.00 FL	*- FL
46	2		*TAILLAMP LOWER BRACKET	Not Necessary	304.00 FL	*- FL
47	2		*REAR FENDER COWLING	Not Necessary	394.00 FL	*- FL
48	2		*REAR WHEEL ARCED GARNISH	Not Necessary	556.00 FL	*- FL
49	1		*TAILGATE	Not Necessary	2,522.00 FL	*- FL
50	1		*TAILGATE LOGO	Not Necessary	84.00 FL	*- FL
51	1		*TAILGATE EMBLEM GLC	Not Necessary	96.00 FL	*- FL
52	1		*TAILGATE EMBLEM 250	Not Necessary	94.00 FL	*- FL
53	1		*TAILGATE EMBLEM 4MATIC	Not Necessary	125.00 FL	*- FL
54	1		*TAILGATE LOCK	Not Necessary	435.00 FL	*- FL
55	1		*TAILGATE FOOT SENSOR MODULE	Not Necessary	687.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*TAILGATE WEATHER STRIP	Not Necessary	383.00 FL	*- FL
57	1		*REAR END PANEL	Not Necessary	1,372.00 FL	*- FL
58	1		*REAR END PANEL INNER GARNISH	Not Necessary	389.00 FL	*- FL
59	1		*REAR FLOOR TOP COVER BOARD	Not Necessary	1,203.00 FL	*- FL
60	1		*REAR EXHAUST BOX	Not Necessary	2,192.00 FL	*- FL
61	2		*REAR EXHAUST INSULATOR	Not Necessary	538.00 FL	*- FL
62	4		*REAR EXHAUST MOUNTING	Not Necessary	168.00 FL	*- FL
63	1		*SET FRONT BUMPER CLIP	Necessary	120.00 FS	*30.00 FS
64	1		*SET FRONT BUMPER FOGLAMP GARNISH CLIP LH	Not Necessary	40.00 FS	*- FS
65	1		*SET FRONT BUMPER BOTTOM GARNISH CLIP	Necessary	30.00 FS	*- FS
66	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
67	1		*SET FRONT FENDER ARCED GARNISH CLIP	Necessary	80.00 FS	*30.00 FS
68	2		*FRONT WHEEL TYTRE	Not Necessary	1,360.00 FS	*- FS
69	1		*REAR NUMBER PLATE (SPECIAL TYPE)	Not Necessary	180.00 FS	*- FS
70	1		*SET REAR BUMPER CLIP	Not Necessary	120.00 FS	*- FS
71	1		*SET TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
72	1		*SET REAR FENDER COWLING CLIP	Not Necessary	60.00 FS	*- FS
73	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
74	1		*SET REAR WHEEL ARCED GARNISH CLIP	Not Necessary	60.00 FS	*- FS
75	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
76	1		*TAILGATE WINDSCREEN GLASS SEALANT	Not Necessary	120.00 FS	*- FS
77	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Not Necessary	80.00 FS	*- FS
78	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	60.00 FS	*- FS
79	1		*REAR END PANEL INSULATION SEAL	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	61,843.00	10,569.00
- List Item Discount on L Items 10.00/10.00% (\$)	5,894.30	1,050.90
Total Parts (\$)	55,948.70	9,518.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS.	New	3,400.00	250.00
2	SPRAY PAINTING TO AFFECTED AREA.	New	3,400.00	250.00
3	WIRING CHECK.	New	150.00	30.00
4	REFOCUS HEADLAMP BEAM.	New	60.00	0.00
5	REMOVE AND REPLACE FRONT BUMPER SENSOR.	New	120.00	60.00
6	REMOVE AND REFIX FRONT UNDERCARRIAGE.	New	650.00	0.00
7	TO PRESS FRONT WHEEL BEARING.	New	120.00	0.00
8	FOUR WHEEL ALIGNMENT.	New	120.00	80.00
9	RESET ABS LIGHT.	New	480.00	0.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	650.00	120.00
11	TUFF COAT.	New	350.00	0.00
12	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.	New	350.00	0.00
13	CONDUCT WATER LEAKAGE TEST.	New	180.00	0.00
14	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	New	80.00	0.00
15	REMOVE AND REFIX AND RESET VIDEO RECORDER.	New	80.00	0.00
16	REMOVE AND REFIX AND RESET TAILGATE FOOR SENSOR.	New	180.00	0.00
17	REMOVE AND REFIX TAILGATE WINDSCREEN GLASS.	New	120.00	0.00
18	REMOVE AND REFIX REAR EXHAUST PIPE.	New	250.00	0.00
19	REAR CHASSIS ALIGNMENT.	New	250.00	0.00
Gross Labour Cost (\$\$)			10,990.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >