



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 8240P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	830.00	-
1	FRONT BUMPER SIDE RETAINER LHS (CONSISTENT)	NOT NECESSARY	70.00	-
10	FRONT BUMPER CLIPS @\$4.00 (CONSISTENT)	NOT NECESSARY	40.00	-
2	FRONT BUMPER RIVET @\$5.00 (CONSISTENT)	NOT NECESSARY	10.00	-
1	FRONT BUMPER FOGLAMP COVER LHS (CONSISTENT)	CUT	75.00	75.00
1	FRONT FENDER LHS (CONSISTENT)	BENT	395.00	395.00
1	FRONT FENDER SPLASH SHIELD LHS (CONSISTENT)	NOT NECESSARY	148.00	-
10	FRONT FENDER SPLASH SHIELD CLIPS LHS @\$4.00 (CONSISTENT)	NOT NECESSARY	40.00	-
1	FRONT FENDER LOWER AIR DEFLECTOR LHS (CONSISTENT)	NOT NECESSARY	75.00	-
1	FRONT DOOR LHS (CONSISTENT)	TO REPAIR SEE LABOUR	1,000.00	-
1	FRONT HEADLAMP LHS (CONSISTENT)	NOT NECESSARY	1,020.00	-
1	FRONT SIDE MIRROR COVER LHS (CONSISTENT)	TO REPAIR SEE LABOUR	155.00	-
1	FRONT SIDE MIRROR ASSY LHS (CONSISTENT)	CUT	398.00	398.00
	LESS 20% DISCOUNT		-851.20	-
	LESS 25% DISCOUNT		-	-217.00
			3,404.80	651.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT WHEEL HUP CAP LHS (CONSISTENT) (SN)	CUT	145.00	145.00
1	FRONT RIM LHS (CONSISTENT) (SN)	TO REPAIR SEE LABOUR	500.00	-
			645.00	145.00
<u>LABOUR</u>				
	TO REMOVE & REFOCUS FRONT HEADLAMP.	NOT NECESSARY	120.00	-
	TO CONDUCT WHEEL ALIGNMENT.		180.00	60.00
	TO REMOVE & REPLACED TYRE ,RIM & CONDUCT WHEEL BALANCING.	NOT NECESSARY	180.00	-
	TO APPLY RUSTPROOFING & TUFFCOATING TREATMENT.		120.00	30.00

Report Ref No. CC4/ASM19006142/T1ga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO KNOCKING & PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER ,FRONT DOOR LHS ,FRONT SIDE MIRROR COVER LHS AND FRONT RIM LHS .		1,200.00	500.00
	TO PUTTY & SPRAY PAINTING.		1,000.00	650.00
	TO REMOVE & REPLACED FRONT SIDE MIRROR & CONDUCT WIRING SYSTEM.		150.00	30.00
			2,950.00	1,270.00
GRAND TOTAL			6,999.80	2,066.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,650.00

Report Ref No. CC4/ASM19006142/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.