

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 29.05.2020

Accident Date : 14.04.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Rav4" Reg. No. SKM6589E Claiming Against Your Insured Reg. No. GBF7373B		
		B/F	-
1pc	license Plate		25.00 SN ✓
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		40.00 201
	To Remove / Replace Air Con Condenser & Refill Air Con Gas		120.00 X
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		80.00 X
	Labour Charge - Panel Beating, Repairing Of Bonnet, Front Fender RH Support Panel and Parts Replacement		800.00 4001
	To Respray Affected Areas		900.00 6001
		Total :	<u>1,965.00</u>

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorised
11 Sep 8?
Resurvey After Paint
4 days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 29.05.2020

Accident Date : 23.04.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Toyota Rav4" Reg. No. SKM6589E Claiming Against Your Insured Reg. No. GBF7373B			
1pc	Front Bumper <i>Br-</i>		
16pc	Front Bumper Clips <i>me-</i>		
1pc	Front Bumper Bracket RH <i>?</i>		
1pc	Front Bumper Sponge <i>?</i>		
1pc	Front Bumper Beam <i>?</i>		
1pc	Front Bumper Reinforcement <i>?</i>		
1pc	Front Bumper Top Retainer <i>?</i>		
1pc	Front Bumper Core (Plastic) <i>?</i>		
1pc	Front Bumper Corner Holder RH <i>Di-</i>		
1pc	Front Bumper Fog lamp RH <i>Sur-</i>		
1pc	Front Bumper Fog Lamp Bracket RH <i>?</i>		
1pc	Front Bumper Center Cover <i>Not/lot-</i>		
1pc	Front Bumper Air Grille <i>in X</i>		
1pc	Front Bumper Lower Air Grille <i>Not-</i>		
1pc	Front Bumper Lower Beam <i>?</i>		
1pc	Front Bumper Emblem <i>me-</i>		
1pc	Front Bumper Lower Lip <i>Not/lot</i>		
1pc	Front Bumper Lower Lip Chrome Moulding <i>Not-</i>		
1pc	Front Bumper Side Protector RH <i>Di-</i>		
1pc	Front Bumper Tow Cover <i>Gr-</i>		
1pc	Front Bumper Rubber Seal <i>me-</i>		
1pc	Front Grille RH <i>me-</i>		
1pc	Front Grille Chrome Moulding <i>me-</i>		
1pc	Headlamp RH (HID) <i>CR-</i>		
1pc	Headlamp Panel RH <i>12 X</i>		
1pc	Aircon Condenser <i>in X</i>		
1pc	Aircon Condenser Air Guide RH <i>Sur X</i>		
1pc	Wiper Tank <i>Not -</i>		
1pc	Wiper Tank Motor <i>in X</i>		
1pc	Front Fender Shield RH <i>?</i>		
10pcs	Front Fender Shield Clips <i>?</i>		
Less 25%			

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: