

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20006045/FPA3Q2

Date:

08/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800049438

Claimant Vehicle No : SHC3995Z**Insured Vehicle No :**

SLP1819Y

Date of Loss: 29/05/2020

Nature of Claim:

TP

Claim No:

1095141663SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC3995Z**

Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A)

Engine No:

G4LEKU407363

Reg. Date: 27/02/2020 (Man. Year: 2019)

Chassis No:

KMHC851CVLU189539

Colour: Blue

Odometer:

28136 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Michelin 9 mm

Rear Left Side:

Michelin 9 mm

Front Right Side: Michelin 9 mm

Rear Right Side:

Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,961.72	976.12	1,985.60	67.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,150.00	480.00	29.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,591.72	2,126.12	2,465.60	53.70
+ GST 7.00/7.00% (S\$)	321.42	148.83	172.59	53.70

Nett Amount (S\$)	4,913.14	2,274.95	2,638.19	53.70
+ Loss of Use (4.5 x S\$50.00/day) (S\$)		225.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,507.44		
Global Sum Settlement (S\$)		2,500.00		

INSPECTION

Date of Assignment: 01/06/2020

Date Inspected: 01/06/2020

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: PARASURAM SHANMUGAM**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Cracked	459.40 FL	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT BRACKET -RH	Not Necessary	138.10 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 FL	*- FL
6	1		*REAR BUMPER SIDE BRACKET -RH	Not Necessary	55.80 FL	*- FL
7	1		*REAR BUMPER UNDERCOVER	Not Necessary	225.00 FL	*- FL
8	1		*REAR FENDER -RH	Repair	1,768.30 FL	*- FL
9	1		*REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
10	1		*REAR BUMPER PROTECTOR	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,644.65	1,162.65
- List Item Discount on L Items 20.00/20.00% (S\$)	682.93	186.53
Total Parts (S\$)	2,961.72	976.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE	New	700.00	480.00
2	SPRAY PAINTING CHARGE	New	500.00	400.00
3	WIRING CHARGE	New	80.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	100.00	60.00
5	COMPUTER PROGRAMMING FOR BSD	New	250.00	180.00
Gross Labour Cost (S\$)			1,630.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >