

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305401236

Date : 9. Jun. 2020

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SHC3995Z

Date of Accident: 29. May. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG SLP1819Y

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$976.12

(b) Labour Charges

\$1,150.00

Total for Part-By-Part Repair Cost

\$2,126.12

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: _____

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : Larry Ng

Signature : Ram

Name : Larry Ng

Name : Ram

Tel : 6214 8316

Date : 9/6/2020

Fax : 6546 8156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 08.06.2020

Time: 14:24:19

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305401236
REGN NO : SHC3995Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 27.02.2020
DATE/TIME IN : 30.05.2020 08:20
ACCIDENT DATE : 29.05.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52	rep/ava
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	nec
0003 04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1	451.25	20.00	361.00	ref
0004 04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1	50.00		50.00	nec
0005 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	180.00		180.00	an

SUB-TOTAL : 976.12

JOB NATURE

0000 PB	PANEL BEATING	480.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	400.00
0002 17-01	WIRING CHARGE	30.00
0003 L	REMOVE/REFIX REVERSE SENSOR	60.00
0004 L	Computer Programming for BSD	180.00

SUB-TOTAL : 1,150.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC3995Z

DATE: 30. May. 2020

MAKE : HYUNDAI

MODEL : IONIQ

DOA: 29. May. 2020

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper <i>def / crg</i>			\$459.40
10	Rear Bumper Clips <i>nee</i>		\$2.20	\$22.00
1	Rear Bumper Centre Molding <i>def</i>			\$451.25
1	Rear Bumper Reinforcement Bracket – RH <i>pxm</i>			\$138.10
1	Rear Bumper Reinforcement <i>pxm</i>			\$294.80
1	Rear Bumper Side Bracket – RH <i>xnn</i>			\$55.80
1	Rear Bumper Undercover <i>xnn</i>			\$225.00
1	Rear Fender – RH <i>x(R)</i>			\$1,768.30
SUB TOTAL				\$3,414.65
LESS 20%				\$682.93
DISCOUNTED TOTAL				\$2,731.72
1	Reverse Sensor <i>pm</i>			\$180.00
1	Rear Bumper Protector <i>nee</i>			\$50.00
				Nett
				Nett
				\$230.00
Labour Charge				
1	Labour Charge			\$700.00
1	Spray Painting Charge			\$500.00
1	Wiring Charge			\$80.00
1	Remove / Refix Reverse Sensor			\$100.00
1	Computer Programming for BSD			\$250.00
TOTAL LABOUR				\$1,630.00
ESTIMATE TOTAL				\$4,591.72
* BSD – Blind Spot Detetion *				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (LKK)

1/6/2020

Rameshram@lkk.co

88622712

(P/R)

Ref paint photo

(3 repair days)

\$480

\$400

\$30

\$60

\$180

Nett

Nett

\$180

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1

RE: SHC3995Z VS SLP1819Y (AIG) DOA: 29.05.2020

AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>

Mon 1/6/2020 8:40 AM

To: Ng Nyuk Phin <ngnp@cdge.com.sg>

Cc: Lim Kwok Eng <limke@cdge.com.sg>

CAUTION: This email originated from an external party outside ComfortDelGro. Do not click on links or open attachment unless you know the sender.

Hi Larry,

We'll appoint LKK to conduct survey.

Thanks.

AIG Claims Survey

From: Ng Nyuk Phin [mailto:ngnp@cdge.com.sg]

Sent: Saturday, May 30, 2020 11:57 AM

To: AIG SGP, Claims-Survey

Cc: Lim Kwok Eng

Subject: [EXTERNAL] SHC3995Z VS SLP1819Y (AIG) DOA: 29.05.2020

This message is from an external sender; be cautious with links and attachments.

Dear Motor Claims,

Please see attached Repair Estimate and SAS. Kindly arrange to survey the taxi at 59 Loyang Drive.

Regards,

Larry Ng

ComfortDelgro Engineering Pte Ltd

Loyang Taxi Crash Repair

6214 8316



Think Before Printing

From: canon@comfortdelgro.com.sg <canon@comfortdelgro.com.sg>

Sent: Saturday, 30 May 2020 11:53 AM

To: Ng Nyuk Phin

Subject: Scan Image