Page 1 of 5 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20006058/ATF3E2

L15B5561693

Date: 29/07/2020

**REFERENCE** 

No:

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle SMJ8210B Insured Vehicle No: YP7598R

ΤP Date of Loss: 27/05/2020 Nature of Claim: Claim No: CDMCG20000721

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMJ8210B

HONDA VEZEL, 1.5 CVT ABS D/AIRBAG 2WD 5DR Make & Model: Engine No:

Reg. Date: 21/03/2019 (Man. Year: 2018) Chassis No: RU11311682 Colour: White Odometer: 42677 km

**Engine Capacity:** 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: Nο

**CONDITION OF TYRES** 

Front Tyre Size: Rear Tyre Size: 215/60 R16 215/60 R16 Front Left Side: Rear Left Side: Dunlop 6 mm Dunlop 6 mm Front Right Side: Rear Right Side: Dunlop 6 mm Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,580.00	165.00	2,415.00	93.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,022.00	1,310.00	8,712.00	86.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,602.00	1,475.00	11,127.00	88.30
+ GST 7.00/7.00% (S\$)	882.14	103.25	778.89	88.30
Nett Amount (S\$)	13,484.14	1,578.25	11,905.89	88.30

INSPECTION

Date of Assignment: 01/06/2020

Date Inspected: 02/06/2020 Inspected At: 24 BENOI SECTOR

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$100.00 NETT) Adjuster Report Page 4 of 5

# **REPAIR DETAILS**

Reference
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jul 2020)

Parts: 144 HONDA VEZEL 1.5 CVT ABS D/AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMJ8210B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER RH	Deformed	165.00 FS	*165.00 FS
2	1		*REAR FENDER RH	Repair	1,440.00 FS	*- FS
3	1		*REAR BUMPER SIDE GUIDE RH	Not Necessary	45.00 FS	*- FS
4	2		*REAR WHEEL COVER LH / RH	Not Necessary	330.00 FS	*- FS
5	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
6	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
7	1		*METAL FILLER POWDER	Not Necessary	180.00 FS	*- FS
8	1		*SUNDRIES	* Check	100.00 FS	*- FS
F=Fra	anchise	part. S=SpcN	ett.	_		
				Total Parts (S\$)	2,580.00	165.00

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	60.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	0.00
3	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	0.00
5	TO DISMANTLE AND RENEW REAR BUMPER. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,500.00	700.00
6	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS		3,250.00	550.00
	Gross Labou	r Cost (S\$)	10,022.00	1,310.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >