



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 6809L

| Qty | Description of Parts  | Condition        | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>  |                  |                           |                   |
| 1   | BONNET  | BENT             | 797.40                    | 797.40            |
| 1   | BONNET HINDGE (LH)  | NOT NECESSARY    | 93.90                     | -                 |
| 1   | HEAD LAMP (LH)  | SCRATCHED        | 895.30                    | 895.30            |
| 1   | FRONT BUMPER  | DENTED           | 648.90                    | 648.90            |
| 1   | FRONT BUMPER RETAINER (LH)  | NOT NECESSARY    | 75.80                     | -                 |
| 1   | FRONT REINFORCEMENT   | BENT             | 545.20                    | 545.20            |
| 5   | FRONT BUMPER CLIPS @\$3.00  | NECESSARY        | 15.00                     | 15.00             |
| 1   | FOG LIGHT (LH)  | MTG CRACKED      | 189.80                    | 189.80            |
| 1   | FOG LIGHT COVER (LH)  | CUT / DENTED     | 110.90                    | 110.90            |
| 1   | FRONT BUMPER LOWER SPOILER  | CUT              | 590.20                    | 590.20            |
| 1   | FRONT BUMPER LOGO   | NECESSARY        | 88.20                     | 88.20             |
| 1   | FRONT RADIATOR SUPPORT PANEL  | NOT NECESSARY    | 564.30                    | -                 |
| 1   | FRONT GRILLE  | CRACKED / BROKEN | 342.80                    | 342.80            |
| 1   | FRONT NUMBERS PLATE   | NOT NECESSARY    | 60.00                     | -                 |
|     | LESS 15% DISCOUNT   |                  | -752.66                   | -                 |
|     | LESS 20% DISCOUNT   |                  | -                         | -844.74           |
|     |   |                  | 4,265.04                  | 3,378.96          |
|     | <b><u>LABOUR</u></b>  |                  |                           |                   |
|     | LABOUR TO DISMANTLE AND CHANGE ALL DAMAGED PARTS.                           |                  | 1,000.00                  | 600.00            |
|     | TO PUTTY AND SPRAY PAINT.   |                  | 800.00                    | 500.00            |
|     | TO DO UNDERCOATING.   |                  | 60.00                     | 30.00             |
|     | TO CHECK WIRING.  |                  | 40.00                     | 30.00             |
|     |   |                  | -                         | -                 |
|     |   |                  | -                         | -                 |
|     |   |                  | 1,900.00                  | 1,160.00          |
|     | <b>GRAND TOTAL</b>  |                  | <b>6,165.04</b>           | <b>4,538.96</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                  |                           | <b>3,600.00</b>   |



Report Ref No. CS/UOI20006059/Dvf3e2

A handwritten signature in black ink, appearing to be 'ANG BRYAN TANI'.

**ANG BRYAN TANI**

**Automotive Assessor / Investigator**

A handwritten signature in black ink, appearing to be 'ADRIAN LING WAI PING'.

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**