



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2004534
INV Date 24/06/2020
Reference CS/SMO20006066/Kqf3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SLJ 9396D
Insured Veh. SLC 6809L
Claim No. CMTD2001695/THE
Policy No.
Accident Date 31/05/2020
Inspection Date 02/06/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20006066/Kqf3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 24-06-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLC 6809L	Veh. Inspected	SLJ 9396D	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2001695/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	01/06/2020	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN TOURAN (A)	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WVGZZZ1TZHW024665	Colour	METALLIC BROWN	
Odometer	70556	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	8 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	8 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	8 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/05/2020	Inspection Date	02/06/2020	
Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 9396D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CRACKED	721.50	721.50
1	REAR BUMPER REINFORCEMENT	BENT	319.20	319.20
1	REAR BUMPER SPONGE	SERVICEABLE	241.70	-
1	REAR BUMPER SIDE RETAINER-LH	DISTORTED	32.40	32.40
1	REAR BUMPER REFLECTOR-LH	SCRATCHED	63.40	63.40
1	REAR BUMPER LOWER GARNISH	SCRATCHED	381.60	381.60
	LESS 10% DISCOUNT		-175.98	-151.81
			1,583.82	1,366.29
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
			280.00	-
	<u>LABOUR</u>			
	TO PULL,KNOCK ON REAR ACCIDENT PORTION & CHANGE THE ABOVE PARTS.		480.00	300.00
	TO SPRAY & PAINT ON REAR ACCIDENT PORTION.		580.00	450.00
	TO ANTI-RUST REAR AFFECTED AREAS.	NOT NECESSARY	60.00	-
	TO CHECK WIRING FUNCTIONS.		50.00	15.00
	TO DISMANTLE AND CHAGNE 1 SET REVERSE SENSOR.		50.00	50.00
			1,220.00	815.00
	GRAND TOTAL		3,083.82	2,181.29
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,750.00

Report Ref No. CS/SMO20006066/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 9396D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



WVGZZZ1TZW024665



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 9396D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLJ 9396D

RE-INSPECTION

