

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20006080/UPA3Q2

Date: 11/08/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	GBE625Y	Insured Vehicle No :	GBH6037P
Date of Loss:	29/05/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0001030

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE625Y		
Make & Model:	NISSAN NV350, 2.5 5MT 5DR EURO V (A)	Engine No:	YD25376155A
Reg. Date:	27/08/2015 (Man. Year: 2015)	Chassis No:	JN1MC2E26Z0004807
Colour:	White	Odometer:	246698 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,823.50	6,107.19	1,716.31	21.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,735.00	1,935.00	800.00	29.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,558.50	8,042.19	2,516.31	23.83
Approved Total (Overridden) (\$\$)		6,400.00		
(\$\$)	10,558.50	6,400.00	4,158.50	39.39
+ GST 7.00/7.00% (\$\$)	739.10	448.00	291.10	39.39
Nett Amount (\$\$)	11,297.60	6,848.00	4,449.60	39.39
+ Loss of Use (5.0 x S\$80.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		7,255.45		

INSPECTION

Date of Assignment: 01/06/2020

Date Inspected: 01/06/2020 Inspected At:

NPH Auto Service (HQ)
Blk 9005 Tampines Steet 93, #01-
246/254
Singapore 528839

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Jul 2020)	
Parts:	N/A	NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE625Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented	2,264.60 F	*2,264.60 FL
2	1		*REAR BOOT NISSAN LOGO	Necessary	65.70 F	*65.70 FL
3	1		*REAR BOOT NV350 EMBLEM	Necessary	101.30 F	*101.30 FL
4	1		*REAR BOOT URVAN EMBLEM	Necessary	59.70 F	*59.70 FL
5	1		*REAR BOOT NUMBER PLATE LAMP CHROME GARNISH	Cracked	511.40 F	*511.40 FL
6	2		*REAR LAMP ASSEMBLY LH & RH	Cracked	419.60 F	*419.60 FL
7	1		*REAR BUMPER	Dented / Deformed	600.50 F	*600.50 FL
8	8		*REAR BUMPER CLIPS	Necessary	40.80 F	*24.00 FL
9	1		*REAR BOOT RUBBER SEAL	Necessary	127.00 F	*127.00 FL
10	1		*REAR BOOT LOCK CENTER	Jammed	256.70 F	*256.70 FL
11	2		*REAR BOOT SIDE LOCK W/SPRING L&R	Not Necessary	96.00 F	*- FL
12	2		*REAR BUMPER SIDE CATCH L&R	Necessary	96.00 F	*96.00 FL
13	1		*REAR END PANEL LOCK LOWER CATCH	Not Necessary	58.00 F	*- FL
14	1		*REAR BUMPER INNER STEP PANEL	Bent	178.00 F	*178.00 FL
15	1		*REAR END PANEL (OUTER)	Badly Dented	168.00 F	*168.00 FL
16	1		*REAR END PANEL (INNER)	Badly Dented	411.80 F	*411.80 FL
17	2		*REAR BOOT RUBBER SIDE STOPPER L&R	Not Necessary	22.00 F	*- FL
18	1		*REAR BOOT INNER CENTER CARPET GARNISH	Torn	160.00 F	*160.00 FL
19	16		*REAR BOOT INNER CENTER CARPET GARNISH CLIPS	Necessary	81.60 F	*62.40 FL
20	1		*REAR BOOT INNER CENTER METAL COVER	Deformed	109.00 F	*109.00 FL
21	1		*REAR ROCKER PANEL TOP ALUMINIUM BAR	Bent	280.00 F	*280.00 FL
22	2		*REAR BOOT DAMPER L&R	Not Necessary	411.80 F	*- FL
23	2		*REAR BOOT HINGE L&R	Not Necessary	104.00 F	*- FL
24	6		*REAR BUMPER SIDE RETAINER CLIP L+R	Necessary	84.00 F	*23.40 FL
25	1		*REAR WIPER MOTOR INNER COVER	Not Necessary	65.00 F	*- FL
26	2		*REAR BOOT NUMBER PLATE LAMP L&R	Not Necessary	156.00 F	*- FL
27	1		*REAR BOOT 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
28	1		*REAR BOOT 8 PAX STICKER	Necessary	15.00 FS	*10.00 FS
29	1		*REAR NUMBER PLATE (YELLOW)	Bent	40.00 FS	*20.00 FS
30	1		*REAR BUMPER PARKING SENSOR	Shorted	200.00 FS	*200.00 FS
31	1		*REAR BOOT CARPET FLOORBOARD (WHOLE PIECE)	Cracked	580.00 FS	*500.00 FS
32	1		*REAR WINDSCREEN SEALANT	Necessary	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,823.50	6,699.10
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	591.91
Total Parts (\$\$)	7,823.50	6,107.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND INSTALL REAR WINDSCREEN	New	150.00	120.00
2	REMOVE AND INSTALL REAR BOOT ,REAR BUMPER ,REAR LAMP ASSEMBLY L&R ,REAR BUMPER ENFORCEMENT .CUT OUT AND RENEW REAR END PANEL INNER AND OUTER,KNOCKING REAR FENDER L&R ,REAR FENDER INNER L&R .RESTRAIGHTEN BODY AND CHASSIS	New	1,200.00	800.00
3	SPRAY PAINTING	New	1,200.00	900.00
4	REMOVE REAR BOT CARPET AND LINING	New	80.00	40.00
5	CHECK WIRING SYSTEM	New	25.00	25.00
6	RENEW REAR PARKING SENSOR	New	80.00	50.00
Gross Labour Cost (\$\$)			2,735.00	1,935.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >