

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20006085/UBA3Q2

Date: 18/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLZ961Y	Insured Vehicle No :	SHC3542Y
Date of Loss: 29/05/2020	Nature of Claim: TP	Claim No: MCT20050220

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ961Y	
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Engine No: R16B25500530
Reg. Date:	23/04/2018 (Man. Year: 2018)	Chassis No: MRHFC5650JT000478
Colour:	White	Odometer: 42146 km
Engine Capacity:	1597 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R16	Rear Tyre Size:	215/55R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	529.09	483.49	45.60	8.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,100.00	1,000.00	47.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,629.09	1,583.49	1,045.60	39.77
+ GST 7.00/7.00% (S\$)	184.04	110.84	73.20	39.77
Nett Amount (S\$)	2,813.13	1,694.33	1,118.80	39.77
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
Nett Liability (S\$)		1,874.33		

INSPECTION

Date of Assignment:	02/06/2020	
Date Inspected:	03/06/2020	Inspected At: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2020)
Parts:	143	HONDA CIVIC 1.6 VTi CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ961Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACEFR BUMPER	Torn	434.92 FS	*434.92 FS
2	1		*GARNISHR.FR.BUMPER SIDE	Grazed	14.77 FS	*14.77 FS
3	1		*SPACERR.FR.BUMPER SIDE	Not Necessary	7.80 FS	*- FS
4	1		*SPACERL.FR.BUMPER SIDE	Not Necessary	7.80 FS	*- FS
5	1		*CLIP .BUMPER (8 PCS)	Necessary	13.80 FS	*13.80 FS
6	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **529.09** **483.49**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON	New	1,200.00	650.00
2	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	900.00	450.00
Gross Labour Cost (S\$)			2,100.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >