



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2005544  
INV Date 13/08/2020  
Reference CC4/FCI20006089/Ads3n2  
Code FCI2



### PROFESSIONAL SERVICE FEE

Vehicle No. SGY 6507B  
Insured Veh. SHD 6910T  
Claim No. D20002275MFSH  
Policy No. D-20094922MFSH  
Accident Date 31/05/2020  
Inspection Date 02/06/2020

Description	Total
Third Party Express Settlement	500.00
<b>Subtotal</b>	<b>500.00</b>
<b>GST (7%)</b>	<b>35.00</b>
<b>Grand Total</b>	<b>535.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20006089/Ads3n2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-08-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6910T	Veh. Inspected	SGY 6507B
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20002275MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	02/06/2020

### 2. Vehicle Particulars & Condition

Make & Model	HONDA STREAM	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	RN61044890	Colour	SILVER
Odometer	320212	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	31/05/2020	Inspection Date	02/06/2020
Survey held at	JOO HAK KEE AUTO PTE LTD 3007 UBI ROAD 1 #01-406 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408701		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 6507B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET	DENTED	866.90	685.20
1	BONNET LOCK	DAMAGED	155.00	155.00
1	FRONT GRILLE	CRACKED	428.00	285.40
1	FRONT GRILLE CHROME	CRACKED	255.90	255.90
1	FRONT GRILLE EMBLEM	NECESSARY	48.80	48.80
2	FRONT R/H FENDER @\$637.00	TO REPAIR SEE LABOUR	1,274.00	-
2	FRONT R/H FENDER TOP GARNISH @\$350.80	NOT NECESSARY	701.60	-
2	RH/LH HEADLAMP @\$1850.00	CRACKED	3,700.00	1,378.60
2	RH/LH HEADLAMP LOWER BRACKET @\$51.60	CRACKED	103.20	103.20
1	FRONT BUMPER	DEFORMED	1,285.00	689.00
1	FRONT BUMPER REINFORCEMENT	BENT	440.00	239.70
2	FRONT BUMPER SIDE RETAINER LH/RH @\$97.00	NECESSARY	194.00	68.00
10	FRONT BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	220.00	-
1	FRONT SUPPORT PANEL	BUCKLED	728.80	466.30
1	FRONT SUPPORT PANEL TOP GARNISH	DEFORMED	108.50	108.50
1	AIR CON CONDENSER	DENTED	1,550.00	826.60
	LESS 20% DISCOUNT		-2,421.94	-1,068.04
			9,687.76	4,272.16
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	NUMBER PLATE WITH COVER (SN)	CRACKED	50.00	50.00
			50.00	50.00
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT R/H FENDER .		600.00	500.00
	TO SAND DOWN ,PUTTY AND SPRAY PAINT ON NECESSARY DAMAGED PARTS.		1,000.00	600.00
	TO CHECK ALL WIRING.		50.00	30.00
	TO ALIGN HEADLAMP.	NOT NECESSARY	50.00	-

Report Ref No. CC4/FCI20006089/Ads3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO VACUUM & REFILL AC REFRIDGERANT.		120.00	60.00
	TO DISMANTLE & REINSTALL RADIATOR & AC.		100.00	60.00
			1,920.00	1,250.00
GRAND TOTAL			11,657.76	5,572.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,450.00

Report Ref No. CC4/FCI20006089/Ads3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGY 6507B

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGY 6507B

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

