



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2004477
INV Date 23/06/2020
Reference CS/AGI20006090/Atf3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. GBK 4400X
Insured Veh. SGW 4128K
Claim No. C10006390
Policy No.
Accident Date 01/06/2020
Inspection Date 03/06/2020

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20006090/Atf3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRES SINGAPORE

239924

Date : 23-06-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGW 4128K	Veh. Inspected	GBK 4400X
Policy No.		Coverage (\$)	0.00
Claim No.	C10006390	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	02/06/2020

2. Vehicle Particulars & Condition

Make & Model	MAXUS G10	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	LSKG4AL10LA043565	Colour	GREY
Odometer	3240	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16C	HANKOOK	6 mm
L/H Front Tyre	215/60 R16C	HANKOOK	6 mm
R/H Rear Tyre	215/60 R16C	HANKOOK	6 mm
L/H Rear Tyre	215/60 R16C	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/06/2020	Inspection Date	03/06/2020
Survey held at	DYNAMIC AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4 #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 4400X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR RH	DENTED	1,899.00	1,650.00
1	FRONT DOOR BLACK STICKER RH	NECESSARY	125.10	125.10
1	FRONT DOOR OUTER STRIP RH	NOT NECESSARY	107.30	-
2	FRONT DOOR HINGE RH @\$73.20	NOT NECESSARY	146.40	-
1	FRONT DOOR INNER LOCK RH	NOT NECESSARY	534.70	-
1	FRONT DOOR INNER TRIM RH	CRACKED	890.20	655.00
1	FRONT DOOR LOCK CATCHER RH	NOT NECESSARY	30.40	-
1	FRONT DOOR WEATHER STRIP RH	NOT NECESSARY	171.20	-
1	FRONT DOOR POWER WINDOW MOTOR RH	NOT NECESSARY	679.80	-
1	FRONT DOOR REGULATOR RH	NOT NECESSARY	243.20	-
1	CENTER PILLAR (OUTER) RH	NOT NECESSARY	307.70	-
1	CENTER PILLAR CHASSIS NUMBER PLATE	NOT NECESSARY	240.30	-
1	SLIDING DOOR RH	DENTED	1,947.00	1,750.00
1	SLIDING DOOR BLACK STICKER RH	NECESSARY	120.40	120.40
1	SLIDING DOOR ROLLER RH (LOWER)	NOT NECESSARY	332.70	-
1	SLIDING DOOR LOCK CATCHER RH	NOT NECESSARY	40.00	-
1	SLIDING DOOR INNER LOCK RH	NOT NECESSARY	536.40	-
1	SLIDING DOOR OUTER STRIP RH	NOT NECESSARY	137.60	-
1	SLIDING DOOR STOPPER	NOT NECESSARY	64.30	-
1	SLIDING DOOR FRAME WEATHER STRIP RH	NOT NECESSARY	386.50	-
	LESS 10% DISCOUNT		-894.02	-430.05
			8,046.18	3,870.45
<u>SPECIAL NETT ITEMS</u>				
1	FRONT DOORSEALANT RH (SN)	NOT NECESSARY	150.00	-
1	SET FRONT DOOR INNER TRIM CLIP RH (SN)	NECESSARY	60.00	30.00
1	SET FRONT DOOR LTA STICKER (SN)	NECESSARY	40.00	20.00
1	SLIDING DOOR SEALANT RH (SN)	NOT NECESSARY	150.00	-
1	SET SLIDING DOOR INNER TRIM RIVERT RH (SN)	NECESSARY	80.00	20.00
1	SET SLIDING DOOR STEP PANEL GARNISH CLIP RH (SN)	NOT NECESSARY	40.00	-
1	SLIDING DOOR WINDOW PLATE SEALANT (SN)	NOT NECESSARY	150.00	-

Report Ref No. CS/AGI20006090/Atf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SLIDING DOOR WINDOW PLATE INNER SEAL (SN)	NOT NECESSARY	60.00	-
1	SLIDING DOOR INNER STANDARD STEEL TRIM (SEPC) (SN)	NOT NECESSARY	650.00	-
1	CENTER PILLAR BLACK STICKER (SN)	NOT NECESSARY	180.00	-
			1,560.00	70.00
	LABOUR			
	PANEL BEATING, REMOVING AND REPLACING PARTS.		1,800.00	400.00
	SPRAY PAINTING TO AFFECTED AREA.		1,800.00	500.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK.		180.00	30.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.	NOT NECESSARY	250.00	-
	REMOVE & REFIX AUDIO SPEAKER.	NOT NECESSARY	120.00	-
	TRANSFER FRONT DOOR MECHANISM RH.		80.00	40.00
	REMOVE & REINSTALL FRONT WINDOW GLASS RH.		80.00	40.00
	REMOVE AND REFIX SLIDING DOOR INNER TRIM PLATE.		80.00	40.00
	TRANSFER SLIDING DOOR WINDOW PANEL.	NOT NECESSARY	100.00	-
	REMOVE & REINSTALL SLIDING DOOR GLASS RH.	NOT NECESSARY	80.00	-
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			5,120.00	1,050.00
GRAND TOTAL			14,726.18	4,990.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CS/AGI20006090/Atf3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 4400X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 4400X

RE-INSPECTION

