Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20006092/R1TF3E2

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 27/11/2020

REFERENCE

Insured/Claimant: SEE CHYE KIM Policy No: 1800111779

Date of Loss: 09/05/2020 Nature of Claim: OD Claim No: 7371053462SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME1081D

Make & Model: AUDI A4, 2.0 (A) Engine No: CVK065298

Reg. Date: 18/09/2018 (Man. Year: 2018) Chassis No: WAUZZZF40JA202860

Colour: Brown Odometer: 26572 km

Engine Capacity: 1984 cc Market Value/New Car Price: \$\$116,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,142.00	2,474.80	17,667.20	87.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,242.00	520.00	7,722.00	93.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,384.00	2,994.80	25,389.20	89.45
- Excess (S\$)	1,800.00	1,800.00	0.00	0.00
(S\$)	26,584.00	1,194.80	25,389.20	95.51
+ GST 7.00/7.00% (S\$)	1,860.88	83.64	1,777.24	95.51
Nett Amount (S\$)	28,444.88	1,278.44	27,166.44	95.51

INSPECTION

Date of Assignment: 02/06/2020

Date Inspected: 02/06/2020 Inspected At: 281 ALEXANDRA ROAD

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,068.00 FS *	1,736.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	269.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	34.00 FS	*-FS
4	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	59.00 FS	*-FS
5	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	36.00 FS	*-FS
6	1		*FRONT FENDER - RH	Not Necessary	722.00 FS	*-FS
7	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	190.00 FS	*-FS
8	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	47.00 FS	*-FS
9	1		*FRONT FENDER BRACKET - RH	Not Necessary	33.00 FS	*-FS
10	1		*FRONT FENDER DEFORMATION ELEMENT - RH	Not Necessary	46.00 FS	*-FS
11	1		*FRONT FENDER BRACE - RH	Not Necessary	112.00 FS	*-FS
12	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	228.00 FS	*190.80 FS
13	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PART - RH	Not Necessary	86.00 FS	*-FS
14	1		*FRONT WHEEL SPOILER	Not Necessary	69.00 FS	*-FS
15	1		*FRONT SPOILER - RH	Not Necessary	34.00 FS	*- FS
16	1		*FRONT STONE CHIP GUARD - RH	Not Necessary	48.00 FS	*-FS
17	1		*FRONT STONE CHIP GUARD COVER - RH	Not Necessary	29.00 FS	*-FS
18	1		*FRONT FENDER LEDGE TOP COVER - RH	Not Necessary	21.00 FS	*-FS
19	1		*LED HEADLIGHT - RH	Not Necessary	7,321.00 FS	*-FS
20	1		*FRONT ALUMINIUM RIM - RH	Scratched	652.00 FS	*547.20 FS
21	1		*FRONT WISHBONE LINK - RH	Not Necessary	507.00 FS	*-FS
22	1		*FRONT SUSPENSION GUIDE - RH	Not Necessary	887.00 FS	*-FS
23	1		*FRONT UPPER CONTROL ARM - RH	Not Necessary	480.00 FS	*-FS
24	1		*FRONT UPPER CONTROL ARM - RH REAR	Not Necessary	480.00 FS	*-FS
25	1		*FRONT WHEEL HOUSING BEARING - RH	Not Necessary	912.00 FS	*-FS
26	1		*FRONT SWIVEL JOINT - RH	Not Necessary	192.00 FS	*-FS
27	1		*FRONT WHEEL HUB - RH	Not Necessary	460.00 FS	*-FS
			Report was unsubmitted during this print-	out.		

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT WHEEL BEARING KIT	Not Necessary	237.00 FS	*- FS
29	1		*FRONT SUSPENSION FORK - RH	Not Necessary	249.00 FS	*-FS
30	1		*FRONT COUPLING ROD	Not Necessary	125.00 FS	*-FS
31	1		*FRONT DRIVE SHAFT	Not Necessary	2,498.00 FS	*-FS
32	1		*FRONT GAS SHOCK ABSORBER - RH	Not Necessary	284.00 FS	*-FS
33	1		*FRONT TRACK ROD	Not Necessary	93.00 FS	*-FS
34	1		*FRONT TRACK ROD CLAMP	Not Necessary	6.00 FS	*-FS
35	1		*FRONT TRACK ROD SPRING BAND CLAMP	Not Necessary	42.00 FS	*-FS
36	1		*FRONT TIE ROD END	Not Necessary	186.00 FS	*-FS
37	1		*SUNDRIES	Not Necessary	400.00 FS	*-FS
F=Fra	anchise	part. S=S	SpcNett.	Total Parts (S\$)	20,142.00	2,474.80

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY	New	1,800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	0.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET	New	2,800.00	0.00
5	TO CARRY OUT PRE-WHEEL ALIGNMENT AND POST-WHEEL ALIGNMENT. TO RENEW RHS FRONT RIM	New	520.00	520.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	0.00
	Gross Labou	r Cost (S\$)	8,242.00	520.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >