

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20006094/KTF3E2

Date: 16/07/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29087909MKC

Claimant Vehicle No : SLL4510M

Insured Vehicle No : YN9850J

Date of Loss: 30/05/2020

Nature of Claim: TP

Claim No: 624460

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL4510M**

Make & Model: MERCEDES-BENZ C200 KOMPRESSION, 1.8 (A)

Engine No: 27195030918810

Reg. Date: 28/08/2007 (Man. Year: 2007)

Chassis No: WDD2040412A023485

Colour: Metallic Pearl Blue

Odometer: 143485 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Michelin 7 mm

Rear Left Side:

Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side:

Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,452.30	4,719.30	2,733.00	36.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	880.00	250.00	22.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,582.30	5,599.30	2,983.00	34.76
Approved Total (Overridden) (S\$)		4,450.00		
(S\$)	8,582.30	4,450.00	4,132.30	48.15
+ GST 7.00/7.00% (S\$)	600.76	311.50	289.26	48.15
Nett Amount (S\$)	9,183.06	4,761.50	4,421.56	48.15

INSPECTION

Date of Assignment: 02/06/2020

Date Inspected: 10/06/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (AMK)

10 ANG MO KIO IND PARK 2A, #01-04

ANG MO KIO AUTOPOINT

Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2020)
Parts:	143	MERCEDES-BENZ C200 KOMPRESSOR 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL4510M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	1,624.00 FN	*1,624.00 FN
2	1		*FRONT BUMPER SPONGE	Serviceable	190.00 FN	*- FN
3	1		*FRONT GRILLE	Cracked	780.00 FN	*780.00 FN
4	1		*FRONT GRILLE BRACKET	Distorted	28.00 FN	*28.00 FN
5	1		*BONNET	Bent	1,850.00 FN	*1,850.00 FN
6	1		*BONNET LOGO	Necessary	84.00 FN	*84.00 FN
7	1		*BONNET INNER TOP RUBBER	Distorted	33.00 FN	*33.00 FN
8	2		*BONNET STOPPER	Necessary	48.00 FN	*48.00 FN
9	1		*FRONT PANEL INNER TOP GARNISH	Buckled / Distorted	130.00 FN	*130.00 FN
10	2		*HEADLAMP	Serviceable	2,180.00 FN	*- FN
11	1		*BODY WRAPPING STICKER	Necessary	1,200.00 FS	*600.00 FS
					Sub Total (S\$)	8,147.00
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	694.70
					Total Parts (S\$)	7,452.30
						4,719.30

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT BUMPER & ATTACHMENTS, GRILLE, HEADLAMPS, BONNET & ATTACHMENTS & REALIGN PANEL THE SAME	New	500.00	400.00
2	PUTTY & RESPRAY FRT BUMPER & PARKING SENSORS, BONNET & ALL AFFECTED AREAS	New	600.00	480.00
3	RUSTPROOFING	New	30.00	0.00
Gross Labour Cost (S\$)			1,130.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >