

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20006101/ESF3E2

**Date:** 16/06/2020

#### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN30577919000

**Claimant Vehicle No :** SLJ1375S

**Insured Vehicle No :** SLV9169E

Date of Loss: 26/05/2020

Nature of Claim: TP

Claim No: SNM20D202025C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ1375S**

Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)

Engine No: HRA2307856A

Reg. Date: 29/11/2016 (Man. Year: 2016)

Chassis No: SJNFEAJ11U1719247

Colour: Silver

Odometer: 58409 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Goodyear 4 mm

Rear Left Side: Goodyear 4 mm

Front Right Side: Goodyear 4 mm

Rear Right Side: Goodyear 4 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,410.68	4,777.78	10,632.90	69.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,700.00	1,900.00	52.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,010.68</b>	<b>6,477.78</b>	<b>12,532.90</b>	<b>65.93</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>19,010.68</b>	<b>5,200.00</b>	<b>13,810.68</b>	<b>72.65</b>

#### INSPECTION

Date of Assignment: 02/06/2020

Date Inspected: 03/06/2020 Inspected At:

My Car Consultant Pte Ltd (Ubi)  
53 Ubi Ave 1, #01-33, Paya Ubi Industrial  
Park  
Singapore 408934

Estimated Period of Repair: 5.0 days

---

**Adjuster:** CHEN TSUE YEE

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 Jun 2020)
<b>Parts:</b> M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLJ1375S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	961.40 FL	*- FL
2	1		*FRONT BUMPER	Deformed	1,855.00 FL	*689.00 FL
3	1		*FRONT BUMPER SPONGE	Not Necessary	195.70 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	665.40 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Broken	35.20 FL	*35.20 FL
6	1		*FRONT BUMPER FOG LAMP OUTER CHROME RH	Cut	130.20 FL	*130.20 FL
7	1		*FRONT HEADLAMP RH	Cut	559.00 FL	*559.00 FL
8	1		*FRONT HEADLAMP LOWER BRACKET RH	Crushed	38.10 FL	*38.10 FL
9	1		*FRONT HEADLAMP CLIPS RH	Not Necessary	28.10 FL	*- FL
10	1		*FRONT GRILLE	Broken	498.30 FL	*498.30 FL
11	1		*FRONT BUMPER FOG LAMP RH	Broken	323.70 FL	*323.70 FL
12	1		*FRONT FENDER RH	Dented	685.00 FL	*685.00 FL
13	1		*FRONT FENDER INNER COWLING RH	Torn	121.30 FL	*121.30 FL
14	1		*FRONT SUPPORT PANEL	Not Necessary	617.50 FL	*- FL
15	1		*WIPER WASHER TANK	Crushed	162.50 FL	*162.50 FL
16	1		*WIPER WASHES TANK MOTOR	Not Necessary	95.60 FL	*- FL
17	1		*RH FRONT DOOR	Repair	1,104.80 FL	*- FL
18	1		*RH FRONT DOOR HING TOP	Not Necessary	87.90 FL	*- FL
19	1		*RH FRONT DOOR HING BOTTOM	Not Necessary	87.90 FL	*- FL
20	1		*RH FRONT DOOR CHECKER	Not Necessary	45.10 FL	*- FL
21	1		*RH FRONT DOOR WEATHER STRIPE	Not Necessary	132.20 FL	*- FL
22	1		*RH FRONT DOOR OUTER CHROME MOULDING	Not Necessary	188.90 FL	*- FL
23	1		*RH FRONT FENDER OUTER GARNISH	Not Necessary	654.00 FL	*- FL
24	1		*RH FRONT SHOCK ABSORBER	Not Necessary	547.60 FL	*- FL
25	1		*RH FRONT KNUCKLER ARM	Bent	534.40 FL	*534.40 FL
26	1		*RH FRONT TIE ROD	Not Necessary	134.50 FL	*- FL
27	1		*RH FRONT TIE ROD END	Not Necessary	121.00 FL	*- FL
28	1		*RH FRONT STABILISED BAR	Not Necessary	353.60 FL	*- FL
29	1		*RH FRONT STABILISED BAR LINK	Not Necessary	39.10 FL	*- FL
30	1		*RH FRONT LOWER ARM	Bent	1,630.80 FL	*240.50 FL
31	1		*RH FRONT SHOCK ABSORBER TOP MOUNTING	Not Necessary	99.10 FL	*- FL
32	1		*RH FRONT DOOR PILLAR	Repair	1,530.30 FL	*- FL
33	1		*RH FRONT TYRE	Not Necessary	280.00 FS	*- FS
34	1		*RH FRONT RIM	Cut	1,681.50 FS	*800.00 FS
35	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
36	1		*RH FRONT KNUCKLER ARM BEARING	Necessary	332.30 FS	*332.30 FS
37	1		*MISCELLANEOUS	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 16,837.00 5,179.50**

**- List Item Discount on L Items 10.00/10.00% (\$\$) 1,426.32 401.72**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Total Parts (S\$)</b>	<b>15,410.68</b>	<b>4,777.78</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
2	REMOVE AND RENEW RH FRONT UNDERCARRIAGE	New	300.00	200.00
3	TOWING FEE	New	120.00	80.00
4	REPAIR AND STRAIGHTEN CHASSIS FRAME	New	250.00	0.00
5	REMOVE AND TRANSFER RH FRONT DOOR FITTING	New	150.00	0.00
6	CHECK AND RESET FAULT CODE LIGHT ON	New	200.00	0.00
7	CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
8	TO RESPRAY UNDERCOATING	New	150.00	0.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	30.00
10	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	800.00
11	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	500.00
			<b>Gross Labour Cost (S\$)</b>	<b>1,700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >