



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDW 6990J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (CONSISTENT)	CRUSHED	1,530.00	1,530.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	850.00	-
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	BROKEN	220.00	220.00
1	REAR BUMPER CENTER PAD (CONSISTENT)	CUT	160.00	160.00
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	CUT	85.00	85.00
1	LH REAR TAILLAMP (CONSISTENT)	BROKEN	460.00	460.00
1	LH REAR TAILLAMP LOWER BRACKET (CONSISTENT)	BROKEN	112.00	112.00
1	REAR TAILGATE (CONSISTENT)	NOT NECESSARY	1,860.00	-
1	LH REAR TAILGATE LAMP (CONSISTENT)	CUT	350.00	350.00
1	LH REAR FENDER (CONSISTENT)	NOT NECESSARY	2,150.00	-
1	REAR END PANEL (CONSISTENT)	NOT NECESSARY	750.00	-
1	LH REAR TAILLAMP SIDE GARNISH (CONSISTENT)	NOT NECESSARY	95.00	-
1	REAR TAILGATE LOCK SENSOR (CONSISTENT)	NOT NECESSARY	125.00	-
	LESS 5% DISCOUNT		-437.35	-
	LESS 10% DISCOUNT		-	-291.70
			8,309.65	2,625.30
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SEALANT (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	80.00	30.00
1	MISCELLANEOUS (SN) (CONSISTENT)	NOT NECESSARY	200.00	-
			340.00	30.00
<b><u>LABOUR</u></b>				
	TO CHECK ELECTRICAL WIRING .		80.00	30.00
	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING.	NOT NECESSARY	200.00	-
	REMOVE AND REFIX REAR WINDSCREEN GLASS .	NOT NECESSARY	150.00	-
	CHECK AND RESET FAULT CODE LIGHT ON.	NOT NECESSARY	150.00	-
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	150.00	-
	APPLY ANTI RUST ON AFFECTED AREAS.		200.00	30.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,000.00	250.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ON AFFECTED AREAS.		800.00	300.00
			2,730.00	610.00
GRAND TOTAL			11,379.65	3,265.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CC4/ASM20006102/Eps3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.