Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC4/III20006112/EPS3Q2 Our File No:

Date: 27/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SMN7636S Insured Vehicle No: SHA7114J

Vehicle No:

Date of Loss: 29/05/2020 Nature of Claim: TP Claim No: MCT20050196

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMN7636S Reg No:

Make & Model: TOYOTA PRIUS PLUS, 1.8 (A) Engine No: 2ZR0E41797

Chassis No: Reg. Date: 27/08/2019 (Man. Year: 2019) JTDZS3EU70J046224

Colour: Odometer: 54962 km Grey

Engine Capacity: 1798 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,773.85	1,332.20	2,441.65	64.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	790.00	860.00	52.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,423.85	2,122.20	3,301.65	60.87
Approved Total (Overridden) (S\$)		1,700.00		
Nett Amount (S\$)	5,423.85	1,700.00	3,723.85	68.66
+ Loss of Use (3.0 x S\$8	30.00/day) (S\$)	240.00		
+ Doc/S	earch Fee (S\$)	7.45		
Net	tt Liability (S\$)	1,947.45		
Global Sum S	Settlement (S\$)	1,940.00		

INSPECTION

Date of Assignment: 03/06/2020

Date Inspected: 03/06/2020 Inspected At: My Car Consultant Pte Ltd (HQ)

25 KAKIT BUKIT RD 4, #03-67/68,

SYNERGY @ KB Singapore 417800

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: CHEN TSUE YEE Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jul 2020)

Parts: M1-MPV TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMN7636S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	610.40 FL	*523.90 FL	
2	1		*REAR BUMPER SIDE RETAINER LH	Broken	113.60 FL	*113.60 FL	
3	1		*REAR BUMPER SIDE RETAINER RH	Broken	113.60 FL	*113.60 FL	
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	310.50 FL	*- FL	
5	1		*REAR BUMPER BRACKET LH	Not Necessary	115.30 FL	*- FL	
6	1		*REAR BUMPER BRACKET RH	Not Necessary	115.30 FL	*- FL	
7	1		*REAR BUMPER LIP	Cut	718.50 FL	*718.50 FL	
8	1		*REAR BUMPER REFLECTOR LH	Not Necessary	80.60 FL	*- FL	
9	1		*REAR BUMPER REFLECTOR RH	Not Necessary	80.60 FL	*- FL	
10	1		*REAR END PANEL	Repair	660.20 FL	*- FL	
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	225.10 FL	*- FL	
12	1		*REAR KEYLESS SENSOR	Not Necessary	169.50 FL	*- FL	
13	1		*REAR KEYLESS SENSOR WIRE HARNESS	Not Necessary	438.60 FL	*- FL	
14	1		*SET REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS	
15	1		*SET REAR REVERSE CAMERA	Not Necessary	300.00 FS	*- FS	
16	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS	
17	1		*SET REAR END PANEL GARNISH CLIP	Not Necessary	30.00 FS	*- FS	
18	1		*FLOOR PANEL SEALANT	Not Necessary	50.00 FS	*- FS	
19	1		*END PANEL SEALANT	Not Necessary	50.00 FS	*- FS	
20	1		*MISCELLANEOUS	Not Necessary	200.00 FS	*- FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
				Sub Total (S\$)	4,711.80	1,699.60	
- List Item Discount on L Items 25.00/25.00% (S\$)					937.95	367.40	

Total Parts (S\$) 3,773.85 1,332.20

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	30.00
3	TO RESPRAY UNDERCOATING	New	100.00	0.00
4	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	30.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	400.00
6	PANEL BEATING ON AFFECTED AREAS	New	600.00	300.00
		Gross Labour Cost (S\$)	1,650.00	790.00
	Report was uns	submitted during this print-out.		

< END OF ESTIMATES >