

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20006121/KPS3Q2

Date: 07/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLT3476T	Insured Vehicle No :	SH9462Z
Date of Loss: 02/06/2020	Nature of Claim: TP	Claim No: MCT20060017

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3476T	
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No: 2ZRS106527
Reg. Date:	26/10/2017 (Man. Year: 2017)	Chassis No: JTDKB3FU103574801
Colour:	Metallic Silver	Odometer: 226356 km
Engine Capacity:	1798 cc	
Market Value/New Car Price:	N/A	
Sum Insured (\$\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,005.90	1,898.89	1,107.01	36.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,550.00	550.00	26.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,105.90	3,448.89	1,657.01	32.45
+ GST 7.00/7.00% (\$\$)	357.41	241.42	115.99	32.45
Nett Amount (\$\$)	5,463.31	3,690.31	1,773.00	32.45
+ Car Rental (5.0 x S\$71.95/day) (\$\$)		359.75		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		4,057.51		
Global Sum Settlement (\$\$)		4,050.00		

INSPECTION

Date of Assignment:	03/06/2020	
Date Inspected:	25/06/2020 Inspected At:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259 Singapore 569536
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2020)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT3476T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT DOOR	Bent	1,121.75 FL	*1,121.75 FL
2	1		*LH FRONT DOOR HINGE TOP	Repair	78.30 FL	*- FL
3	1		*LH FRONT DOOR HINGE BOTTOM	Repair	78.30 FL	*- FL
4	1		*LH FRONT DOOR WEATHERSTRIP	Serviceable	211.69 FL	*- FL
5	1		*LHF DOOR GLASS OUTER MOULDING	Serviceable	121.75 FL	*- FL
6	1		*LH REAR DOOR	Bent	1,211.40 FL	*1,211.40 FL
7	1		*LH REAR DOOR HINGE TOP	Repair	78.34 FL	*- FL
8	1		*LH REAR DOOR HINGE BOTTOM	Repair	78.34 FL	*- FL
9	1		*LH REAR DOOR WEATHERSTRIP	Torn	198.70 FL	*198.70 FL
10	1		*LHR DOOR GLASS OUTER MOULDING	Serviceable	107.80 FL	*- FL
11	1		*LH SIDE SKIRT	Repair	721.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,007.87	2,531.85
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,001.97	632.96
Total Parts (\$\$)	3,005.90	1,898.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (LHF DOOR ,LHR DOOR ,LH SIDE SKIRT ,LHR FENDER)	New	800.00	550.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (LHR DOOR ,LHR DOOR ,LH SIDE SKIRT)	New	800.00	800.00
3	TO TUFF COAT	New	150.00	60.00
4	TO REMOVE & REFIT DOOR TRIM ,DOOR GLASS ,WINDOW REGULATOR,DOOR LOCK TO ASSIST WORK LOAD	New	300.00	120.00
5	TO CHECK WIRING	New	50.00	20.00
Gross Labour Cost (\$\$)			2,100.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >