

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: **SBZ 9382 T**

Model: **TOYOTA AXIO**

Chassis No: **NZE1416052522**

Year of manufacturing: **2007**

90110243
Mei 1/04

S/No	Qty	Items	Unit Price	Amount
1	1	LHS Front Door X <i>negot.</i>	\$ 1,120.30	\$ 1,120.30
2	2	LHS Front Door Hinge X <i>NN</i>	\$ 95.00	\$ 190.00
3	1	LHS Front Door Tape X <i>NN</i>	\$ 68.90	\$ 68.90
4	1	LHS Front Door Inner Trim Board X <i>NN</i>	\$ 985.60	\$ 985.60
5	1	LHS Front Door Power Window Regulator X <i>NN</i>	\$ 287.40	\$ 287.40
6	1	LHS Front Door Outer Moulding X <i>NN</i>	\$ 101.30	\$ 101.30
7	1	LHS Front Door Weatherstrip X <i>NN</i>	\$ 194.60	\$ 194.60
8	1	LHS Front Window Glass X <i>NN</i>	\$ 497.70	\$ 497.70
9	1	LHS Front Fender <i>Buc</i>	\$ 778.20	\$ 778.20 606.1
10	1	LHS Front Fender Shield <i>de</i>	\$ 210.60	\$ 210.60 124.1
11	1	LHS Front Fender Signal <i>CHP</i>	\$ 97.20	\$ 97.20 35
12	1	LHS Front Door Rain Guard with Chrome <i>CHP</i>	\$ 189.60	\$ 189.60 80 (SN)
13	1	Front Bumper <i>CHP</i>	\$ 520.60	\$ 520.60 478.4
14	1	Front Bumper Retainer <i>de</i>	\$ 75.30	\$ 75.30 53.5
15	1	Front Bumper Grille X <i>NN</i>	\$ 400.50	\$ 400.50
16	1	LHS Front Bumper Fog Light Cover X <i>NN</i>	\$ 58.60	\$ 58.60
17	1	LHS Headlamp <i>CHP</i>	\$ 730.40	\$ 730.40 347.8
18	1	LHS Headlamp Panel X <i>NN</i>	\$ 184.50	\$ 184.50
19	1	LHS Side Mirror Assy <i>BR</i>	\$ 1,114.50	\$ 1,114.50 972
20	1	LHS Front Pillar Upper Outer X	\$ 394.70	\$ 394.70
21	1	Steering Rack X <i>NN</i>	\$ 852.30	\$ 852.30
22	1	LHS Front Absorber X	\$ 569.50	\$ 569.50
23	1	LHS Front Lower Arm X	\$ 365.20	\$ 365.20
24	1	LHS Front Knuckle X	\$ 378.40	\$ 378.40
25	1	LHS Front Wheel Bearing <i>Im</i>	\$ 367.80	\$ 367.80 171.55

\$ 2788.45 **10,733.70**

-25% \$ **2,683.43**

Total for spare parts \$ **8,050.28**

2091.34

Special Nett

1	10	Front Bumper Clip <i>GAC</i>	\$		
2	10	LHS Front Fender Shield Clip <i>GAC</i>	\$ 5.00	\$	50.00 30
3	1	LHS Front Tyre X <i>NN</i>	\$ 5.00	\$	50.00 20
4	1	LHS Front Rim <i>Cut</i>	\$ 400.00	\$	400.00
			\$ 600.00	\$	600.00 300

Total for SP \$ **1,100.00**

Sub-Total for Parts : \$ **9,150.28**

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-	\$ 650	900.00 600
2		To putty and spray paint on all accident damage parts and other accident	\$ 800	1,000.00
3		To check wiring system to facilitate repair and refit the same	\$ 30	150.00
4		Apply rust proofing on the adjacent panels	\$ 40	60.00
5		Reset engine management system with diagnostic fault	\$ NN X	80.00
6		To supply under coating / putty on parts replaced	\$ NN X	80.00
7		To conduct wheel alignment	\$ 60	150.00
8		To perform water seepage test after repair	\$ NN X	150.00
9		Dismantle and transfer door fitting and mechanism to new door/facilitate repair	\$ 50	150.00
10		To remove and refit under carriage	\$ 50	150.00
11		To conduct headlamp focus	X NN \$ 20	100.00
				1650
TOTAL AMOUNT :			\$	2,970.00
OVERALL COST:			\$	12,120.28

Gua Qiang - 8288 0282 .

4151.34

-20%: 3300

Unpaid repair .

5 Days .

After repair photos.

Gua Qiang @ lkkauto. com

04/6/2020 .

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--