

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006124/QGA3Q2
Date: 30/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900015081
Claimant Vehicle No : SLF3279U **Insured Vehicle No :** SJP5820P
 Date of Loss: 21/12/2019 Nature of Claim: TP Claim No: 2299705911SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF3279U**
 Make & Model: KIA FORTE K3, 1.6 (A) Engine No: G4FGGH649217
 Reg. Date: 23/08/2016 (Man. Year: 2016) Chassis No: KNAFX411MH5656123
 Colour: Blue Odometer: 228746 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm
 Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	700.00	1,100.00	61.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,800.00	700.00	1,100.00	61.11
+ GST 7.00/7.00% (\$\$)	126.00	49.00	77.00	61.11
Nett Amount (\$\$)	1,926.00	749.00	1,177.00	61.11
+ Loss of Use (4.0 x S\$50.00/day) (\$\$)		200.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		951.00		

INSPECTION

Date of Assignment: 03/06/2020
 Date Inspected: 04/06/2020 Inspected At: Lion City Rentals Pte Ltd (HQ)
 60 Jalan Lam Huat, #04-35/36 Carros Centre
 Singapore 737569
 Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR STRAIGHTENING R/R FENDER AND R/R DOOR	New	900.00	250.00
2	TO RESPRAY R/R FENDER ,REAR BUMPER AND R/R DOOR ,WHEEL CAP	New	900.00	450.00
Gross Labour Cost (S\$)			1,800.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >