



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address

CYCLE & CARRIAGE LEASING PTE LTD

239 ALEXANDRA ROAD

SINGAPORE 159930

Contact No Mobile: 85188668

Owner Name & Vehicle Info

Reg No/Reg Date SKX5979L / 18/12/2015

Date In/Mileage / 0

Chassis No RU11104694

Engine No

Make/Model Veze1

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00061	Cash	03/06/2020/ 17:20	TLC	442 / CocoLu	23920			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E	PNT88000							800.00
	RENEW REAR BUMPER, TAILGATE, REAR BUMPER TOP LEFT COVER							
	REPAIR REAR END PANEL							
E	PNT98000							1000.00
	SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, TAILGATE							
	REAR BUMPER TOP LEFT COVER							
E	PNT88000							160.00
	REMOVE & INSTALL TAILGATE GLASS							
M	SUNDRY							60.00
	APPLY SEALANT FOR TAILGATE GLASS							
M	SUNDRY							220.00
	SUPPLY REVERSE SENSOR							
M	SUNDRY							40.00
	APPLY SEALANT FOR ACCIDENT PORTION							
E	PNT88000							40.00
	REMOVE & INSTALL PARKING SENSOR							
A	54900099							20.00
	CHECK WRIRING & ELECTRICAL SYSTEM							
A	10028901							120.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
	USING HI-SCAN PRO TEST							
M	SUNDRY							20.00
	Sundry							
M	SUNDRY							563.00
	REAR BUMPER							
M	SUNDRY							1070.00
	TAILGATE							
M	SUNDRY							168.00
	REAR TOP BUMPER COVER LH							
M	SUNDRY							36.00
	TAILGATE GLASS MOULDING X 2							
M	SUNDRY							58.00
	EMBLEM VEZAL							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address

CYCLE & CARRIAGE LEASING PTE LTD
239 ALEXANDRA ROAD
SINGAPORE 159930
Contact No Mobile: 85188668

Owner Name & Vehicle Info

Reg No/Reg Date SKX5979L / 18/12/2015
Date In/Mileage / 0
Chassis No RU11104694
Engine No
Make/Model Veze1

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00061	Cash	03/06/2020/ 17:20	TLC	442 / CocoLu	23920

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY REAR BUMPER SIDE RETAINER LH				22.00
M SUNDRY REAR BUMPER CLIPS				55.00
M SUNDRY REAR BUMPER REFLECTOR LH				175.00

Estimate

Confirm & accepted by

7% GST on **Nett** **4,627.00**
4627.00 323.89

Authorized signatory and company stamp

Total Payable **4,950.89**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.