

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2100342

3 ANSON ROAD #16-00 INV Date 15/01/2021 SPRINGLEAF TOWER Reference CC6/CT120

SPRINGLEAF TOWER

SINGAPORE 079909

Reference CC6/CTI20006143/Kea3q2

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKE 1722L

Insured Veh. SJL 6167G

Claim No. SNM20D202038

Policy No. DMPCSN1838231903

Accident Date 01/06/2020

Inspection Date 04/06/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En Autom	obile
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	Ref:	CC6/CTI20006143/Kea3q2
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	Date:	15/01/2021
			Code:	CTI
1.		Policy Particulars	:- THIRD PARTY CLAI	М
	Insured Veh.	SJL 6167G	Veh. Inspected	SKE 1722L
	Policy No.	DMPCSN1838231903	Coverage (\$)	0.00
	Claim No.	SNM20D202038	Excess (\$)	0.00
	Assign From		Assign Date	04/06/2020
2.		Vehicle Partic	culars & Condition	
	Make & Model	TOYOTA PRIUS (A)	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	JTDKD3B3201500791	Colour	METALLIC PEARL WHITE
	Odometer	194171 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Condition	ons of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195/50 R16	DUNLOP	3 mm
	L/H Front Tyre	195/50 R16	DUNLOP	3 mm
	R/H Rear Tyre	195/50 R16	DUNLOP	3 mm
	L/H Rear Tyre	195/50 R16	DUNLOP	3 mm
4.		Description	on of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR PORTION.	
	DAMAGES SEE DETAILS.			
5.		General	Information	
	Accident Date	01/06/2020	Inspection Date	04/06/2020
	Survey held at	ALAN'S UNITED AUTO PTE LTE)	
		BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
5a.		Re	emarks	
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W		
5b.		Estimate	Days of Repair	
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	4 Wor	king Days
	•			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 1722L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER FASCIA	CRACKED	503.10	503.10
1	REAR BUMPER REINFORCEMENT	BENT	648.90	648.90
2	REAR BUMPER BRACKET @\$139.70	BENT / DISTORTED	279.40	279.40
2	REAR BUMPER SIDE SEAL @\$97.60	SERVICEABLE	195.20	-
2	REAR BUMPER SIDE RETAINER @\$81.70	O/S DISTORTED	163.40	81.70
1	TAIL GATE	BENT	1,076.10	1,076.10
1	TAIL GATE 'PRIUS C' EMBLEM	NECESSARY	59.40	59.40
1	TAIL GATE 'TOYOTA' EMBLEM	NECESSARY	51.30	51.30
1	TAIL GATE LOGO	NECESSARY	54.80	54.80
1	TAIL GATE 'HYBRID' PLATE	NECESSARY	77.40	77.40
1	REAR END PANEL	TO REPAIR SEE LABOUR	595.80	-
1	END PANEL TOP GARNISH	SERVICEABLE	208.50	-
2	TAILLAMP LOWER BRACKET @\$53.80	SERVICEABLE	107.60	-
	LESS 25% DISCOUNT		-1,005.23	-708.03
			3,015.67	2,124.07
	SPECIAL NETT ITEMS			
1	REAR BUMPER LOWER SPOILER (SN)	DENTED/ DISTORTED	450.00	450.00
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	CRACKED	300.00	200.00
			810.00	690.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEKA TEST.		150.00	120.00
	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET.		120.00	50.00
	TO APPLY UNDERSEALING.		80.00	30.00
	TO PUTTY AND SPRAY REPLACED PARTS.		900.00	720.00

Report Ref No. CC6/CTI20006143/Kea3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE,CUT -OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		800.00	500.00
			2,050.00	1,420.00
	GRAND TOTAL		5,875.67	4,234.07

RECOMMENDED COST OF LUMP SUM REPAIRS	3,350.0	0
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/CTI20006143/Kea3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKE 1722L

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKE 1722L

RE-INSPECTION













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKE 1722L

RE-INSPECTION





