LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way, #09-16

Our File No:

CC3/AIG20006144/ATF3E2

Singapore 079120

Date:

02/02/2021

REFERENCE

Insured/Claimant: Date of Loss:

NG SEOK LAY

19/05/2020

Policy No: Nature of Claim: 2070008660

OD

Claim No:

3879239230SG

WAUZZZF34L1024994

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SDF710E

Make & Model:

AUDI Q3, 1.4 TFSI (A) 21/01/2020 (Man. Year: 2019) Engine No: Chassis No: Odometer:

CZD887077

5054 km

Reg. Date: Colour:

Blue

Engine Capacity: Market Value/New Car Price: 1395 cc

S\$134,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

Front Right Side:

215/65 R17 Pirelli 6 mm Rear Tyre Size: Rear Left Side:

215/65 R17 Pirelli 6 mm

Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,890.00	1,868.80	1,021.20	35.34
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,752.00	1,602.00	1,150.00	41.79
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,642.00	3,470.80	2,171.20	38.48
	- Excess (S\$)	800.00	800.00	0.00	0.00
	(S\$)	4,842.00	2,670.80	2,171.20	44.84
	+ GST 7.00/7.00% (S\$)	338.94	186.96	151.98	44.84
	Nett Amount (S\$)	5,180.94	2,857.76	2,323.18	44.84

INSPECTION

Date of Assignment:

04/06/2020

Premium Automobiles Pte Ltd (UBI)

Date Inspected:

04/06/2020

Inspected At:

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

3.0 days

DENISE TAY KWEE CHENG

Adjuster: **ADRIAN LING** Manager:

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,397.00 FS	*1,117.60 FS
2	1		*REAR BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*-FS
3	1		*REAR BUMPER SPOILER	Deformed	433.00 FS	*346.40 FS
4	1		*TOWING EYE COVER	Not Necessary	41.00 FS	*-FS
5	1		*REAR BUMPER CROSS REINFORCEMENT - CENTRE	Not Necessary	91.00 FS	*-FS
6	5		*CLIP	Not Necessary	24.00 FS	*-FS
7	1		*REAR BUMPER BRACKET	Not Necessary	45.00 FS	*-FS
8	1		*REAR LIGHT REFLECTOR - RH	Not Necessary	39.00 FS	*-FS
9	1		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*-FS
10	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*-FS
11	2		*REAR WHEEL COVER - LH / RH	Necessary	506.00 FS	*404.80 FS
12	1		*SUNDRIES	Not Necessary	300.00 FS	*-FS
F=Fra	nchise	part. S=Spcl	Nett.			
				Total Parts (S\$)	2,890.00	1,868.80
			Report was unsubmitted during this p	rint-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			,
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labou	r Cost (S\$)	2,752.00	1,602.00
	Report was unsubmitted during this pr	rint-out.		

< END OF ESTIMATES >