

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20006149/ADS3Q2

Date: 30/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100303269

Claimant
Vehicle No : SLT3107J **Insured Vehicle No :** SDJ716T

Date of Loss: 21/12/2019 Nature of Claim: TP Claim No: 3038425367SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3107J	Engine No:	B14XER19NU4672
Make & Model:	OPEL ADAM, 1.4 (A)	Chassis No:	W0L0MAP08H6006456
Reg. Date:	01/08/2017 (Man. Year: 2016)	Odometer:	30429 km
Colour:	Blue		
Engine Capacity:	1398 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R16	Rear Tyre Size:	195/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,018.00	3,238.20	4,779.80	59.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,180.00	850.00	41.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,048.00	4,418.20	5,629.80	56.03
Approved Total (Overridden) (\$\$)		3,500.00		
Nett Amount (\$\$)	10,048.00	3,500.00	6,548.00	65.17
+ Loss of Use (4.0 x S\$60.00/day) (\$\$)		240.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,747.45		

INSPECTION

Date of Assignment: 04/06/2020

Date Inspected: 04/06/2020 Inspected At: ACE AUTO SOLUTION
23 KAKI BUKIT AVE 4, #04-01
(SOUTH WING)
SINGAPORE 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,538.00 FL	*1,538.00 FL
2	1		*REAR WINDSCREEN WITH MOULDING	Not Necessary	1,032.00 FL	*- FL
3	1		*REAR TAILGATE HINGE -RH	Not Necessary	70.00 FL	*- FL
4	1		*REAR TAILGATE HINGE -LH	Not Necessary	70.00 FL	*- FL
5	1		*REAR TAILGATE STRIKER	Not Necessary	25.00 FL	*- FL
6	1		*REAR TAILGATE LATCH	Not Necessary	265.00 FL	*- FL
7	1		*LHR TAILLAMP	Not Necessary	461.00 FL	*- FL
8	1		*RHR TAILLAMP	Not Necessary	461.00 FL	*- FL
9	1		*REAR BUMPER UPPER	Deformed	1,450.00 FL	*1,450.00 FL
10	1		*REAR BUMPER LOWER -EXTENSION	Repair	931.00 FL	*- FL
11	1		*REAR BUMPER NUMBER PLATE LAMP	Not Necessary	30.00 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT BAR	Bent	460.00 FL	*460.00 FL
13	1		*REAR END PANEL	Repair	387.00 FL	*- FL
14	1		*LHR BUMPER BRACKET -GUIDE OUTER	Not Necessary	65.00 FL	*- FL
15	1		*RHR BUMPER BRACKET -GUIDE OUTER	Not Necessary	65.00 FL	*- FL
16	1		*LHR BUMPER BRACKET -GUIDE INNER	Not Necessary	65.00 FL	*- FL
17	1		*RHR BUMPER BRACKET -GUIDE INNER	Not Necessary	65.00 FL	*- FL
18	1		*REAR BUMPER BRACKET -GUIDE CENTRE	Not Necessary	75.00 FL	*- FL
19	1		*REAR NUMBER PLATE	Deformed	45.00 FS	*45.00 FS
20	10		*REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
21	5		*REAR END PANEL TRIM CLIP	Not Necessary	32.50 FS	*- FS
22	1		*SET REVERSE SENSOR	Not Necessary	360.00 FS	*- FS
23	1		*REAR REVERSE CAMERA	Not Necessary	280.00 FS	*- FS
24	1		*REAR END PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS
25	8		*TAIL GATE INNER TRIM BOARD CLIP	Not Necessary	52.00 FS	*- FS
26	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
27	1		*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,769.50	3,583.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	751.50	344.80
Total Parts (\$\$)	8,018.00	3,238.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	800.00	400.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	800.00	500.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	30.00	30.00
4	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	80.00	50.00
5	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	80.00	80.00
6	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIR OF VEHICLE	New	40.00	0.00
7	TO APPLY DOOR SEALANT TO 5 TH REAR DOOR	New	80.00	0.00
8	TO REMOVE AND REPLACE REAR TAIL GATE WINDSCREEN	New	120.00	120.00
Gross Labour Cost (\$\$)			2,030.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >