

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006166/KRA3Q2
Date: 15/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800113640	
Claimant Vehicle No :	GBJ5511H	Insured Vehicle No :	SMM3663U	
Date of Loss:	05/06/2020	Nature of Claim:	TP	Claim No: 8767602366SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ5511H		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KD2856582
Reg. Date:	27/05/2019 (Man. Year: 2019)	Chassis No:	JTFHT02P100249192
Colour:	White	Odometer:	36492 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,160.60	3,592.60	568.00	13.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,520.00	810.00	34.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,490.60	5,112.60	1,378.00	21.23
+ GST 7.00/7.00% (S\$)	454.34	357.88	96.46	21.23

Nett Amount (S\$)	6,944.94	5,470.48	1,474.46	21.23
+ Car Rental (10.0 x S\$180.00/day + 7.00% GST) (S\$)		1,926.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,398.48		

INSPECTION

Date of Assignment: 09/06/2020

Date Inspected: 10/06/2020

Inspected At:

Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,162.00 FL	*2,162.00 FL
2	1		*TAILGATE EMBLEM	Necessary	81.00 FL	*81.00 FL
3	1		*TAILGATE STICKER TOYOTA	Necessary	49.60 FL	*49.60 FL
4	1		*TAILGATE STICKER HIACE	Necessary	49.60 FL	*49.60 FL
5	1		*TAILGATE LOCK	Dented	286.00 FL	*286.00 FL
6	15		*TAILGATE TRIM BOARD CLIPS	Necessary	109.20 FL	*109.20 FL
7	1		*TAILGATE WEATHERSTRIP	Serviceable	476.00 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP TOP PROTECTIVE PLATE	Dented	390.00 FL	*390.00 FL
9	1		*REAR BUMPER	Buckled	435.00 FL	*435.00 FL
10	1		*REAR BUMPER BRACKET	Bent	38.60 FL	*38.60 FL
11	10		*REAR BUMPER CLIPS	Necessary	57.80 FL	*57.80 FL
12	1		*END PANEL	Bent	522.00 FL	*522.00 FL
13	1		*TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
14	1		*TAILGATE GLASS SEALER	Necessary	40.00 FS	*20.00 FS
15	1		*TAILGATE GLASS FASTENER	Necessary	50.00 FS	*30.00 FS
16	1		*TAILGATE STICKER 70KM	Malfunction	18.00 FS	*12.00 FS
17	1		*TAILGATE STICKER	Necessary	50.00 FS	*50.00 FS
18	1		*TAILGATE LOWER PROTECTOR	Necessary	135.00 FS	*80.00 FS
19	1		*REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
20	1		*REAR NUMBER PLATE	Bent	45.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,324.80	4,637.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,164.20	1,045.20
Total Parts (\$\$)	4,160.60	3,592.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT ELECTRICAL CHECK ,REPLACE REVERSE SENSORS ,MODULE REWIRING ETC	New	120.00	50.00
2	TO DISMANTLE /TRANSFER TAILGATE FITTINGS /ANCILLARY ACCESSORIES	New	120.00	60.00
3	TO DISMANTLE /REFIT TAILGATE GLASS TO FACILITATE REPAIR	New	160.00	120.00
4	TO SUPPLY END PANEL BODY SEALANT	New	60.00	30.00
5	TO APPLY RUST-PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL JOINT SEALANT	New	120.00	60.00
6	LABOUR CHARGE -PANEL BEATING ,REPAIRING OF REAR FLOOR PLATE ,END INNER PANEL ,CNT WELD END PANEL AND PARTS REPLACEMENT	New	950.00	600.00
7	TO RESPRAY AFFECTED AREAS	New	800.00	600.00
Gross Labour Cost (\$\$)			2,330.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >