

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20006172/UKA3Q2

**Date:** 30/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070028707

**Claimant**  
**Vehicle No :** SMC5579U **Insured Vehicle No :** SMS6241C

Date of Loss: 05/06/2020 Nature of Claim: TP Claim No: 3414248039SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMC5579U</b>		
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Engine No:	D4FDJH553039
Reg. Date:	10/07/2018 (Man. Year: 2018)	Chassis No:	KNAHU815VJ7208356
Colour:	Grey/Silver	Odometer:	157363 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,822.20	2,669.80	7,152.40	72.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,840.00	1,560.00	1,280.00	45.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,662.20</b>	<b>4,229.80</b>	<b>8,432.40</b>	<b>66.60</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,350.00</b>		
<b>(S\$)</b>	12,662.20	3,350.00	9,312.20	73.54
<b>+ GST 7.00/7.00% (S\$)</b>	886.35	234.50	651.85	73.54
<b>Nett Amount (S\$)</b>	<b>13,548.55</b>	<b>3,584.50</b>	<b>9,964.05</b>	<b>73.54</b>
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,586.50</b>		

### INSPECTION

Date of Assignment: 09/06/2020

Date Inspected: 09/06/2020 Inspected At: Tan Lim Motor Pte Ltd (Defu)  
1 Defu Lane 6  
Singapore 539365

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	549.00 FL	*549.00 FL
2	8		*REAR BUMPER CLIP	Necessary	28.00 FL	*28.00 FL
3	2		*REAR BUMPER SIDE RETAINER	Not Necessary	56.00 FL	*- FL
4	2		*REAR BUMPER SPLASH GUIDE	Not Necessary	1,360.00 FL	*- FL
5	1		*REAR BUMPER CENTRAL PAD	Grazed	189.00 FL	*189.00 FL
6	1		*REAR BUMPER LOWER DIFFUSION	Repair	285.00 FL	*- FL
7	1		*REAR BUMPER TOW COVER	Not Necessary	48.00 FL	*- FL
8	2		*REAR BUMPER REFLECTOR	Not Necessary	232.00 FL	*- FL
9	2		*REAR BUMPER REVERSE SENSOR	Shorted	324.00 FL	*324.00 FL
10	2		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	10.00 FL	*10.00 FL
11	1		*REAR BUMPER BEAM	Cracked	367.00 FL	*367.00 FL
12	2		*REAR BUMPER BEAM BRACKET	Not Necessary	112.00 FL	*- FL
13	2		*REAR LAMP	Not Necessary	1,540.00 FL	*- FL
14	6		*REAR LAMP CLIP	Not Necessary	36.00 FL	*- FL
15	1		*TAILGATE LID	Badly Dented	1,088.00 FL	*1,088.00 FL
16	1		*TAILGATE LID INNER TRIMBOARD	Not Necessary	203.00 FL	*- FL
17	6		*TAILGATE LID INNER TRIMBOARD-TOP	Not Necessary	1,218.00 FL	*- FL
18	1		*TAILGATE LID TOP GARNISH	Not Necessary	135.00 FL	*- FL
19	1		*TAILGATE LID TOP GARNISH OUTER CHROME	Not Necessary	104.00 FL	*- FL
20	1		*TAILGATE LID CAREN EMBLEM	Necessary	28.00 FL	*28.00 FL
21	1		*TAILGATE LID C&C EMBLEM	Necessary	31.00 FL	*31.00 FL
22	1		*TAILGATE LID CRDI EMBLEM	Necessary	29.00 FL	*29.00 FL
23	1		*TAILGATE LID KIA EMBLEM	Necessary	35.00 FL	*35.00 FL
24	1		*TAILGATE LID LOCK	Shorted	112.00 FL	*112.00 FL
25	1		*TAILGATE LID OPENER	Not Necessary	88.00 FL	*- FL
26	1		*TAILGATE LID OPENER COVER	Not Necessary	79.00 FL	*- FL
27	2		*TAILGATE LID REFLECTOR	Not Necessary	1,546.00 FL	*- FL
28	2		*TAILGATE LID DAMPER	Not Necessary	160.00 FL	*- FL
29	1		*REAR END PANEL	Repair	611.00 FL	*- FL
30	1		*REAR END PANEL TOP GARNISH	Not Necessary	123.00 FL	*- FL
31	1		*REAR END PANEL WEATHERSTRIP	Twisted	132.00 FL	*132.00 FL
32	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 10,908.00 2,962.00  
**- List Item Discount on L Items 10.00/10.00% (\$\$)** 1,085.80 292.20

**Total Parts (\$\$)** 9,822.20 2,669.80

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
3	TO TRANSFER OF TAILGATE FITTINGS, FIXTURE AND PERFORM WATERSEEPAGE TEST	New	100.00	60.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	250.00	30.00
5	TO PERFORM WATER SEEPAGE TEST, WIND NOISE AND TEST-DRIVE	New	50.00	0.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	New	80.00	80.00
7	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	60.00	50.00
8	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,000.00	500.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,100.00	700.00
<b>Gross Labour Cost (\$)</b>			<b>2,840.00</b>	<b>1,560.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >