



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2007956
INV Date 26/11/2020
Reference CC4/FCI20006173/Upa3s2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SKS 1465E
Insured Veh. SHD 4096G
Claim No. D20002357MFSH
Policy No. D-20094922MFSH
Accident Date 05/06/2020
Inspection Date 10/06/2020

Description	Total
Survey Inspection	3,084.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Less:Discount	-2,504.00
Subtotal	580.00
GST (7%)	40.60
Grand Total	620.60

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20006173/Upa3s2

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 26-11-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4096G	Veh. Inspected	SKS 1465E
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20002357MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	10/06/2020

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN JETTA (A)	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WVWZZZ1KZ8U030642	Colour	BLACK
Odometer	187339	Steering	AFFECTED
Brakes	IN ORDER	Modification	IN ORDER
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	GITI	5 mm
L/H Front Tyre	205/55 R16	GITI	5 mm
R/H Rear Tyre	205/55 R16	GITI	5 mm
L/H Rear Tyre	205/55 R16	GITI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. THE UNDERCARRIAGE AND CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/06/2020	Inspection Date	10/06/2020
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	15 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 1465E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WINDSCREEN	CRACKED	1,432.00	1,120.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	269.00	182.30
1	FRONT WIPER PANEL	TO REPAIR SEE LABOUR	497.00	-
2	FRONT WIPER (L+R)	NOT NECESSARY	316.00	-
2	FRONT WIPER GARNISH (L+R)	NOT NECESSARY	164.00	-
2	FRONT WIPER NOZZLE	NOT NECESSARY	210.00	-
1	FRONT WIPER NOZZLE PIPE	NOT NECESSARY	159.00	-
1	FRONT WIPER WEATHERSTRIP	NOT NECESSARY	134.00	-
1	BONNET	BUCKLED	1,227.00	839.60
1	BONNET INSULATOR	TORN	495.00	155.60
1	BONNET LOCK	TWISTED	297.00	75.01
1	BONNET LOCK CATCH	NOT NECESSARY	90.00	-
2	BONNET HINGE (L+R)	BENT	268.00	170.00
4	BONNET STOPPER	NOT NECESSARY	36.00	-
1	BONNET WEATHERSTRIP	NECESSARY	205.00	66.20
2	HEADLAMP (L+R)	N/S CRACKED / O/S BROKEN	3,980.00	1,840.00
2	HEADLAMP BRACKET (L+R)	NOT NECESSARY	560.00	-
1	FRONT GRILLE	BROKEN	789.00	288.20
1	FRONT GRILLE CHROME	BROKEN	651.00	210.00
1	FRONT GRILLE LOGO	MISSING	105.00	55.00
1	FRONT BUMPER	DISTORTED	1,090.00	992.96
2	FRONT BUMPER RETAINER (L+R)	BENT	322.00	70.00
1	FRONT BUMPER REINFORCEMENT BAR	BENT	625.00	545.20
2	FRONT BUMPER BRACKET (L+R)	NO SUCH PARTS	486.00	-
1	FRONT BUMPER SPONGE	TORN	390.00	86.00
1	FRONT BUMPER GRILLE	TORN	423.00	185.20
2	FRONT BUMPER FOG LAMP (L+R)	O/S BROKEN	778.00	315.00
2	FRONT BUMPER FOG LAMP GARNISH (L+R)	O/S BROKEN	460.00	190.00
2	FRONT BUMPER FOG LAMP GARNISH CHROME (L+R)	O/S BROKEN	500.00	115.00

Report Ref No. CC4/FCI20006173/Upa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER TOW COVER	MISSING	110.00	25.00
1	FRONT BUMPER UNDERCOVER	TORN	594.00	288.20
2	FRONT FENDER (L+R)	N/S TO REPAIR SEE LABOUR / O/S BUCKLED	1,966.00	681.00
2	FRONT FENDER TOP GARNISH (L+R)	NO SUCH PARTS	440.00	-
2	FRONT FENDER INNER PANEL (L+R)	TO REPAIR SEE LABOUR	2,432.00	-
2	FRONT FENDER COWLING (L+R)	TORN	488.00	188.20
1	FRONT SUPPORT PANEL	DISTORTED	1,069.00	745.30
1	FRONT SUPPORT PANEL TOP GARNISH	NO SUCH PARTS	342.00	-
1	AIRCON CONDENSER	DISTORTED	979.00	850.00
1	HIGH PRESSURE HOSE	NO SUCH PARTS	342.00	-
1	LOW PRESSURE HOSE	NO SUCH PARTS	357.00	-
1	RADIATOR	DISTORTED	1,219.00	981.30
1	RADIATOR BRACKET	NOT NECESSARY	210.00	-
1	RADIATOR TOP HOSE	TORN	501.00	112.00
2	RADIATOR LOWER HOSE	NOT NECESSARY	822.00	-
1	SUCTION PIPE	BENT	401.00	299.00
1	DISCHARGE PIPE	BENT	427.00	302.00
1	RADIATOR FAN COWLING }	BROKEN	809.00	451.05
1	RADIATOR FAN MOTOR }		940.00	-
1	RADIATOR FAN BLADE }		105.00	-
1	RADIATOR FAN CONTROL UNIT	NOT NECESSARY	796.00	-
1	AIRCON CONDENSER FILTER	NOT NECESSARY	510.00	-
1	RADIATOR SPARE TANK	CRACKED	182.00	166.00
1	RADIATOR SPARE TANK TOP PIPE	NOT NECESSARY	402.00	-
1	RADIATOR SPARE TANK LOWER PIPE	NOT NECESSARY	397.00	-
2	ELECTRIC WATER PUMP (L+R)	NOT NECESSARY	3,542.00	-
2	ELECTRIC WATER PUMP BRACKET (L+R)	NOT NECESSARY	210.00	-
2	ELECTRIC WATER PUMP TOP HOSE (L+R)	NOT NECESSARY	620.00	-
2	ELECTRIC WATER PUMP LOWER HOSE (L+R)	NOT NECESSARY	654.00	-
2	HORN (L+R)	NOT NECESSARY	600.00	-
1	WIPER WASHER	DISTORTED	130.00	130.00

Report Ref No. CC4/FCI20006173/Upa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WIPER WASHER MOTOR	CRACKED	189.00	150.00
1	AIRCON COMPRESSOR	BENT / JAMMED	2,476.00	1,885.30
1	AIRCON COMPRESSOR WIRE SOCKET	NOT NECESSARY	433.00	-
1	FAN BELT	NOT NECESSARY	161.00	-
1	ALTERNATOR	CRACKED / JAMMED	2,940.00	1,688.30
1	THROTTLE BODY	NOT NECESSARY	2,816.00	-
1	ENGINE COVER	NOT NECESSARY	409.00	-
1	ENGINE TIMING COVER	NOT NECESSARY	411.00	-
1	ENGINE UNDERCOVER	NOT NECESSARY	214.00	-
1	ENGINE SUPPORT	NOT NECESSARY	1,022.00	-
2	ENGINE MOUNTING	NOT NECESSARY	850.00	-
1	GEAR BOX	NOT NECESSARY	26,790.00	-
1	GEAR BOX MOUNTING	NOT NECESSARY	421.00	-
1	BATTERY BRACKET	NOT NECESSARY	195.00	-
1	BATTERY TRAY	NOT NECESSARY	202.00	-
1	BATTERY COVER (NPA)	NOT NECESSARY	-	-
1	BATTERY CABLE (NPA)	NOT NECESSARY	-	-
1	FUSE BOX	NOT NECESSARY	1,025.00	-
1	FRONT CROSSMEMBER EXTENSION	NOT NECESSARY	1,870.00	-
1	ENGINE ECU	NOT NECESSARY	3,071.00	-
1	ENGINE ECU BRACKET	NOT NECESSARY	286.00	-
1	AIRBAG ECU	ACTIVATED	2,087.00	945.30
2	FRONT AIRBAG SENSOR (L+R)	ACTIVATED 1PC ONLY	1,984.00	250.00
1	FRONT AIR BAG WIRE HARNESS	ACTIVATED	1,432.00	315.50
1	FRONT AIR BAG COMPUTER	REPEATED	1,989.00	-
1	DASHBOARD TOP	TORN	2,021.00	1,100.00
1	DASHBOARD LOWER	NO SUCH PARTS	1,797.00	-
1	DASHBOARD TOP COVER	NO SUCH PARTS	565.00	-
1	DASHBOARD INNER TRIM	NOT NECESSARY	931.00	-
1	DASHBOARD BRACKET	NOT NECESSARY	722.00	-
1	DASHBOARD AIRCON GARNISH CENTER	NOT NECESSARY	695.00	-
1	DASHBOARD AIR BAG (LH)	ACTIVATED	1,262.00	1,262.00

Report Ref No. CC4/FCI20006173/Upa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DASHBOARD LOWER AIRBAG (RH)	NO SUCH PARTS	1,340.00	-
1	STEERING WHEEL AIR BAG (RH)	ACTIVATED	1,285.00	1,285.00
1	STEERING COIL	NO SUCH PARTS	921.00	-
1	STEERING WHEEL	NOT NECESSARY	874.00	-
1	STEERING WHEEL COVER	NOT NECESSARY	356.00	-
1	AIRCON BLOWER MOTOR	NOT NECESSARY	839.00	-
1	AIRCON BLOWER BOX	NOT NECESSARY	795.00	-
1	FRONT DRIVER SAFETY BELT	ACTIVATED	852.00	645.00
1	FRONT PASSENGER SEAT SAFETY BELT	NOT NECESSARY	859.00	-
2	A' PILLAR (L+R)	TO REPAIR SEE LABOUR	1,524.00	-
2	FRONT DOOR (L+R)	TO REPAIR SEE LABOUR	2,932.00	-
1	FRONT DOOR SIDE MIRROR ASSY (RH)	NOT NECESSARY	772.00	-
1	FRONT DOOR SIDE MIRROR SIGNAL LAMP (RH)	NOT NECESSARY	302.00	-
1	FRONT DOOR LOCK CYLINDER (RH)	NOT NECESSARY	324.00	-
1	FRONT DOOR WINDOW MOULDING (RH)	NOT NECESSARY	120.00	-
1	FRONT DOOR WINDOW INNER MOULDING (RH)	NOT NECESSARY	122.00	-
2	FRONT DOOR HINGE (UPPER & LOWER) (RH)	NOT NECESSARY	246.00	-
1	FRONT DOOR CHECKER (RH)	NOT NECESSARY	136.00	-
1	FRONT DOOR WEATHER STRIP (RH)	NOT NECESSARY	312.00	-
1	FRONT DOOR INNER WEATHER STRIP (RH)	NOT NECESSARY	323.00	-
1	ROCKER PANEL (RH)	TO REPAIR SEE LABOUR	745.00	-
1	ROCKER PANEL GARNISH (RH)	NOT NECESSARY	624.00	-
2	FRONT ABSORBER (L+R)	O/S BENT	1,464.00	455.00
2	FRONT LOWER ARM (L+R)	O/S BUCKLED	1,098.00	345.00
2	FRONT KNUCKLE (L+R)	O/S BENT	1,174.00	399.00
2	FRONT KNUCKLE BEARING (L+R)	O/S NECESSARY	848.00	215.00
2	FRONT BEARING HUB (L+R)	O/S BENT	658.00	288.00
1	FRONT CROSSMEMBER	NOT NECESSARY	2,259.00	-
1	FRONT STEERING RACK AND PINION ASSY	NOT NECESSARY	2,732.00	-
2	FRONT DRIVE SHAFT (L+R)	O/S BENT	2,426.00	1,005.00
2	FRONT TIE ROD (L+R)	NOT NECESSARY	874.00	-

Report Ref No. CC4/FCI20006173/Upa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT TIE ROD END (L+R)	NOT NECESSARY	451.00	-
1	FRONT STABILIZER BAR	NOT NECESSARY	879.00	-
2	FRONT STABILIZER LINK (L+R)	NOT NECESSARY	422.00	-
	LESS 10% DISCOUNT		-13,270.80	-2,495.37
			119,437.20	22,458.35
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	120.00	40.00
1	FRONT WINDSCREEN DECL (SN)	NOT NECESSARY	300.00	-
2	FRONT WIPER BLADE (L+R) (SN)	NOT NECESSARY	120.00	-
10	BONNET INSULATOR CLIPS (SN)	NECESSARY	100.00	50.00
1	FRONT CARPLATE (SN)	BROKEN	200.00	40.00
1	FRONT CARPLATE FRAME (SN)	NOT NECESSARY	200.00	-
10	FRONT BUMPER CLIPS (SN)	NECESSARY	100.00	50.00
1	FRONT FENDER INNER PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
20	FRONT FENDER COWLING CLIPS (L+R) (SN)	O/S NECESSARY	200.00	50.00
10	FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	100.00	-
1	ROCKER PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
10	ROCKER PANEL GARNISH CLIPS (SN)	NOT NECESSARY	100.00	-
1	AUTO OIL COOLER (SN)	NOT NECESSARY	6,000.00	-
1	AUTO OIL COOLER BRACKET (SN)	NOT NECESSARY	1,200.00	-
1	AUTO OIL COOLER TOP PIPE (SN)	NOT NECESSARY	550.00	-
1	AUTO OIL COOLER LOWER PIPE (SN)	NOT NECESSARY	550.00	-
1	RADIATOR COOLANT (SN)	NECESSARY	100.00	30.00
1	ENGINE OIL COOLER (SN)	NOT NECESSARY	8,000.00	-
1	ENGINE OIL COOLER BRACKET (SN)	NOT NECESSARY	2,200.00	-
20	DASHBOARD TOP CLIPS (SN)	NOT NECESSARY	200.00	-
20	DASHBOARD LOWER CLIPS (SN)	NOT NECESSARY	200.00	-
20	DASHBOARD INNER TRIM CLIPS (SN)	NOT NECESSARY	200.00	-
2	SET FRONT TYRE (SN)	SERVICEABLE	2,000.00	-
2	SET FRONT RIM (SN)	O/S DENTED	8,000.00	400.00
			30,980.00	660.00

Report Ref No. CC4/FCI20006173/Upa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO RNR ACCIDENT DAMAGED PARTS, CUT / WELD, KNOCK & REALIGN.		5,100.00	1,500.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		4,500.00	1,200.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.		250.00	100.00
	TO RNR FRONT WINDSCREEN.		400.00	120.00
	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS.	NOT NECESSARY	400.00	-
	TO RNR DOOR MECHANISM (FRONT) (L+R).	NOT NECESSARY	800.00	-
	TO RNR UNDERCARRIAGE SYSTEM.		250.00	250.00
	TO CHECK WHEEL ALIGNMENT.		250.00	60.00
	TO RNR A/C CONDENSER ASSY AND REFILL GAS.		250.00	100.00
	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS. }		150.00	30.00
	TO CHECK WIRING LAYOUT AND FOG LAMP FUNCTION. }		150.00	-
	TO RNR TYRE AND WHEEL BALANCING.	NOT NECESSARY	250.00	-
	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	NOT NECESSARY	600.00	-
	TO DO WATER LEAK TEST.	NOT NECESSARY	100.00	-
	TO RNR ENGINE. INCLUSIVE OF THE REPAIR OF FRONT WIPER PANEL, N/S FRONT FENDER (L+R), FRONT FENDER INNER PANEL (L+R), A' PILLAR (L+R), FRONT DOOR (L+R) AND ROCKER PANEL (RH). }		6,000.00	350.00
	TO RNR GEARBOX. }		6,000.00	-
	TO RNR DASHBOARD. }		2,000.00	260.00
	TO RNR SAFETY BELTS. }		4,000.00	-
	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD.	NOT NECESSARY	250.00	-
	TO CLEAN AND VACUUM GLASSES TO ASSIST WORK LOAD.	NOT NECESSARY	350.00	-
			-	-
			-	-
			-	-
			32,050.00	3,970.00
	GRAND TOTAL		182,467.20	27,088.35

Report Ref No. CC4/FCI20006173/Upa3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			12,000.00
---	--	--	-----------

Report Ref No. CC4/FCI20006173/Upa3s2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKS 1465E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKS 1465E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKS 1465E

RE-INSPECTION

