MOTORS

ESTIMATE

GST Reg No : MR-8500111-X

: 197701469G Invoice Name & Address Owner Name & Vehicle Info /Tham Cheng-E (Tan Jingyu) Cust No/Name Tham Cheng-e (tan Jingyu) 31/05/201 Reg No/Reg Date SMA2261R Blk 55 Strathmore Avenue Date In/Mileage Chassis No MMBSTA13AJH001687 #05-147 Singapore 140055 3A92UGR8679 Engine No Contact No Mobile: 90114007 Make/Model MIT/18MY ATTRAGE 1.2 CVT A06 COOL SILVER MET/ BK BLACK Colour/Trim

AT NO	me Printed CSE	Operator		VIP No	
Cash 10/06/	2020/ 10:49 QUE	261 / Edwin Caina		3565	
SM00041 Cash 10/06/	iption of Goods / Servic	es	Qty Un	it Price Disc%	Amount
PNT88000 RENEW RHF DOOR , RHR DOOR REPAIR RHF FENDER , RHR PNT98000 RESPRAY RHF FENDER , RHF RR BUMPER BÓDY KIT & ROC PNT88000 REMOVE & REFIT RHF DOOR PAT88000 REMOVE & REFIT RHR DOOR 64900099 CHECK WIRING ELECTRICAL 0028901 TO CARRY OUT DIAGNOSTIC USING HI-SCAN PRO TEST UNDRY APPLY ANTI CORROSION ON NT88000 REMOVE & REFIT REVERSE S UNDRY SUNDRY SURVEYOR SURVEYOR	DOOR, RHR DOOR, R KER PNL BODY KIT LH COMPONENT COMPONENT SYSTEM CHECK USING THE SCAN AFFECTED AREAS SENSOR NAME: SIGNATURE:	HR FENDER , RR BUMPER	-	996.00 00.00 29.00 00.00 799.00 00.0 29.00 00.0 1643.00 00.0	0 29.00 799.00 0 29.00 0 1643.00
DATE:	8 days			Nett	10,533
	Rearing befor	re paint	7% GST on	10533.00	737 11,270

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 1

Authorized signatory and company stamp